

		A dial O	IL CONSER	RVATION				
Form 3 <sup>1</sup> 60-5 (August 2007) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WE Do not use this form for proposals to drill or to re-			APR of the Arrenja RECEIVED ELLS		FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMLC054988B 6. If Indian, Allottee or Tribe Name			
abandoned well. Use form 3160-3 (APD) for such proposals.					7. If Unit or CA/Agreement, Name and/or No.			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.								
1. Type of Well 🖸 Gas Well 🗋 Other					8. Well Name and No. JENKINS B FEDERAL 8			
2. Name of Operator Contact: DAVID A EYLER COG OPERATING LLC E-Mail: DEYLER@MILAGRO-RES.COM					9. API Well No. 30-015-29388-00-S1			
3a. Address ONE CONCHO CENTER 600 MIDLAND, TX 79701	DNE CONCHO CENTER 600 W ILLINOIS AVENUE   Ph: 432-687-3033					10. Field and Pool, or Exploratory GRAYBURG		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				-	11. County or Parish, and State			
Sec 20 T17S R30E SENW 2310FNL 1650FWL					EDDY COUNTY, NM			
12. CHECK APPI	ROPRIATE BOX(ES) TO	) INDICATE	NATURE OF	NOTICE, RE	EPORT, OR OTHE	ER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION							
Notice of Intent	Acidize	Deep		—	ion (Start/Resume)	U Water S		
Subsequent Report	<ul> <li>Alter Casing</li> <li>Casing Repair</li> </ul>		ure Treat Construction	<ul> <li>Reclamation</li> <li>Recomplete</li> <li>Temporarily Abandon</li> <li>Water Disposal</li> </ul>		<ul> <li>Well Integrity</li> <li>Other</li> </ul>		
Final Abandonment Notice	<ul> <li>Change Plans</li> <li>Convert to Injection</li> </ul>		and Abandon					
<ul> <li>13. Describe Proposed or Completed Op If the proposal is to deepen direction: Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f</li> <li>1) TAG EXISTING CIBP+CMT</li> <li>2) SET 5-1/2" CIBP @ 3,100";</li> <li>3) PUMP 35 SXS.CMT. @ 1,3</li> <li>4) PUMP 30 SXS.CMT. @ 57</li> <li>5) PERF. X ATTEMPT TO CIF</li> <li>6) DIG OUT X CUT OFF WEL HOLE MARKER.</li> </ul>	ally or recomplete horizontally, rk will be performed or provide l operations. If the operation res andonment Notices shall be file inal inspection.) T.@+/-4,260';PUMP 45 SX PUMP 85 SXS.CMT. @ 350'-1,150'(T/YATES,B/SA 5'-400'(8-5/8"CSG.SHOE, RC. TO SURF., FILLING A	give subsurface to the Bond No. on sults in a multiple ad only after all re (S.CMT.@ 4,2 3,100'-2,430'(T ALT); WOC X T/SALT); WOC ALL ANNULI, 4	cations and meas file with BLM/BI completion or rec quirements, inclu 260'-3,980'(DV 7S.A., T/GBRG 7AG CMT. PLI C X TAG CMT. 40 SXS.CMT.	sured and true ve A. Required sub completion in a n ding reclamation (TOOL); TAG. COL); UG. PLUG. @ 100'-3'.	rtical depths of all perti sequent reports shall b iew interval, a Form 31 h, have been completed,	nent markers an e filed within 30 60-4 shall be file and the operato y/28 preci for fa	d zones. days ed once r has	
DURING THIS PROCEDURE THE REQUIRED DISPOSAL,	PER OCD RULE 19.15.1	7					Ō	
		ON PROCEDU	RE		TACHED FO			
AC- Below governd	Level Cryho,	le Mari	ter	CONDE	<u>TIONS OF A</u>	PROVA	<u> </u>	
14. I hereby certify that the foregoing is Control Name (Printed/Typed) DAVID A	Electronic Submission #2 For COG Ol ommitted to AFMSS for pro	PERATING LLC cessing by JA	<ol><li>sent to the C</li></ol>	arisbad 04/06/2015 (15	-		-	
			AGLN				<i></i>	
	Submission)		Date 03/05/2					
Signature (Electronic S			OD CTATE	OFFICE US	SE .			
Signature (Electronic S						11	1	
Approved By	Approval of this notice does a	not warrant or	Title S	AE T		Date	-15	
Approved By fames C	A pproval of this notice does to itable title to those rights in the ct operations thereon.	not warrant or subject lease	Title <i>S</i>	AG T 40			2-15	



# COG Operating LLC



DAE 03105/15

### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

#### Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>minety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.

J. Amos 3/6/11

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>minety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary. Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Below Ground Level Cap (Lesser Prairie-Chicken Habitat)</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be motified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/Condition of Approval for Lesser Prairie-Chicken:</u> From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted