## NM OIL CONSERVATION

Form 3160-5 (August 2007)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia APR 1 3 2015

FORM APPROVED

OMB Expire		
eace Serial No.	•	

SUNDRY NOTICES AND REPORTS ON WELL&ECEIVED  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.		NMLC054988B  6. If Indian, Allottee or Tribe Name					
					SUBMIT IN TRIPLICATE - Other instructions on reverse side.		
Type of Well     ☐ Gas Well    ☐ Other			Well Name and No.     JENKINS B FEDERAL 3				
Name of Operator Contact: DAVID A EYLER COG OPERATING LLC E-Mail: DEYLER@MILAGRO-RES.COM			9. API Well No. 30-015-04216-00-S1				
3a. Address ONE CONCHO CENTER 600 W ILLINOIS AVENUE MIDLAND, TX 79701  3b. Phone No. (include area code) Ph: 432-687-3033				)	10. Field and Pool, or Exploratory LOCO HILLS		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, and State				
Sec 20 T17S R30E NENW Lc	t C 330FNL 2310FWL				EDDY COUNTY	′, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATI	E NATURE OF 1	NOTICE, RI	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION			TYPE O	F ACTION			
Notice of Intent⁻	☐ Acidize	□ Dec	epen	☐ Producti	ion (Start/Resume)	■ Water Shut-Off	
_	☐ Alter Casing	🗖 Fra	cture Treat	□ Reclama	ation	■ Well Integrity	
☐ Subsequent Report	Casing Repair	□ Nev	v Construction	☐ Recomp	lete	□ Other	
☐ Final Abandonment Notice	☐ Change Plans	<b>⊠</b> Plu	g and Abandon	☐ Tempor	arily Abandon		
	Convert to Injection	Plu	g Back	☐ Water Disposal			
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  1) SET 4-1/2" CIBP @ 4,250'; PUMP 45 SXS.CMT. @ 4,250'-3,900'(SQZD.GB/S.A.PERFS, DV TOOL); WOC X TAG CMT. PLUG. 2) PUMP 50 SXS.CMT. @ 3,150'-2,715'(ORG.GB/S.A. O/H,7"CSG.SHOE,T/S.A.); TAG. 3) PUMP 45 SXS.CMT. @ 3,50'-2,715'(B/ANHY.,T/QN); WOC X TAG CMT. PLUG. 4) PERF.X ATTEMPT TO SQZ.80 SXS.CMT. @ 1,187'-975'(T/YATES,T/ANHY.,B/SALT); TAG. 5) PERF.X ATTEMPT TO SQZ.45 SXS.CMT. @ 555'-455'(T/SALT,8-5/8"CSG.SHOE); TAG. 6) PERF.X CIRC. TO SURF., FILLING ALL ANNULI, 45 SXS.CMT. @ 100'-3'. 7) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSGS. X INSTALL GROUND LEVEL DRY HOLE MARKER.  DURING THIS PROCEDURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM W/ A STEEL TANK AND HAUL CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17.  Below ground level dry hale macker (e.g. Life Contents) and the performs and surface							
14. I hereby certify that the foregoing is  Contact (Printed/Typed) DAVID A E	#Electronic Submission # For COG O Dommitted to AFMSS for pro	PERATING L	C, sent to the Ca	arlsbad 04/06/2015 (15		ATTACHED	₹E
Signature (Electronic S	ubmission)		Date 03/28/2	N15	•	i for secord OCD 4/28/15	_
Britain	THIS SPACE FO	R FEDERA				<u> </u>	
	00	<del></del>		12-		4-7-15	
Approved By	4. Como_		Title 7	PET		Date	2
Conditions of approval, if any, are attached certify that the applicant holds legal or equi which would entitle the applicant to condu-	itable title to those rights in the ct operations thereon.	subject lease	Office A				\ <u>``</u>
Title & U.S. Section 1001 and Title 43 U.S. States of false fictitious or fraudulent s	J.S.C. Section 1212, make it a	crime for any pe	rson knowingly and	willfully to mai	ke to any department or	agency of the United	

### **COG Operating LLC**

Jenkins B Federal #3 (After conversion to WIW) Lease & Well # Sce 20C, 17S, 30 E, Eddy Co., NM 30-015-042716 Spudded - 4/19/1938 KB -Elevation - 3649' 8 5/8" 32# @ 505', cmt w 50 sx Top of cmt @ 1960' fs, heavy mud to surface. 7" 24# csg @ 2875", cmt w/100 sx GB/SA Märker jt 3101' Completed in Open Hole, 2875 3/5/1966 Acidized 1000 gal 15% HCL, fraced w/45,000 gal LG, 450 sx sd Now behind pipe. \*\*Squeezed off with 225 sx. DV toool @ 3951; 4050 - 4071, 10 holes Acidized w/1000 gal 15% HCl 2/4/1997 Packer fluid 2 7/8" IP tbq Injection packer @ 4,245' Converted to WIW 8-26-10 Yeso 2/6/1997 4337 - 4600, 1 spf, 25 holes Acidized w/2000 gal 15% HCL Treated w/32,000 gal 20% HCL,54.000 gal LG, 5000 gal 15% HCL 1st stage cmt: 130 sx 50/50/2 .5% FL25, 5#sit, circ ? sx. PBTD - 4726' 2nd stage cm:: 250 sx 50/50 .5% fl-25, 5# slt, TOC @ 1960' 4 1/2" 11.6# csg @ 4741'.

#### COG Operating LLC

Lease & Well #

Jenkins B Federal #3

(After conversion to WIW)

30-015-0422/16

Sce 20C, 17S, 30 E, Eddy Co., NM

Spudded - 4/19/1938

Elevation - 3649

KB -PERF. X CERC. 45 SXS. CMT. @ 100'-3! 8 5/8" 32#@ 505', cmt w 50 sx PERF. XSQZ, 45 SXS. CMT. @ 555'-455'-7HG PERF. X SQZ. BOSXS.CMT. @11871-975-7AG - Pump 45 5x5. CMT.C 2340'-1975'-TAG 7" 24# csg @ 2875', cmt w/100 sx - Pump 50 5x5. cmT.@3150'-2715'-TAG GB/SA Marker it 3101' Completed in Open Hole, 2875 Acidized 1000 gal 15% HCL, fraced w/45,000 gal LG, 450 sx sd Now behind pipe. \*\*Squeezed off with 225 sx. DV toool @ 3951' 4050 - 4071, 10 holes Acidized w/1000 gal 15% HCl Pump 45 SXS.CMT. @ 42501-39001-TAG SET \$ 1/2" CJBP@ 4250" Yeso 2/6/1997 4337 - 4600, 1 spf, 25 holes Acidized w/2000 gal 15% HCL Treated w/32,000 gal 20% HCL,54,000 gal LG, 5000 gal 15% HCL 1st stage cmt: 130 sx 50/50/2 .5% FL25, 5#slt, circ ? sx. PBTD - 4726' 2nd stage cmt: 250 sx 50/50 .5% fl-25, 5# slt, TOC @ 1960'

DA & 03/28/15 SH

4 1/2" 11.6# csg @ 4741'.

#### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greenc Street Carlsbad, New Mexico 88220 575-234-5972

#### Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

  The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and
- The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.

J. Amos 3/6/11

#### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

#### Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>minety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted