

District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

APR 29 2015  
RECEIVED  
CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.  
30-015-01963

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name  
Rotary State

8. Well Number 4

9. OGRID Number 370080

10. Pool name or Wildcat  
Artesia (Queen-Grayburg-San Andrs)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
Breitburn Operating LP

3. Address of Operator  
1401 McKinney Street, Suite 2400, Houston, TX 77010

4. Well Location  
Unit Letter G 2100 feet from the N line and 1980 feet from the E line  
Section 20 Township 18S Range 28E NMPM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3594' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU Plugging Equipment. POH w/production Equipment.

Set CIBP @ 1950'. Circulate hole w/mud laden fluid. Spot 15 sx cement on top of plug fr 1950-1850'.

Perf and sqz 45 sx @ 1650-1550'. WOC & tag.

Perf and sqz 45 sx @ 580-480'. WOC & tag.

Perf and sqz 25 sx @ 60' to surface.

Cut off wellhead and weld on dry hole marker.

Approved for plugging of well bore only.  
Liability under bond is retained pending receipt  
of C-103 (Subsequent Report of Well Plugging)  
which may be found at OCD Web Page under  
Forms: www.emnrd.state.nm.us/oed.

\* well must be plugged by 5/8/2016

Spud Date: 09/15/1957

Rig Release Date: 11/06/1957

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jeanie McMillan

TITLE Regulatory Manager

DATE 04/27/2015

Type or print name Jeanie McMillan

E-mail address: jeanie.mcmillan@breitburn.com PHONE: 713-634-4696

For State Use Only

APPROVED BY: RDade

TITLE Dist # Supervisor

DATE 5/8/2015

Conditions of Approval (if any):

\* See Attached COA's

BREITBURN OPERATING

30-015-02074

STATE 647 AC 711 #47

H-28-185-28E

1840 FNL 800 FEL

Perf 1 Sg 2 35 SX  
60' - SURFACE

Perf 1 Sg 2 55 SX  
@ 500 - 400

Perf 1 Sg 2 55 SX  
@ 1600 - 500 TAG

C.I.B. @ 2725 W/  
1590 @ 2725 - 2425

Perf 1 @ 2760 -  
2803

7 @ 2137' W/

4 1/2 @ 2803 135 SX TAG 1608

Brentburn Operating

30-015-02074

State 647 AC 711 #47

H-28-18S-28E

1840 FNL 800 FEL

Pet @ 2760-2803

7" @ 2137'

4 1/2" @ 2803 w/ 135sx TOC 1608

Perforated Operating

30-015-02074

State 647 AC 711 #47

H-28-185-28E

1840 FNL 800FEL

Perf' Sg2 35SX  
60' - Surface

Perf' Sg2 55SX  
@ 500-400

Perf' Sg2 55SX  
@ 1600-1500 TAG

C.I.B.P. @ 2725W/  
1590 @ 2725-2625

Perf' @ 2760-  
2803

7 @ 2137' W1

4 1/2 @ 2803 1355X TUE 1608

Brentburn Operating

30-015-02074

State 647 AC 711 #47

H-28-188-28E

1840 FNL 800 FEL

Pets @ 2760-2803

7" @ 2137'

4 1/2" @ 2803 w/ 135sx Toc 1608

NEW MEXICO OIL CONSERVATION DIVISION  
DISTRICT 2 OFFICE  
811 S. FIRST STREET  
ARTESIA, NM 88210  
(575)748-1283

**CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT**

Operator: Breitburn Op.  
Well Name & Number: Rotary State #4  
API #: 30-015-01963

1. Produced water **will not** be used during any part of the plugging & abandonment operation.
2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
4. Trucking companies being used to haul oilfield waste fluids to a disposal – commercial or private – shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
7. Every attempt must be made to clean the well bore out to below the perms, before any plugs can be set, by whatever means possible.
8. **Cement Retainers may not be used.**
9. **Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.**
10. **Plugs may be combined after consulting with and getting approval from NMOCD.**
11. **Minimum WOC time for tag plugs will be 4 Hrs.**

*ASD*

*5/8/15*

## GUIDELINES FOR PLUGGING AND ABANDONMENT

### DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
  - Fusselman
  - Devonian
  - Morrow
  - Wolfcamp
  - Bone Spring
  - Delaware
  - Any Salt Section (Plug at top and bottom)
  - Abo
  - Glorieta
  - Yates (this plug is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).