1 <b>A</b>		NM OIL CONSE	NAULA I			
Form 3160-5	UNITED STAT	ES OPERAN	RICT	12. The second	FORM APPROVED MB No. 1004-0137	
(August 2007) · DI		INTERIOR MAY 26	2015		xpires: July 31, 2010	
BU	REAU OF LAND MAN	NAGEMENT MAY 26		5. Lease Serial No.	LC 58709A	
SUNDRY	NOTICES AND REP	ORTS ON WELLSET	/ED	6. If Indian, Allottee of		····
Do not use this	form for proposals	to drill or to re-enter a APD) for such proposi	an			
SUBMIT IN TRIPLICATE – Other instructions on page 2.			7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well			Taylor Unit NM71048x			
	Well Other		•	8. Well Name and No.	No.13	· · · · · · · · · · · · · · · · · · ·
2. Name of Operator Ray Westall Operating, Inc.			9. API Well No. <b>30-015-05534</b>			
3a. Address		3b. Phone No. (include area c	cođe)	10. Field and Pool or E	-	•
P.O. Box 4, Loco Hills, I		575-622-2372			even Rivers-Queen-Grayb	urg
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 660' FNL & 660' FWL, 13-18S-31E			•	11. Country or Parish, State Eddy, NM		
	•	DX(ES) TO INDICATE NATUR	RE OF NOTIC	E, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION			YPE OF ACT		· · · · · · · · · · · · · · · · · · ·	
	X Acidize	Deepen		ction (Start/Resume)	Water Shut-Off	
X Notice of Intent	Alter Casing	Fracture Treat		mation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	_	nplete	Other	
Subsequent Report	Change Plans	Plug and Abandon	Temp	orarily Abandon		
Final Abandonment Notice	X Convert to Injection	Plug Back	Water Water	Disposal		
Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo	work will be performed or proved operations. If the operation Abandonment Notices must be r final inspection.)	on results in a multiple completion be filed only after all requiremen	I measured and BLM/BIA. Re on or recompletes, including r	equired subsequent repo etion in a new interval, a eclamation, have been c	rts must be filed within 30 day a Form 3160-4 must be filed o	ys mce s
Attach the Bond under which the v following completion of the involv testing has been completed. Final	work will be performed or pro- ved operations. If the operatio Abandonment Notices must b r final inspection.) pump, tubing, horsehead.	y, give subsurface locations and vide the Bond No. on file with I on results in a multiple completion e filed only after all requiremen	I measured and BLM/BIA. Re on or recomple its, including r	equired subsequent repo etion in a new interval, a eclamation, have been o $\mathcal{MMCCD} W \mathcal{P}$	rts must be filed within 30 day a Form 3160-4 must be filed of completed and the operator has $2 \times 23 $ $2 - 1 + 1 $	ys mce s
Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo MIRU Pulling Unit. Pull rods, p	work will be performed or proved operations. If the operatio Abandonment Notices must be r final inspection.) pump, tubing, horsehead.	y, give subsurface locations and vide the Bond No. on file with I on results in a multiple completion e filed only after all requiremen uppermost perf / openhole	I measured and BLM/BIA. Re on or recomple its, including r	equired subsequent repo etion in a new interval, a eclamation, have been o $\mathcal{MMCCD} W \mathcal{P}$	rts must be filed within 30 day a Form 3160-4 must be filed of completed and the operator has $2 \times 23 $ $2 - 1 + 1 $	ys once s
Attach the Bond under which the w following completion of the involv testing has been completed. Final determined that the site is ready fo MIRU Pulling Unit. Pull rods, p RIH w/ 2-3/8" IC Tubing & PKF	work will be performed or proved operations. If the operatio Abandonment Notices must be r final inspection.) pump, tubing, horsehead. R. Set PKR within 100' of u re, pressure gauge, injectio	y, give subsurface locations and vide the Bond No. on file with I on results in a multiple completion e filed only after all requiremen uppermost perf / openhole on flowline.	I measured and BLM/BIA. Re on or recomple its, including r	equired subsequent reportion in a new interval, a calculation, have been a $\mathcal{M}\mathcal{M}\mathcal{O}\mathcal{C}\mathcal{D}\mathcal{W}\mathcal{P}$	rts must be filed within 30 day a Form 3160-4 must be filed of completed and the operator has $Z = \frac{2}{3} = \frac{2}{4} = \frac{1}{4}$ interval: 3461'-3567'.	ys once s
Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo MIRU Pulling Unit. Pull rods, p RIH w/ 2-3/8" IC Tubing & PKF Install injection wellhead, valv	work will be performed or proved operations. If the operatio Abandonment Notices must be r final inspection.) pump, tubing, horsehead. R. Set PKR within 100' of u re, pressure gauge, injectio	y, give subsurface locations and vide the Bond No. on file with I on results in a multiple completion e filed only after all requiremen uppermost perf / openhole on flowline.	I measured and BLM/BIA. Re on or recomple its, including r	equired subsequent reportion in a new interval, a column for $\mathcal{MMCCD}$ in $\mathcal{MMCCD}$ in $\mathcal{MMCCD}$ in $\mathcal{MMCCD}$ in $\mathcal{MMCCD}$ is consistent of $\mathcal{MMCCD}$ is a constant of $\mathcal{MMCD}$ is a co	rts must be filed within 30 day a Form 3160-4 must be filed of completed and the operator has $ZX \cdot JJL = Z - / IL / $	ys mce s
Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo MIRU Pulling Unit. Pull rods, J RIH w/ 2-3/8" IC Tubing & PKF Install injection wellhead, valv Commence Injection - Max Pre	work will be performed or pro- ved operations. If the operatio Abandonment Notices must be r final inspection.) pump, tubing, horsehead. R. Set PKR within 100' of u ve, pressure gauge, injection essure: 692 psi (.2 psi / for Vells may be tagged on bo	y, give subsurface locations and vide the Bond No. on file with I on results in a multiple completion e filed only after all requiremen uppermost perf / openhole on flowline.	I measured and BLM/BIA. Re on or recompletes, including r injection int	equired subsequent report etion in a new interval, a eclamation, have been of MMCCD WF erval @ ~3365'. Inj. SUBJE APPRO	rts must be filed within 30 day a Form 3160-4 must be filed of completed and the operator has $Z = \frac{2}{3} = \frac{2}{4} = \frac{1}{4}$ interval: 3461'-3567'.	ys once s
Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo MIRU Pulling Unit. Pull rods, J RIH w/ 2-3/8" IC Tubing & PKF Install injection wellhead, valv Commence Injection - Max Pre	work will be performed or pro- ved operations. If the operatio Abandonment Notices must be r final inspection.) pump, tubing, horsehead. R. Set PKR within 100' of u ve, pressure gauge, injection essure: 692 psi (.2 psi / for Vells may be tagged on bo	y, give subsurface locations and vide the Bond No. on file with I on results in a multiple completion e filed only after all requiremen uppermost perf / openhole on flowline not depth)	I measured and BLM/BIA. Re on or recompletes, including r injection int	equired subsequent report etion in a new interval, a eclamation, have been of MMCCD WF erval @ ~3365'. Inj. SUBJE APPRO	rts must be filed within 30 day a Form 3160-4 must be filed of completed and the operator has $ZX \cdot JJL = Z - / IL / $	ys mce s
Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo MIRU Pulling Unit. Pull rods, J RIH w/ 2-3/8" IC Tubing & PKF Install injection wellhead, valv Commence Injection - Max Pre	work will be performed or pro- ved operations. If the operatio Abandonment Notices must be r final inspection.) pump, tubing, horsehead. R. Set PKR within 100' of u ve, pressure gauge, injectio essure: 692 psi (.2 psi / for Vells may be tagged on bo d clean up of formation or	y, give subsurface locations and vide the Bond No. on file with I on results in a multiple completion e filed only after all requiremen uppermost perf / openhole on flowline not depth) ottom, cleaned out w/ baile r perfs as applicable. 500-10	I measured and BLM/BIA. Re on or recompletes, including r injection int	equired subsequent reportion in a new interval, a column of the second s	rts must be filed within 30 day a Form 3160-4 must be filed of completed and the operator has $ZX \cdot JJL = Z - / IL / $	ys mce s
Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo MIRU Pulling Unit. Pull rods, J RIH w/ 2-3/8" IC Tubing & PKF Install injection wellhead, valv Commence Injection - Max Pre	work will be performed or proved operations. If the operatio Abandonment Notices must be r final inspection.) pump, tubing, horsehead. R. Set PKR within 100' of u re, pressure gauge, injection essure: 692 psi (.2 psi / for Vells may be tagged on bo d clean up of formation or	y, give subsurface locations and vide the Bond No. on file with I on results in a multiple completion e filed only after all requiremen uppermost perf / openhole on flowline not depth)	I measured and BLM/BIA. Re on or recompletes, including r injection int	equired subsequent reportion in a new interval, a calamation, have been of <i>M.M.C.D. WF</i> serval @ ~3365'. Inj. SUBJE APPRC 6. SEE AT	rts must be filed within 30 day a Form 3160-4 must be filed of completed and the operator has $Z + \frac{2}{3}L = \frac{2}{1L}$ interval: 3461'-3567'. CCT TO LIKE DVAL BY STATE	ys once s 115
Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo MIRU Pulling Unit. Pull rods, J RIH w/ 2-3/8" IC Tubing & PKF Install injection wellhead, valv Commence Injection - Max Pre Note: M small acid	work will be performed or proved operations. If the operatio Abandonment Notices must be r final inspection.) pump, tubing, horsehead. R. Set PKR within 100' of u re, pressure gauge, injection essure: 692 psi (.2 psi / for Vells may be tagged on bood clean up of formation or	y, give subsurface locations and vide the Bond No. on file with I on results in a multiple completion e filed only after all requiremen uppermost perf / openhole on flowline not depth) ottom, cleaned out w/ baile r perfs as applicable. 500-10	I measured and BLM/BIA. Re on or recompletes, including r injection int	equired subsequent reportion in a new interval, a calamation, have been of <i>M.M.C.D. WF</i> serval @ ~3365'. Inj. SUBJE APPRC 6. SEE AT	rts must be filed within 30 day a Form 3160-4 must be filed of completed and the operator has Z + JJ + Z - / I + I + I interval: 3461'-3567'. CCT TO LIKE OVAL BY STATE TACHED FOR	ys once s 115
Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo MIRU Pulling Unit. Pull rods, J RIH w/ 2-3/8" IC Tubing & PKF Install injection wellhead, valv Commence Injection - Max Pre Note: W small acid	work will be performed or proved operations. If the operatio Abandonment Notices must be r final inspection.) pump, tubing, horsehead. R. Set PKR within 100' of u re, pressure gauge, injectio essure: 692 psi (.2 psi / for Vells may be tagged on bo d clean up of formation or Clean up of formation or and correct.	y, give subsurface locations and vide the Bond No. on file with I on results in a multiple completion e filed only after all requirement uppermost perf / openhole on flowline not depth) ottom, cleaned out w/ baile r perfs as applicable. 500-10 Signature	i measured and BLM/BIA. Re on or recompletes, including r injection int er or basket, 000 gals 159	equired subsequent reportion in a new interval, a column of the second s	rts must be filed within 30 day a Form 3160-4 must be filed of completed and the operator has $2 \times 23 \pm 2 - / 1 \pm $	ys once s //5
Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo MIRU Pulling Unit. Pull rods, p RIH w/ 2-3/8" IC Tubing & PKF Install injection wellhead, valv Commence Injection - Max Pre Note: W small acid	work will be performed or proved operations. If the operatio Abandonment Notices must be r final inspection.) pump, tubing, horsehead. R. Set PKR within 100' of u re, pressure gauge, injectio essure: 692 psi (.2 psi / for Vells may be tagged on bo d clean up of formation or Clean up of formation or and correct.	y, give subsurface locations and vide the Bond No. on file with I on results in a multiple completion e filed only after all requirement uppermost perf / openhole on flowline not depth) ottom, cleaned out w/ baile r perfs as applicable. 500-10 Signature	i measured and BLM/BIA. Re on or recompletes, including r injection int er or basket, 000 gals 159	equired subsequent reportion in a new interval, a column of the second s	rts must be filed within 30 day a Form 3160-4 must be filed of completed and the operator has Z + JJ + Z - / I + I + I interval: 3461'-3567'. CCT TO LIKE OVAL BY STATE TACHED FOR	ys once s //5
Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo MIRU Pulling Unit. Pull rods, p RIH w/ 2-3/8" IC Tubing & PKF Install injection wellhead, valv Commence Injection - Max Pre Note: W small acid	work will be performed or proved operations. If the operatio Abandonment Notices must be r final inspection.) pump, tubing, horsehead. R. Set PKR within 100' of u re, pressure gauge, injectio essure: 692 psi (.2 psi / for Vells may be tagged on bo d clean up of formation or Clean up of formation or and correct.	y, give subsurface locations and vide the Bond No. on file with I on results in a multiple completion e filed only after all requirement uppermost perf / openhole on flowline not depth) ottom, cleaned out w/ baile r perfs as applicable. 500-10 Signature	I measured and BLM/BIA. Re on or recompletions, including r injection int of or basket, 000 gals 159	equired subsequent reportion in a new interval, a column of the second s	rts must be filed within 30 day a Form 3160-4 must be filed of completed and the operator has Z + JJ = Z - / IE / interval: 3461'-3567'. CCT TO LIKE DVAL BY STATE TACHED FOR NS OF APPROVA	ys once s //5
Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo MIRU Pulling Unit. Pull rods, p RIH w/ 2-3/8" IC Tubing & PKF Install injection wellhead, valv Commence Injection - Max Pre Note: W small acid	work will be performed or proved operations. If the operatio Abandonment Notices must be r final inspection.) pump, tubing, horsehead. R. Set PKR within 100' of u re, pressure gauge, injection essure: 692 psi (.2 psi / for Vells may be tagged on bood clean up of formation or Clean up of formation or a clean up of formation or clean correct. 903-488	y, give subsurface locations and vide the Bond No. on file with I on results in a multiple completion e filed only after all requirement uppermost perf / openhole on flowline bot depth) ottom, cleaned out w/ baile r perfs as applicable. 500-10 <i>S</i> / <i>A</i> / <i>J</i> / <i>C</i> 8-9850 Title Partner,	I measured and BLM/BIA. Re on or recompletion injection int r or basket, 000 gals 159 )/J , SOS Consul 2015	Approximation and a new interval, a column in a new interval, a column interval, a column interval, a column interval and a column i	rts must be filed within 30 day a Form 3160-4 must be filed of completed and the operator has Z + JJ = Z - / IE / interval: 3461'-3567'. CCT TO LIKE DVAL BY STATE TACHED FOR NS OF APPROVA	ys once s //5
Attach the Bond under which the v following completion of the involve testing has been completed. Final determined that the site is ready for MIRU Pulling Unit. Pull rods, p RIH w/ 2-3/8" IC Tubing & PKF Install injection wellhead, valve Commence Injection - Max Press Note: W small acid I hereby certify that the foregoing is tru Name (Printed/Typed) Ben Stone Signature	work will be performed or proved operations. If the operatio Abandonment Notices must be r final inspection.) pump, tubing, horsehead. R. Set PKR within 100' of u re, pressure gauge, injection essure: 692 psi (.2 psi / for Vells may be tagged on bood clean up of formation or Clean up of formation or a clean up of formation or clean correct. 903-488	y, give subsurface locations and vide the Bond No. on file with I on results in a multiple completion is filed only after all requirement uppermost perf / openhole on flowline bot depth) ottom, cleaned out w/ baile r perfs as applicable. 500-10 Sign Sign Date 2/18/2 OR FEDERAL OR STA	I measured and BLM/BIA. Re on or recompletion injection int r or basket, 000 gals 159 )/J , SOS Consul 2015	Approximation and a new interval, a column in a new interval, a column interval, a column interval, a column interval and a column i	rts must be filed within 30 day a Form 3160-4 must be filed of completed and the operator has Z + JJ = Z - / IE / interval: 3461'-3567'. CCT TO LIKE DVAL BY STATE TACHED FOR NS OF APPROVA	ys once s //5
Attach the Bond under which the v following completion of the involve testing has been completed. Final determined that the site is ready for MIRU Pulling Unit. Pull rods, p RIH w/ 2-3/8" IC Tubing & PKF Install injection wellhead, valve Commence Injection - Max Press Note: W small acid I hereby certify that the foregoing is the Name (Printed/Typed) Ben Stone Signature Signature	work will be performed or proved operations. If the operatio Abandonment Notices must be r final inspection.) pump, tubing, horsehead. R. Set PKR within 100' of u re, pressure gauge, injection essure: 692 psi (.2 psi / for Vells may be tagged on bood clean up of formation or Vells may be tagged on bood clean up of formation or a clean up of formation or THIS SPACE FO Approval of this notice does no e to those rights in the subject le	y, give subsurface locations and vide the Bond No. on file with I on results in a multiple completion is filed only after all requirement uppermost perf / openhole on flowline bot depth) ottom, cleaned out w/ baile r perfs as applicable. 500-10 Sign Sign Sign Sign Sign Sign Sign Sign	I measured and BLM/BIA. Re on or recompletion injection int r or basket, 000 gals 159 )/J , SOS Consul 2015	Approximation in a new interval, a column	rts must be filed within 30 day a Form 3160-4 must be filed of completed and the operator has $i \times i j \leq i \leq -//l < /$ interval: 3461'-3567'. CCT TO LIKE DVAL BY STATE TACHED FOR NS OF APPROVA Ray-Westall-Operating-Inc ROVED	ys once s //5
Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready fo MIRU Pulling Unit. Pull rods, p RIH w/ 2-3/8" IC Tubing & PKF Install injection wellhead, valv Commence Injection - Max Pre Note: W small acid	work will be performed or proved operations. If the operatio Abandonment Notices must be r final inspection.) pump, tubing, horsehead. R. Set PKR within 100' of u re, pressure gauge, injectio essure: 692 psi (.2 psi / for Vells may be tagged on bo d clean up of formation or Vells may be tagged on bo d clean up of formation or THIS SPACE FO Approval of this notice does no e to those rights in the subject le ereon. S.C. Section 1212, make it a cri	y, give subsurface locations and vide the Bond No. on file with I on results in a multiple completion is filed only after all requirement uppermost perf / openhole on flowline not depth) ottom, cleaned out w/ baile r perfs as applicable. 500-10 Sign Sign Date 2/18/2 OR FEDERAL OR STA	I measured and BLM/BIA. Re on or recompletions, including r injection inf er or basket, 000 gals 159 )/J , SOS Consul 2015 ATE OFFI	equired subsequent reportion in a new interval, a column of the second s	rts must be filed within 30 day a Form 3160-4 must be filed of completed and the operator has $X \cdot JJ = Z - / I = /$ interval: 3461'-3567'. CCT TO LIKE DVAL BY STATE TACHED FOR NS OF APPROVA Ray-Westall-Operating=Inc ROVED	

## **Conditions of Approval**

## Ray Westall Operating, Inc. Taylor Unit - 04, API 3001505526 T18S-R31E, Sec 12, 1980FSL & 660FWL May 13, 2015

- Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00am through 3:00am for the period of March 1 through June 15. Exceptions to these restrictions may be granted by BLM's Johnny Chopp
  <a href="mailto:ichopp@blm.gov">ichopp@blm.gov</a>> 575.234.2227 or Bob Ballard <a href="mailto:source">> 575.234.5973</a>.
- 2. Subject to like approval by the New Mexico Oil Conservation Division.
- 3. Perform a charted casing integrity test of 500psig minimum from 3400' above the open hole to surface. Document the pressure test on a one hour full rotation calibrated (within 6 months) recorder chart registering within 25 to 85 per cent of its full range. Verify all annular casing vents are plumbed to the surface and open during this pressure test. Call BLM 575-200-7902 and arrange for a BLM witness of that pressure test. Include a copy of the chart in the subsequent sundry for this workover.
- 4. Before casing or a liner is added, replaced, or repaired prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 5. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from 3300 (just above open hole or below to top of cement taken with 0psig casing pressure. The CBL may be attached to a <u>pswartz@blm.gov</u> email. The CFO BLM on call engineer may be reached at 575-706-2779.
- 6. Do not exceed the approved WFX-936 injection pressure of 692psig with stimulation pump pressure.
- 7. Surface disturbance beyond the existing pad shall have prior approval.
- 8. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 9. Functional  $H_2S$  monitoring equipment shall be on location.
- 10. 2000 (2M) Blow Out Prevention Equipment to be used. All BOPE and workover procedures shall establish fail safe well control. Blind ram(s) and pipe ram(s) designed to close on all workstring diameters used is required equipment. A manual BOP closure system (hand wheels) shall be available for use regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) shall be employed when needed for reasonable well control requirements.
- 11. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal

facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.

- 12. Submit the BLM Form 3160-4 Recompletion Report via BLM's Well Information System; <u>https://www.blm.gov/wispermits/wis/SP</u> (email <u>pswartz@blm.gov</u> for operator setup instructions) within 30 days of the date all BLM approved procedures are complete.
- 13. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.

## Well with a Packer - Operations

- 1) Conduct a Mechanical Integrity Test of the tubing/casing annulus after a tubing, packer or casing seal is established.
- 2) The minimum test pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with a minimum 200 psig differential between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need to be reduced). Verify all annular casing vents are plumbed to surface and those valves open to the surface during this pressure test. An alternate method for a BLM approved MIT is to have the fluid filled system open to atmospheric pressure and have a loss of less than five barrels in 30 days witnessed by a BLM authorized officer.
- 3) Document the pressure test on a one hour full rotation chart recorder (calibrated within the last 6 months) registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict injection approval.
- 4) Make arrangements 24 hours before the test for BLM to witness. In Eddy County email Paul R. Swartz <u>pswartz@blm.gov</u> or phone 575-200-7902, if there is no response, 575-361-2822. If no answer, leave a voice mail or email with the API#, workover purpose, and a call back phone number.
- 5) Use of tubing internal protection, tubing on/off equipment just above the packer, a profile nipple, and an in line tubing check valve below the packer or between the on/off tool and packer is a "Best Management Practice". The setting depths and descriptions of each are to be included in the subsequent sundry.
- 6) Submit a (BLM Form 3160-5 subsequent report (daily reports) via BLM's Well Information System; <u>https://www.blm.gov/wispermits/wis/SP</u> (email <u>pswartz@blm.gov</u> for instructions) describing all wellbore activity and Mechanical Integrity Test as per item 1) above. Include the date(s) of the well work, and the setting depths of installed equipment: internally corrosive protected tubing, tubing on/off equipment just above the packer. The setting depths and descriptions of each are to be included in the subsequent sundry.

- 7) Compliance with a NMOCD Administrative Order is required, submit documentation of that authorization.
  - a) Approved injection pressure compliance is required.
  - b) If injection pressure exceeds the approved pressure you are required to reduce that pressure and notify the BLM within 24 hours.
  - c) When injection pressure is within 50 psig of the maximum pressure, install automation equipment that will prevent exceeding that maximum. Submit a subsequent report (Sundry Form 3160-5) describing the installed automation equipment within 30 days.
- 8) Unexplained significant variations of rate or pressure to be reported within 5 days of notice.
- 9) The casing/tubing annulus is required to be monitored for communication with injection fluid or loss of casing integrity. A BLM inspector may request verification of a full annular fluid level at any time.
- 10) A "Best Management Practice" is to maintain the annulus full of packer fluid at atmospheric pressure. Equipment that will display on site, continuous open to the air fluid level is necessary to achieve this goal.
- 11) Loss of packer fluid above five barrels per month indicates a developing problem. Notify BLM Carlsbad Field Office, Petroleum Engineering within 5 days.
- 12) A suggested format for monthly records documenting that the casing annulus is fluid filled is available from the BLM Carlsbad Field Office.
- 13) Gain of annular fluid pressure requires notification within 24 hours. Cease injection and maintain a production casing pressure of 0psia. Notify the BLM's authorized officer ("Paul R. Swartz" <<u>pswartz@blm.gov></u>, cell phone 575-200-7902). If there is no response phone 575-361-2822.
- 14) A request for increased wellhead pressures is to be accompanied by a step rate test. PRIOR to a Step Rate Test BLM CFO is requiring a Notice of Intent.
- 15) Class II (production water injection) wells will not be permitted stimulation injection pressures that exceed frac pressure.

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil\_and\_gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.