

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

710737
Name of Company: BOPCO, L.P. 210737 OPERATOR ☒ Initial Report ☐ Final Report
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Contact: Bradley Blevins
Telephone No. 575-887-7329
Facility Name: PLU #144 Flowline; The flow line spill was located on the PLU #140 Tank Battery pad Facility Type: Exploration and Production

Surface Owner: State Mineral Owner: API No. 30-015-30541

LOCATION OF RELEASE

Unit Letter E	Section 32	Township 23S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude: N 32.26294° Longitude: W 103.91075°

NATURE OF RELEASE

Type of Release: crude oil	Volume of Release: 6 bbls	Volume Recovered: 1 bbl
Source of Release: flow line	Date and Hour of Occurrence: 6/15/15 @ unknown	Date and Hour of Discovery: 6/15/15 @ 1:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? NM OIL CONSERVATION ARTESIA DISTRICT	
By Whom?	Date and Hour: JUN 22 2015	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

If a Watercourse was Impacted, Describe Fully.* Not Applicable
RECEIVED

Describe Cause of Problem and Remedial Action Taken.*
Corrosion caused a release of oil from the #144 flowline. Flow path from the release gathered around production equipment on the PLU #140 Battery.

Describe Area Affected and Cleanup Action Taken.*
The spill impacted approximately 1,200 sq. ft. of caliche on the PLU 140 tank battery pad. A vacuum truck was called and recovered 1 bbl of oil. The area will be remediated in accordance to the NMOCD and BLM guidelines for spill remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Assistant Remediation Foreman	Approval Date: <u>6/25/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 7/30/15

2RP-3067

* Attach Additional Sheets If Necessary