

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 21 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1520432614

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production	Contact	Rudy Zuniga
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575-390-5435
Facility Name	Parkway West Unit 15	Facility Type	Oil

Surface Owner	State	Mineral Owner	State	API No.	30-015-32363
---------------	-------	---------------	-------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	28	19S	29E	1310	North	660	East	Eddy

Latitude: N 32°63'50.88"

Longitude: W 104°07'33.49"

NATURE OF RELEASE

Type of Release Spill	oil	Volume of Release	6 bbl	Volume Recovered	5 bbls
Source of Release	Corrosion on bottom of tank	Date and Hour of Occurrence	7.16.2015 @2:30 PM	Date and Hour of Discovery	7.16.2015 @2:30 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Randy Dade @ OCD Heather Patterson @OCD		
By Whom?	Jesse Armendariz	Date and Hour	7.16.2015 3:00 PM 7.16.2015 8:00 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

On July 16, 2015, at 2:30 PM Devon Lease Operator was checking his route and found that the bottom of a tank had corrosion and was leaking oil into the containment. There was a total of 6 bbls of oil leaked, 5 bbls were recovered, and the other was in the gravel.

Describe Area Affected and Cleanup Action Taken.*

Devon Lease Operator switched the production out of the leaking tank into another tank, he then emptied out the leaking tank into another tank. Legendary was called out to do cleanup and 5 bbls of oil were recovered. The other was in the gravel and unable to be recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Corina Moya</u>	OIL CONSERVATION DIVISION Signed By <u>M. H. [Signature]</u> Approved by Environmental Specialist:	
Printed Name: <u>Corina Moya</u>		
Title: <u>Field Admin Support</u>	Approval Date: <u>7/23/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>corina.moya@dvn.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>7.17.2015</u> Phone: <u>575.746.5559</u>	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>8/24/15</u>	

Attach Additional Sheets If Necessary

2RP-3144