

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 24 2015

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1526753593

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Amy Ruth	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: James Ranch Unit #29 SWD Tank Battery	Facility Type: SWD	
Surface Owner: State of New Mexico	Mineral Owner: State of New Mexico	API No. 30-015-27735

LOCATION OF RELEASE

Unit Letter K	Section 36	Township 22S	Range 30E	Feet from the 1980	North/South Line South	Feet from the 2310	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.346409° Longitude -103.835868°

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 290 bbls	Volume Recovered 240 bbls
Source of Release Water Transfer Pump	Date and Hour of Occurrence 9/18/2015 at 6:30 pm	Date and Hour of Discovery 9/18/2015 at 7 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Heather Patterson	
By Whom? Tony Savoie	Date and Hour 9/19/2015 at 9:35 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A



Describe Cause of Problem and Remedial Action Taken.\*

Flange bolts on the south water transfer pump failed. Most of the fluids were released to zero perm containment. Pump was repaired.

Describe Area Affected and Cleanup Action Taken.\*

A total of 4235 square feet of pasture west of the containment was affected. The leak occurred within a previously remediated area containing a 20 mil plastic liner approximately 3 feet below ground surface. Vacuum truck recovered standing fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Amy Ruth		Signed By:  Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman		Approval Date: 9/24/15	Expiration Date: N/A
E-mail Address: ACRuth@basspct.com		Conditions of Approval:	
Date: 9-24-15	Phone: 432-661-0571	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 10/25/15	

\* Attach Additional Sheets If Necessary

Attached ☐

2RP-3302