Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM A	PPRO	VED
OMB No.	1004	-0135
Expires Ju	ly 31.	1996

5. Lease Serial No. NMLC029339A

6.	If Indian.	Allottee	or Tribe	Name

abandoned we	ell. Use Form 3160-3 (APD)) tor sucn proposals.		
SUBMIT IN TR	IPLICATE - Other Instruc	ctions on reverse sid	RECEIVEN	7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well Oil Well Gas Well			FEB 0 6 2006	8. Well Name and No. JACKSON A #35
2. Name of Operator BURNETT OIL CO., INC.		9. API Well No.		
3a. Address 801 CHERRY S		3b. Phone No. (include area	· +	30-015-34502
UNIT #9 FORT WORTH,		(817) 332~5108		10. Field and Pool, or Exploratory Area CEDAR LAKE, YESO
4. Location of Well (Footage, Sec.	, T., R., M., or Survey Description)		-	11. County or Parish, State
UNIT G, 2450' FNL, 2310 SEC 13 T17S R30F	0' FEL- SURFACE, UNIT	T B 340' FNL, 2312' FE		
12. CHECK AP	PROPRIATE BOX(ES) TO	INDICATE NATURE	F NOTICE, RE	PORT, OR OTHER DATA
TYPE OF SUBMISSION		TYPEC	F ACTION	
Notice of Intent	l	Deepen Z	Production (Start/F Reclamation	Resume)
Subsequent Report	Casing Repair	New Construction		Other NEW DRILL
Final Abandonment Notice	1	Plug and Abandon Plug Back		idon WEAL
If the proposal is to deepen dire Attach the Bond under which the following completion of the inv	ectionally or recomplete horizontally he work will be performed or prov- volved operations. If the operation inal Abandonment Notices shall be	y, give subsurface locations an ide the Bond No. on file with results in a multiple completion	d measured and true BLM/BIA. Require n or recompletion in	proposed work and approximate duration thereof vertical depths of all pertinent markers and zones d subsequent reports shall be filed within 30 days a new interval, a Form 3160-4 shall be filed once action, have been completed, and the operator has
11/17/05 Spud 14.75" well. w/FS, FC & centralizers (to	. 11/18/05 Run 10 JTS 9 5/ otal 6) on every other joint, i	/8" 32.30# H40 R3 ST&6 btm three joints thread lo	C new casing set ocked. Halliburtt	@ 387' w/notched Texas pattern shoe,
Thixotropic mix then 450 s	ks Premium plus. Plug down	n 7:34 am 11/18/05. Cen	nent did circulate	to surface. BLM was a no show.
WOC 18 hrs. NU wellhead	d & hydril. Test to 1000 psi-	held ok. 11/28/05 Log to	o vertical TD of	5216' and run total 114 its
(5205) 7" 23# J55 R3 LT& cement w/total 1980 sks 50	cC csg(77 jts w/Rytwrap ctg, /50 Cl "C" & Poz & 250 sks	,) FC @5157', DV tool @ s Cl "C" in two stages. Ha	2590' total 20 o ad cement to pit.	centralizers. Halliburton Plug down 3:00 PM 11/29/05. BLM

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed) STERLING RANDOLPH

Signature Date

Date

1/3//2006

THIS SPACE FOR FEDERAL-OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

a no show on this job. Set slips, install wellhead, NU BOP, tag DV tool & test all to 1500 PSI for 30 mins-held ok. Drill out to 5157'

12/15-18 MI comp rig, run sliding sleeves @ 6815', 6597',6406',6218',6007',5810',5595',5409',5191' and 5005'. Frac w/total 122,000 gals 20% Hcl, 11,000 gals 5% zonal acid and 170,798 gals gel.12/23-26 Run tubing and submersible pump, tie in flow line and put on

test to 1000 PSI- held ok. 12/02-09/2005 Cut window in 7" csg from 4719' to 4721'. Drill lateral to 6940'. Rig down 12/10/05

production.