

Submit I Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 Revised July 18, 2013
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Ellergy, Millerars and Ivaturar Resources	WELL API NO.
<u>District II</u> – (575) 748-1283	OIL CONSERVATION DIVISION	30-015-33349
811 S. First St., Artesia, NM 88210		5. Indicate Type of Lease
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE 🖌 FEE 🗌
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		
87505 SUNDRY NOT	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLI	CATION FOR PERMIT" (FORM C-101) FOR SUCH	State W
PROPOSALS,)		8. Weli Number
1. Type of Well: Oil Well 🗹 Gas Well 🗌 Other		
2. Name of Operator	,	9. OGRID Number
OXY USA	Inc.	16696
3. Address of Operator	0250 Midland TX 70710	10. Pool name or Wildcat
	0250 Midland, TX 79710	Carlsbad Delaware, S.
4. Well Location		. (
Unit Letter N:	780 feet from the <u>South</u> line and	2310 feet from the west line
Section 3	Township 235 Range 26E	NMPM County Eddy
the management of the same of the same of the same	11. Elevation (Show whether DR, RKB, RT, GR, et	
and the second	3305	A Company of the second s
12. Check A	Appropriate Box to Indicate Nature of Notice	e, Report or Other Data
NOTICE OF IN		
		BSEQUENT REPORT OF:
	PLUG AND ABANDON	
		RILLING OPNS. P AND A
	MULTIPLE COMPL	NT JOB
OTHER:	Deted operations. (Clearly stelle all pertinent details, a	and give pertinent datagingly ding estimated data
	ork). SEE RULE 19.15. SMAC. For Multiple C	
proposed completion or rec		completions. Attach wendore diagram of
proposed completion of rec		
	TD-12000' PBTD-2900' Perfs-2660-2732' Cil	BP-2900'
Approved for plugging of well bore only.	13-3/8" 48# csg @ 509' w/ 700sx, 17-1/2" hole, TC	DC-Surf-Circ
Liability under bond is retained pending receipt P-5/8" 43.5# csg @ 2490' w/ 1000sx 12-1/4" hole TOC surf circ		TOC Surf Circ
Brc-103 (Subsequent approximate p 29# CSB @ 9/50' w/ 2000sx, 8-1/2" hole TOC 1500' Calc		
Forms, www.cmnrd.state.nm.us/ocd.	5" 15# csg @ 9549-12000' w/ 325sx, 6-1/8" hole, T	「OC-9549'-Circ
	1. RIH & set CIBP @ 2610', M&P 40sx cmt to 2440'	ARTESIA DISTRICT
	2. Perf @ 1400', sqz 40sx cmt to 1300' WOC-Tag	
	3. Perf @ 559' sqz 210sx cmt to surface	NOV 0 2 2015
	10# MLF between plugs	
	Above ground steel tanks will be utilized	
Spud Date:	Rig Release Date:	
A I		
Well Dore must D	e phased by 11/03/20/6	
I hereby certify that the information	above is true and complete to the best of my knowled	lge and belief.
		-
	1 de la companya de l	
SIGNATURE	TITLE Sr. Regulatory Advi	SOT DATE 10 29 15
Type or print name <u>David Stewa</u>	rt E-mail address: <u>david_stewar</u>	t@oxy.comPHONE:432-685-5717
For State Use Only	1 -	
The A	10 Down Simo	madadu das
APPROVED BY: //////	TITLE TITLE TITLE	<u>/////////////////////////////////////</u>
Conditions of Approval (if any):	/	



<u>_</u>____



jî (

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: <u>OXY USA</u> Well Name & Number: <u>State W</u> **ZE 7** API #: <u>3</u>0 - O/S · 333 79

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.
- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.
- **12. 19.15.7.16 :** B. In the case of a dry hole, a complete record of the well on form C-105 with the attachments listed in Subsection A of 19.15.7.16 NMAC shall accompany the notice of intention to plug the well, unless previously filed. The division shall not approve the plugging report or release the bond the operator has complied with 19.15.7.16 NMAC.

DATE: 11/03/2015

APPROVED B

REVISED:11/2015

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman

7

č,

ŀ.

- o Devonian
- o Morrow
- o Wolfcamp
- o Bone Spring
- o Delaware
- o Any Salt Section (Plug at top and bottom)
- o Abo
- o Glorieta
- Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
 Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).