UNITED STATES UNITED STATES DEPARTMENT OF THE INTENMOIL CONSERVATION BUREAU OF LAND MANAGEMENT ARTESIA DISTRICT			T OMB	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMNM0558959	
SUNDRY	J. Lease Schalling.				
abandoned we	nis form for proposals to ell. Use form 3160-3 (AP	D) for such proposals.	6. If Indian, Allottee	or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.	
I. Type of Well			8. Well Name and N		
Oil Well Gas Well O 2. Name of Operator	OBS FEDERAL 9. API Well No.	з 			
EL PASO NATURAL GAS C	30-015-20659	· · · · · · · · · · · · · · · · · · ·			
 3a. Address 2 N. NEVADA AVENUE COLORADO SPRINGS, CO 80903 		3b. Phone No. (include area code Ph: 719-520-4557		or Exploratory N RANCH (MORROW)	
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Description	n)	11. County or Parish	11. County or Parish, and State	
Sec 4 T26S R24E Mer 6PM	SENE 1986FNL 660FEL		EDDY COUN	FY, NM	
12. CHECK APP	PROPRIATE BOX(ES) TO	O INDICATE NATURE OF	NOTICE, REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent		🗖 Deepen	Production (Start/Resume)	□ Water Shut-Off	
-	Alter Casing	Fracture Treat	Reclamation	U Well Integrity	
□ Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back	Temporarily Abandon Water Disposal		
13. Describe Proposed or Completed O					
If the proposal is to deepen direction Attach the Bond under which the w following completion of the involve testing has been completed. Final A determined that the site is ready for	bandonment Notices shall be fil	, give subsurface locations and meas the Bond No. on file with BLM/BL sults in a multiple completion or rec led only after all requirements, inclu-	ared and true vertical depths of altreet A. Required subsequent reparts shall completion in a new interval, Com S ding reclamation, have been completed	inent markers and zones. filed within 30 days 160-4 shall be filed once find the operator has	
BLM Bond No. on File: 400J	F2507			à Ta	
Integrity Test. Well was imm NMOCD requires the well to before being returned to serv Listed below is El Paso Natu documents are attached: We	ediately shut in and will re be plugged and abandone ice. ral Gas Company's propos ellbore Diagrams (Current	ation) well failed a NMOCD- v main so until it is plugged and ed or repaired by 12/06/15 and sed plans for plugging the we Wellbore and Proposed Plug	vitnessed Mechanical d abandoned. d to be re-tested I. The following ged Wellbore).	160-4 shall be filed once and the operator has the operator has	
Proposed plugs - all depende	ent on cement coverage b	ehind pipe.	Accepted for MixOC	racord 2	
14. I hereby certify that the foregoing	Electronic Submission # For EL PASO NA	321718 verified by the BLM We TURAL GAS COMPANY, sent t for processing by ED FERNAN	Il Information System o the Carlsbad	-	
Name (Printed/Typed) ANTHON					
Signature (Electronic	Submission)	Date 10/27/2	2015		
	· · · · · · · · · · · · · · · ·	OR FEDERAL OR STATE			
			TPETROLEUM ENGINER	R	
_Approved By		Title		- Date	
Conditions of approval, if any, are attached. Approval of this notice does certify that the applicant holds legal or equitable title to those rights in the which would entitle the applicant to conduct operations thereon.			DEC - 1 2015 Kenneth Rennic	ĸ	
Title 18 U.S.C. Section 1001 and Title 4. States any false, fictitious or fraudulen	3 U.S.C. Section 1212, make it a statements or representations as	a crime for any person knowing y and s to any matter within its jurisd ction	BUREAU OF LAND MANAGEMEN CARLSBAD FIELD OFFICE	Tagency of the United	
** OPERA	TOR-SUBMITTED ** C	PERATOR-SUBMITTED	** OPERATOR-SUBMITTE	D **	

•

.

Pb-P

Additional data for EC transaction #321718 that would not fit on the form


32. Additional remarks, continued

1) Notify BLM 24 hours prior to commencement of work. 2) Rig up and install BOPs. 3) Release packer and pull tubing and packer out of hole.	
3) Release packer and pull tubing and packer out of hole.	
4) <u>Set CIBP + 2 sacks of cement (0 6.825)</u> 5) Load hole with fluid and run a cement bond log from TD to surface. 5) PILM with 7/01 tubing and cost a 20 costs compare alug from 5 500' 5 400'	
D) KIR W/Z-770, UDIND AND SODUA ZU SACK CEMENLORUD ITUM D DUU-D 400	
7) Pull up hole with tubing and spot a 15 sack cement plug from 1.700'-1.600'. See COA	
8) Pull tubing out of hole.	
9) Perforate squeeze holes @ 750' and at 50' in 5-1/2" casing.	•
	CDA.
 10) <u>Run tubing and retainer in and set retainer @ 700'.</u> 11) Pump 25 sacks of cement through retainer; leaving 3 sacks of cement on retainer. 	<u> </u>
12) Pull tubing out of hole.	

13) Tie onto casing, pump top plug down casing through squeeze holes and up surface casing.14) Set surface marker.

Ĺ

El Paso Natural Gas




PBTD @ 7063' GL

TD 7-7/8" hole @ 7109' GL

le @ 7109' GL

4 jis, 5-1/2", 14#, K55, 8K, ST&C csg from 0 – 82', 2 jts, 5-1/2", 15.5#, K55, 8R, ST&C csg from 82' – 148', 157 jts, 5-1/2", 14#, K55, 8R, ST&C csg from 148' – 5176'', 60 jts, 5-1/2", 15.5#, K55, 8R ST&C csg from 5176' – 7109' GL



OBS FEDERAL 3 30-015-20659 El Paso Natural Gas Company Surface Location: Sec. 4, T. 26S, R. 24E Conditions of Approval

Notify BLM at 575-361-2822 (Eddy County) a minimum of 24 hours prior to commencing work. Some procedures are to be witnessed, which for this case shall be the tagging of certain Cement Plugs. If there is no response, leave a voice mail with the API#, workover purpose and a call back phone number.

Work to be completed by within ninety (90) days from the approval date.

- 1. Operator is approved to set a Cast-Iron Bridge Plug (CIBP) at 6825 feet and set cement as a cap as outlined in **Step #4** of the notification. A tag at 6775 feet is required, which shall be witnessed by BLM.
- As per Step #5, Operator shall submit an electronic copy of Cement Bond Log to the BLM. This can be done via email to <u>krennick@blm.gov</u>. Continue with procedure if assumed Top of Cement is indicated by the log. Contact the BLM if otherwise.
- 3. Operator shall set a Balance Plug to isolate the top of the Morrow formation. This plug shall have minimum length of 160 feet, covering the interval of 6300 to 6140 feet. Tag is required.
- 4. Operator shall set a Balance Plug to isolate the pressure associated with the Lower and the Upper Pennsylvanian, more specifically the Strawn formation. This plug shall have minimum length of 160 feet, covering the interval of 5935 to 5775 feet. Tag is required.
- 5. Operator is approved to set a Balance Plug for the interval of 5500 to 5400 feet as outlined in **Step #6**. Additional cement shall be required to ensure that the top of the Wolfcamp formation is properly isolated. Because of this, a tag at 5300 feet is required which shall be witnessed by BLM.
- 6. Operator shall set a Balance Plug to isolate the top of the Bone Spring formation. This plug shall have minimum length of 130 feet, covering the interval of 3640 to 3510 feet. Tag is required.

- 7. Operator is approved to set a Balance Plug from 1700 to 1600 feet to isolate casing leak as outlined in **Step #7**. Tag is required.
- 8. Operator shall then set a "Balance Plug" to cover the surface casing shoe at the interval of 759 to 659 feet. Please note no retainer is allowed as outlined in Step #10.
- 9. Operator is approved to tie onto casing, and then set top plug through the perforations at 400 feet and up the surface casing. This top plug is to cover any cave/ karst that may exist. As well as Operator is approved to set surface marker. Tag is required.
- 10. Surface disturbance beyond the originally approved pad must have prior approval.
- 11. Closed loop system required.
- 12. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 13. Operator to have H2S monitoring equipment on location.
- 14. A minimum of a 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above precharge. The pre-charge test shall follow requirements in Onshore Order #2.
- 15. Subsequent sundry required detailing work done. Operator to include well bore schematic of current well condition when work is complete.
- 16. See attached for the general guidelines to permanently abandon Federal Wells and reclamation procedure.

KGR 12012015

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.** Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Interim Reclamation Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses.

Interim reclamation consists of minimizing the footprint of disturbance by reclaiming all portions of the well site not needed for production operations. The portions of the cleared well site not needed for operational and safety purposes are recontoured to a final or intermediate contour that blends with the surrounding topography as much as possible. Sufficient level area remains for setup of a workover rig and to park equipment. Topsoil is respread over areas not needed for all-weather operations. Production facilities should be clustered to maximize the opportunity for interim reclamation. In order to inspect and operate the well or complete workover operations, it may be necessary to drive, park, and operate on restored, interim vegetation within the previously disturbed area. This is generally acceptable provided damage is repaired and reclaimed following use.

To reduce final reclamation costs; maintain healthy, biologically active topsoil; and to minimize habitat, visual, and forage loss during the life of the well, all salvaged topsoil should be spread over the area of interim reclamation, rather than stockpiled.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). Interim reclamation is to be completed within 6 months of well completion.
- 3. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with interim reclamation as per approved APD or Sundry Notice. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
- 4. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 5. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Linda Denniston Environmental Protection Specialist 575-234-5974 Robertson, Jeffery Natural Resource Specialist 575-361-2632

Trishia Bad Bear Natural Resource Specialist 575-393-3612