State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin

Cabinet Secretary

David Catanach, Director

Oil Conservation Division

Brett F. Woods, Ph.D. Deputy Cabinet Secretary



Response Required - Deadline Enclosed

Underground Injection Control Program "Protecting Our Underground Sources of Drinking Water"

30-Mar-16

MEMORIAL PRODUCTION OPERATING, LLC

500 DALLAS SUITE 1800 HOUSTON TX 77002-

LETTER OF VIOLATION and SHUT-IN DIRECTIVE Failed Mechanical Integrity Test

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

URNHAM GRAYBURG SAN ANDRES UNIT No.001C				30-015-04049-00-00
		Active Injection - (All Types)		P-2-17S-30E
Test Date:	3/22/2016	Permitted Injection PSI:	Actual PSI:	
Test Reason:	5-year Test	Test Result: F	Repair Due:	6/25/2016 ·
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Other Internal Failure	FAIL CAUSE:	
Comments on	MIT: Informed by operator, v	vell will not pass MIT.		
JRNHAM GRAYBURG SAN ANDRES UNIT No.001D			30-015-04056-00-00	
		Active Injection - (All Types)		F-2-17S-30E
Test Date:	3/23/2016	Permitted Injection PSI:	Actual PSI:	
Test Reason:	Post Workover Test	Test Result: F	Repair Due:	6/26/2016
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Permit Violation	FAIL CAUSE:	
	MIT: Repaired? Failure on 2/	11/15, No paperwork on repairs. Reporting inj	ection from April	- Nov 2015 despite

NORTH SQUARE LAKE UNIT No.012

30-015-04856-00-00

Active Injection - (All Types)

P-19-16S-31E

Test Date:

3/23/2016

Permitted Injection PSI:

Actual PSI:

Test Reason:

Post Workover Test

Test Result:

Repair Due:

Test Type:

Std. Annulus Pres. Test

FAIL TYPE: Permit Violation

FAIL CAUSE:

Comments on MIT:

Repaired? Failure on 2/10/15 5/19/15 - intend to P&A. Well not plugged. No c103 subsequent.

NORTH SOUARE LAKE UNIT No.005

Active Injection - (All Types)

30-015-10322-00-00 L-20-16S-31E

Test Date:

3/23/2016

Permitted Injection PSI:

Actual PSI:

Test Reason:

Test Result:

Repair Due:

6/26/2016

6/26/2016

Test Type:

Post Workover Test

Std. Annulus Pres. Test

FAIL TYPE: Permit Violation

FAIL CAUSE:

Comments on MIT:

Renaired? Failure on 2/10/15 5/19/15 - intend to P&A

Well not plugged. Shut-in, looks like it might have been repaired. No c103 subsequent.

30-015-20536-00-00

Test Date:

3/22/2016

LOCO HILLS A FEDERAL No.002

Active Injection - (All Types) Permitted Injection PSI:

Actual PSI:

N-10-17S-30E 1750

Test Reason:

FEDERAL R No.007

5-year Test

Test Result:

Repair Due:

Test Type:

6/25/2016

Std. Annulus Pres. Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: Well will not hold pressure.

Active Injection - (All Types)

30-015-20695-00-00

Test Date:

3/22/2016

B-10-17S-30E

Test Reason:

Permitted Injection PSI:

Actual PSI:

1900

5-year Test

Test Result:

Repair Due: FAIL CAUSE:

6/25/2016

Test Type:

FAIL TYPE: Other Internal Failure Std. Annulus Pres. Test Comments on MIT: Well will not hold pressure. Fluid came from ground around casing,

30-015-20696-00-00

Active Injection - (All Types)

H-10-17S-30E

Test Date:

3/22/2016

Permitted Injection PSI:

Actual PSI:

FAIL CAUSE:

750

Test Reason:

5-year Test

Test Result:

Repair Due:

6/25/2016

Test Type:

FEDERAL R No.008

Std. Annulus Pres. Test

Comments on MIT: Well will not hold pressure. 15 bbls then went on vacuum.

FAIL TYPE: Other Internal Failure

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely.

KILHARD INGUS

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.