## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin
Cabinet Secretary

David Catanach, Director Oil Conservation Division

Brett F. Woods, Ph.D. Deputy Cabinet Secretary



### \*Response Required - Deadline Enclosed\*

Underground Injection Control Program
"Protecting Our Underground Sources of Drinking Water"

26-Apr-16

LINN OPERATING, INC. 600 TRAVIS STREET SUITE 4900 HOUSTON TX 77002-7002

# LETTER OF VIOLATION and SHUT-IN DIRECTIVE Failed Mechanical Integrity Test

### Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

### MECHANICAL INTEGRITY TEST DETAIL SECTION

H E WEST B No.026				30-015-05060-00-00
		Active Injection - (All Types)		I-3-17S-31E
Test Date:	4/12/2016	Permitted Injection PSI:	Actual PSI:	160
Test Reason:	5-year Test	Test Result: F	Repair Due:	7/16/2016
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Other Internal Failure	FAIL CAUSE:	
Comments on	MIT: Well will not hold pres	sure. 4 attempts to pressure up.		
J L KEEL B	No.007			30-015-05108-00-00
		Active Injection - (All Types)		C-8-17S-31E
Test Date:	4/11/2016	Permitted Injection PSI:	Actual PSI:	1380
Test Reason:	5-year Test	Test Result: F	Repair Due:	7/15/2016
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Other Internal Failure	FAIL CAUSE:	
Comments on !	MIT: Well will not hold press	sure. After dumping in 20 bbls, well went on	vacuum.	

J L KEEL B No.012 30-015-05111-00-00

Active Injection - (All Types)

A-8-17S-31E

Test Date: 4/11/2016

Permitted Injection PSI:

Actual PSI:

Test Reason:

5-year Test

Test Result:

Test Type:

FAIL TYPE: Other Internal Failure Std. Annulus Pres, Test

Repair Due: **FAIL CAUSE:** 

30-015-05317-00-00

Comments on MIT: SKELLY UNIT No.063

Active Injection - (All Types)

E-21-17S-31E

Test Date:

4/12/2016

Permitted Injection PSI:

Actual PSI:

1340

7/15/2016

Test Reason:

5-year Test

Test Result:

Repair Due:

7/16/2016

Test Type:

Std. Annulus Pres. Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: SKELLY UNIT No.075

Well will not hold pressure.

Well will not hold pressure.

30-015-05333-00-00

Active Injection - (All Types) Permitted Injection PSI:

Actual PSI:

N-21-17S-31E

Test Date: Test Reason:

4/25/2016 Annual IMIT

Test Result:

F

Repair Due:

7/29/2016

Test Type:

Bradenhead Test

FAIL TYPE: Other Internal Failure

**FAIL CAUSE:** 

No guage on tubing. Continuous flow from casing. Comments on MIT:

**SKELLY UNIT No.052** 

Active Injection - (All Types)

30-015-05345-00-00

Test Date:

4/12/2016

Permitted Injection PSI:

Actual PSI:

J-22-17S-31E 1260

Test Reason:

5-year Test

Test Result: F Repair Due:

7/16/2016

Test Type:

Std. Annulus Pres. Test

FAIL TYPE: Other Internal Failure

**FAIL CAUSE:** 

Comments on MIT:

**SKELLY UNIT No.088** 

Well would not pressure-up. Took 12 bbls to load.

30-015-05426-00-00 A-28-17S-31E

Test Date:

4/25/2016

Active Injection - (All Types) Permitted Injection PSI:

Test Reason:

Annual IMIT

Test Result: F Actual PSI:

Repair Due: 7/29/2016

Test Type:

Bradenhead Test

FAIL TYPE: Permit Violation

FAIL CAUSE:

Comments on MIT: Original failure on 4/8/2015. Not repaired from previous failure. Out of compliance over 1 year,

TURNER B No.047

Active Injection - (All Types)

30-015-05435-00-00 B-29-17S-31E

Test Date:

4/12/2016

Permitted Injection PSI:

Actual PSI:

1430

Test Reason:

5-year Test

Test Result:

FAIL TYPE: Other Internal Failure

Repair Due: **FAIL CAUSE:**  7/16/2016

Test Type:

**TURNER B No.068** 

Comments on MIT:

Std. Annulus Pres. Test

Well will not hold pressure.

30-015-05452-00-00 P-29-17S-31E

Test Date:

4/13/2016

Active Injection - (All Types) Permitted Injection PSI:

Actual PSI:

Test Reason:

Annual IMIT

Test Result:

Repair Due: 7/17/2016

Test Type:

Bradenhead Test

FAIL TYPE: Permit Violation

**FAIL CAUSE:** 

Comments on MIT:

Repaired? Surface is cemented. No paperwork on repair.

Original failure on 5/5/2015. Not repaired from previous failure. Out of compliance over 1 year.

**TURNER B No.053** 

Active Injection - (All Types)

30-015-05472-00-00 I-30-17S-31E

7/17/2016

Test Date: Test Reason: 4/13/2016 Annual IMIT

Permitted Injection PSI: Test Result:

Repair Due:

Test Type:

Bradenhead Test

F FAIL TYPE: Other Internal Failure

Comments on MIT: Guage reads 3300psi on tubing, (assume it is broken.) Continuous blow of fluid from casing.

FAIL CAUSE:

Actual PSI:

NORTH BENSON QUEEN UNIT No.025

30-015-10127-00-00

7/17/2016

Active Injection - (All Types)

N-28-18S-30E

Test Date:

4/13/2016

Permitted Injection PSI:

Actual PSI:

Test Reason: Test Type:

Annual IMIT

Test Result:

Repair Due: FAIL CAUSE:

Comments on MIT:

Bradenhead Test FAIL TYPE: Permit Violation

SKELLY UNIT No.107

Original failure on 2/17/2015. Not repaired from previous failure. Out of compliance over 1 year.

30-015-20410-00-00

Active Injection - (All Types)

E-27-17S-31E

Test Date:

4/25/2016

Permitted Injection PSI:

Actual PSI:

Test Reason:

Annual IMIT

Test Result:

Repair Due:

7/29/2016

Test Type:

Bradenhead Test

FAIL TYPE: Permit Violation

FAIL CAUSE:

Comments on MIT:

Original failure on 4/8/2015. Not repaired from previous failure. Out of compliance over 1 year.

30-015-23122-00-00

**RED LAKE UNIT No.016** 

Active Injection - (All Types)

O-25-16S-28E

Test Date: Test Reason:

4/13/2016 Annual IMIT Permitted Injection PSI: Test Result:

Repair Due: 7/17/2016

Test Type:

Bradenhead Test

FAIL TYPE: Permit Violation

FAIL CAUSE:

Actual PSI:

Comments on MIT:

Original failure on 2/17/2015. Not repaired from previous failure. Out of compliance over 1 year.

30-015-24016-00-00

**RED LAKE UNIT No.012** 

Active Injection - (All Types)

I-25-16S-28E

Test Date:

4/13/2016

Permitted Injection PSI:

Actual PSI: Repair Due:

Test Reason:

Annual IMIT

Test Result:

7/17/2016

Test Type:

Bradenhead Test

FAIL TYPE: Permit Violation

FAIL CAUSE:

Original failure on 2/17/2015. Not repaired from previous failure. Out of compliance over 1 year.

Comments on MIT: J L KEEL B No.034

Active Injection - (All Types)

30-015-25447-00-00 H-6-17S-31E

Test Date:

4/11/2016

Permitted Injection PSI:

Actual PSI:

1250

Test Reason:

Annual IMIT

Test Result:

Repair Due: FAIL CAUSE:

7/15/2016

Test Type:

Bradenhead Test FAIL TYPE: Other Internal Failure Comments on MIT: Took a while to load, but would not hold pressure.

30-015-25934-00-00

J L KEEL B No.037

Active Injection - (All Types)

Test Date:

Permitted Injection PSI:

E-5-17S-31E

Test Reason:

4/11/2016

Actual PSI:

1450 7/15/2016

5-year Test

Test Result:

Repair Due:

Test Type:

**TURNER A No.057** 

FAIL CAUSE:

FAIL TYPE: Other Internal Failure Std. Annulus Pres. Test Well is leaking from cap. Need to replace gasket and re-test.. Comments on MIT:

30-015-29000-00-00

C-19-17S-31E

Test Date:

Active Injection - (All Types) Permitted Injection PSI:

Actual PSI:

Test Reason:

4/14/2016 Annual IMIT

Test Result:

Repair Due: 7/18/2016

Test Type: Comments on MIT:

FAIL TYPE: Permit Violation Bradenhead Test FAIL CAUSE: Original failure on 3/25/2015. Not repaired from previous failure. Out of compliance over 1 year. Part of

WFX946 implementation.

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. \* Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.