

Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103			
District 1 – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals enviration Resource	es Revised July 18. 2013 WELL API NO.			
District II - (575) 748-1283	NM OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	30-015-35098			
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE			
1000 Rio Brazos Rd., Aztec, NM 87410 District_IV – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505	RECEIVED	V-2516			
SUNDRY NOT	TCES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name			
	DSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ICATION FOR PERMIT" (FORM C-101) FOR SUCH	mostey cutyon phi state com			
PROPOSALS.) 1. Type of Well: Oil Well	8. Well Number				
2. Name of Operator	Gas Well 🛛 Other	9. OGRID Number			
Yates Petroleum Corporation 3. Address of Operator	025575 10. Pool name or Wildcat				
105 South Fourth Street, Artesia, 1	Mosley Canyon; Bone Spring				
4. Well Location					
Unit Letter <u>A</u> :	660 feet from the North line and	660 feet from the East line			
Section 5	Township 24S Range 25. 11. Elevation (Show whether DR, RKB, RT, G				
	3814'GR	(, eic.)			
12. Check	Appropriate Box to Indicate Nature of No	tice, Report or Other Data			
NOTICE OF I	NTENTION TO:	SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK 🗌	PLUG AND ABANDON 🛛 REMEDIAL	WORK ALTERING CASING			
		E DRILLING OPNS. P AND A			
		EMENT JOB			
CLOSED-LOOP SYSTEM					
		ils, and give pertinent dates, including estimated date			
of starting any proposed w	ork). SEE RULE 19.15.7.14 NMAC. For Multip				
proposed completion or re	completion.				
Yates Petroleum Corporation plans to p	lug and abandon this well as follows:				
1. MIRU all safety equipment as neede	ed for H2S environment.				
2. TIH to drill out composite frac plug	set at 5400' and clean out down to 8220'. Spot a 105 st	x Class "C" cement plug from 7581'-8220' across the			
stage tool and Wolfcamp top. WOC and tag, reset if necessary. 3. Set a 7 inch CIBP at 4968' then cap it with 25 sx Class "C" cement. This will leave a plug over open Bone Spring perfs. WOC and tag, reset if					
necessary.	it with 25 sx class C cement. This will leave a plug	over open Bone Spring peris. wOC and tag, reset in			
4. Spot a 140 sx Class "C" cement plug	g from 1800'-2653'. This will leave a plug across casin	g shoe and TOC on the production casing. WOC and tag,			
reset if necessary.5. Perforate at 520' and establish circu	lation up the 9-5/8" x 7" annulus. Spot a 200 sx Class	"C" cement plug inside and outside 7" casing from 0-520',			
this will form surface plug and plug acr	oss surface casing shoe. WOC and tag, reset if necessa				
6. Cut off wellhead, install dry hole ma	irker and clean location.				
Wellbore schematics attached		Approved for plugging of well bore only. Liability under bond is retained pending receipt			
F		of C-103 (Subsequent Report of Well Plugging)			
Spud Date:	Rig Release Date:	which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.			
WELL MUST BE	· · ·				
I hereby certify that the information	above is true and complete to the best of my know	wledge and belief.			
SIGNATURE	TITLE Regulatory Report	ting Supervisor DATE June 17, 2016			
Type or print name <u>Tina Hu</u> For State Use Only	erta E-mail address: <u>tinah@yatespetrole</u>	eum.com PHONE: <u>575-748-4168</u>			
	10	concer iloniani			
APPROVED BY: flabert 2 line TITLE COMPLIANCE OFFICER DATE 6/22/2016					
Conditions of Approval (if any):					

<u> </u>				
(if any):	×.	SEE	ATTAC HED	RADIS
	N -		11 11 - 11-0	





CONDITIONS FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases

- 1. Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 7. Produced water will not be used during any part of the plugging operation.
- 8. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 10. Class 'C' cement will be used above 7500 feet.
- 11. Class 'H' cement will be used below 7500 feet.
- 12. A cement plug is required to be set 50' above and 50' below, all casing shoes, casing stubs, DV tools, attempted casing cut offs, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 13. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 14. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 15. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 16. No more than **3000' is allowed between cement plugs in cased hole and 2000' in open** hole.
- 17. Formations to be isolated with cement plugs are:
 - A) Fusselman
 - B) Devonian
 - C) Morrow

- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 18. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, cement will be set 50' below to 50' above perforation inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and well number
- 3. API number
- 4. Unit letter
- 5. Quarter section (feet from North, South, East or West)
- 6.Section, Township and Range
- 7. Plugging date
- 8. County

(SPECIAL CASES)

AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude be GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)