Office	State of New Mexico)	Form C-103	
District 1 - (575) 393-6161	Energy, Minerals and Natural R	Resources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240			API NO. 24447	
<u>District II</u> - (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		ate Type of Lease	
District III - (505) 334-6178	1220 South St. Francis Dr.		TATE FEE X	
1000 Rio Brazos Rd., Aztec. NM 87410 <u>District IV</u> - (505) 476-3460	Santa Fe, NM 87505		Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	·	V. 2		
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease	Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			BOGGS FEE	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				
1. Type of Well: Oil Well Gas Well X Other			8. Well Number #1	
2. Name of Operator BC OPERATING, INC.			9. OGRID Number 160825	
3. Address of Operator P.O. BOX 50820		10. Pool	10. Pool name or Wildcat	
MIDLAND, TX 79710		ESP	ESPERANZA; DELAWARE	
4. Well Location				
Unit Letter [:	1980 feet from the SOUTH	line and990	feet from the <u>EAST</u> line	
Section 21	Township 22S Range		EDDY County	
The state of the second	11. Elevation (Show whether DR, RKB	R, RT, GR, etc.)	"是我们的是我们的	

12 Charle An		of Matian Donast a	n Othan Data	
12. Check Ap	propriate Box to Indicate Nature	e of Notice, Report of	r Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK		MEDIAL WORK	☐ ALTERING CASING ☐	
TEMPORARILY ABANDON ☑ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A			NS.□ PANDA □	
PULL OR ALTER CASING	MULTIPLE COMPL 🔲 CAS	SING/CEMENT JOB		
DOWNHOLE COMMINGLE]			
CLOSED-LOOP SYSTEM		IED.		
OTHER:	ed operations. (Clearly state all pertine	HER:	neut datas including estimated data	
). SEE RULE 19.15.7.14 NMAC. For			
proposed completion or recon		i Munipie Completions.	Attach wellbore diagram of	
•				
	poses to temporarily abandon the subje			
1. MIRU pulling unit, install BOP's, and pull production tubing				
2. Set CIBP @ +/-3,510' and dump bail 35' of cement on top of CIBP. Note that top existing perforation is at 3,560'.				
 GBIH with production tubing and circulate well with fresh water containing 1% KCL. Perform mechanical integrity pressure test on casing and obtain chart. 				
	=	•		
Leave well temporari	y abandoned.	TA status may be	granted after a	
successful MIT test is performed.			it is performed.	
		Contact the OCD t	o schedule the test	
		so it may be witne		
		LAST PROD	, , ,	
<u></u>	7	_ (//// //200	W [.] = 3.	
Spud Date:	Rig Release Date:			
I hereby certify that the information about	ove is true and complete to the best of	my knowledge and belief	f.	
SIGNATURE CERCULATORY ANALYST DATE 7.14.2016				
X				
Type or print name SARAH PRESLEY E-mail address: spresley@bcoperating.com PHONE: 432-684-9696				
For State Use Only	E-mail address: spr	esley@bcoperating.com	THORE. ISB OUT SUS	
	1		. 1	
APPROVED BY: 7	1	LIMUE OFFI	. 1	

Boggs Fee #1

Existing wellbore

13%" 54.50# K55 STC @ 600'

Delaware Perfs 3,560' to 3,586' Squeezed w/150 sx

Delaware Perfs 3,804' to 3,809' Squeezed w/ ?? sx

Delaware Perfs 5,250' to 5,310' Squeezed w/50 sx

9 1/4" 36# K55 STC @ 5,354

Casing Stub @ ± 8,100'

TOC @ 8,220'

Cement plug 9,157' to 8,931'

CIBP 9,450'

Lower Wolfcamp Perfs 9,583' to 9,873'

CIBP 10,476' w/ 35' cmt Strawn Perfs 10,526' to 10,538'

CIBP 11,500' w/ 50' cmt

Morrow Perfs 11,514' to 11,583'

Morrow Perfs 11,790' to 11,888'

PBTD 11,909'

5 1/2" - 17# S95 LTC 8rd @ 11,960'

