

Submit I Copy To Appropriate District	State of New Mexico		Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resources		August 1, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> - (575) 748-1283	OV. COMERNAL TRANSPORTER		30-015-33559
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505		STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa I C, INVI 67303		6. State Oil & Gas Lease No. VO-6967
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Bobber State
PROPOSALS.) 1. Type of Well: Oil Well 🔯 Gas Well 🔲 Other			8. Well Number 1
2. Name of Operator		9. OGRID Number	
COG Operating LLC 3. Address of Operator			229137 10. Pool name or Wildcat
550 W Texas, Ste. 1300, Midland, TX 79701			McMillan Escarpment; Bone Spring Gas
4. Well Location			
Unit Letter <u>E</u> :	1980 feet from the N	line and	feet from the W line
Section 30	Township 20S Rai	nge 27E	NMPM County Eddy
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			:-)
	3241' GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
•			
			SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WOR TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DR			_
DOWNHOLE COMMINGLE	<u> </u>		
OTHER:	П	OTHER:	П
	pleted operations. (Clearly state all		nd give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
1. Set 5 1/2 CIBP @ 6120'. 2. Circulate hole w/ mud laden fluid.			
3. Spot 25 sx cement @ 6120-6020. — WOE 4 HRS 2 TAB			NM OIL CONSERVATION
4. Spot 25 sx cement (a)	2953-2853. (Bone Springs)		ARTESIA DISTRICT
5. Spot 35 sx cement @ 2520-2320. (shoe) - WOE HRS > TA L			JUL 20 2016
6. Perf & Sqz 45 sx cement @ 2000-1875. WOC & Tag (Delaware) 7. Perf & Sqz 45 sx cement @ 1250-1150. (San Andres) - WOL 4HAS + TAL			
9. Perf & Sqz 45 sx cement @ 100-surface.			RECEIVED
10.Cut off wellhead and weld on Dry Hole Marker.		Approved for plugging of well bore only.	
			Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging)
		<u> </u>	which may be found at OCD Web Page under
Spud Date:	Rig Release	Date:	Forms, www.cmnrd.state.nm.us/ocd.
WELL MUST BE	PLUBER BY 7	120/2012	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
the state of the s			
SIGNATURE / Lu / h	术 、 TITLE A	i mit	DATE 7-20-16
Type or print name 13. 14 14 15 E-mail address: beware bon and Associate PHONE: 432. 580-7161			
APPROVED BY: Salut 2 Regil TITLE COMPLIANCE OFFICER DATE 7/20/2016			
Conditions of Approval (if any):			

Form provided by Forms On-A-Disk · (214) 340-9429 · FormsOnADisk.com





CONDITIONS FOR PLUGGING AND ABANDONMENT

District II / Artesia N.M.

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work.

- A notice of intent to plug and abandon a wellbore is required to be approved before plugging
 operations are conducted. A cement evaluation tool is required in order to ensure isolation of
 producing formations, protection of water and correlative rights. A cement bond log or other
 accepted cement evaluation tool is to be provided to the division for evaluation if one has not
 been previously run or if the well did not have cement circulated to surface during the original
 casing cementing job or subsequent cementing jobs.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 7. Produced water will not be used during any part of the plugging operation.
- 8. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 10. Class 'C' cement will be used above 7500 feet.
- 11. Class 'H' cement will be used below 7500 feet.
- 12. A cement plug is required to be set 50' above and 50' below, Formations, all casing shoes, casing stubs, DV tools, attempted casing cut offs, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 13. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 14. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 15. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 16. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.

- 17. Formations to be isolated with cement plugs are:
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 18. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, and cement will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and well number
- 3. API number
- 4. Unit letter
- 5. Quarter section (feet from North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging date
- 8. County

(SPECIAL CASES)

AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)