District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action													
NABIL	12854	42275		<b>OPERA</b>	TOR .	٥							
Name of Co					dley Blevins								
		mod, Suite 70		Telephone No. 575-887-7329									
Facility Name: PLU 347 Facility Type: Exploration and Production													
Surface Owner: Federal Mineral Owner:							Federal API No. 30-015-38668						
	LOCATION OF RELEASE												
Unit Letter C	Section 11	Township 25S	Range 30E	Feet from the 540	North/	South Line	Feet from the 1440	East/We	est Line	County Eddy			
Latitude: 32.150845 Longitude: 103.855589													
NATURE OF RELEASE													
Type of Release: Produced Water Source of Release: Failed connection on wellhead							Volume of Release: 273 barrels Volume Recovered: 230 barrels						
Source of Re	lease: Faile	d connection of		Date and Hour of Occurrence: Date and Hour of Discovery: 10-07-16 @ 11:00am Date and Hour of Discovery: 10-07-16 @ 12:30pm						:			
Was Immedia	te Notice (	Given?		If YES, To Whom?									
☐ Yes ☐ No ☐ Not Required							Mike Bratcher, Heather Patterson, Jim Amos BLM via email						
By Whom? Bradley Blevins Was a Watercourse Reached?							Date and Hour: 10-7-16 @ 3:43pm						
was a water	course Read	ched?	If YES, Volume Impacting the Watercourse.										
If a Watercourse was Impacted, Describe Fully.*													
			<u></u>										
Describe Cause of Problem and Remedial Action Taken.*  The lease operator arrived on location and found the release was caused by corrosion on the nipple that connects the tubing gauge to the Baird BPV, the													
nipple broke off causing the release. Vacuum trucks were called to the location and were able to recover 230 barrels of fluid from the location. All fluid													
remained on the well pad.													
Describe Ara	a Affected	and Cleanup A	Action Tal	van *				<del></del>	· · · · · · · · · · · · · · · · · · ·				
				cation and began i	removing	g the saturate	d surface soils an	d stockpil	ed soil or	plastic unt	il the m	aterial can be	
				s also sampled or						-			
I hereby certi	fy that the	information gi	ven above	is true and comp	lete to th	ne best of my	knowledge and u	inderstand	that purs	suant to NM	OCD r	ules and	
regulations al	l operators	are required to	o report as	nd/or file certain r	elease no	otifications a	nd perform correc	ctive actio	ns for rel	eases which	may er	ndanger	
				ce of a C-141 report investigate and r									
				otance of a C-141									
federal, state, or local laws and/or regulations.													
		•					OIL CON	SERVA	ATION	DIVISIO	<u>N</u>		
Signature:	Den	May 5											
Printed Name	- Bradley I	Rlevins		Approved by Environmental Specialist:									
T TANKE T TANK	. Brudiey i	31011113		·	Mulila			11	Λ				
Title: Assista	nt Remedia	tion Foreman		Approval Date: 1) Expiration Date: N H									
E-mail Addre	ess: bblevin	is@basspet.co		Conditions of Approval:									
Date: 10	10 1	<i>,</i>		Conditions of Approval: Remediation per O.C.D. Rules & Guidelinated SUBMIT REMEDIATION PROPOSAL NO									
		ets If Necess		: 432-214-3704		LATER THAN: 11/2/16 200 2021							
						LAIEN	17171			Ök	¥-;	74 JI	