	Do not use thi abandoned we	is form for proposals to dr II. Use form 3160-3 (APD)	for such proposed in the second	RICUC	6. If Indian, Allottee or	Tribe Name	
	SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposes SUBMIT IN TRIPLICATE - Other instructions on Veverse Side 11				7. If Unit or CA/Agreement, Name and/or No. NMNM68294X		
	1. Type of Well Oil Well Sas Well Oth		EIVED	8. Well Name and No. BIG EDDY UNIT 166			
	2. Name of Operator BOPCO LP	RACIE J CHERRY	HERRY		9. API Well No. 30-015-36019		
	3a. Address P O BOX 2760 MIDLAND, TX 79702	3 F	b. Phone No. (include area code) Ph: 432-683-2277)	10. Field and Pool, or I SAND POINT; A		
	4. Location of Well (Footage, Sec., 7				11. County or Parish, a		
	Sec 11 T21S R28E Mer NMP NWSW 2380FNL 660FEL EDDY COUNTY, NM					, NM	
	12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
	TYPE OF SUBMISSION TYPE OF ACTION						
	Notice of Intent	AcidizeAlter Casing	 Deepen Fracture Treat 	Produc	tion (Start/Resume) nation	□ Water Shut-Of □ Well Integrity	
	Subsequent Report	Casing Repair	□ New Construction	Recom		🗖 Other	
	Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back	⊠ Tempo □ Water	rarily Abandon Disposal		
	The well is not capable of con	intercial production in the c	unent zone nowever, there	•	8" thg. woc & tag.		
	potential for recompletion in a TA procedure is as follows: 1. Install 5K BOP and test. Re	more favorable economic e elease packer. POOH with s	ame and 2-3/8" tbg.	SPOT = 11883 WOC	-11663 to a \$ tag.	from T errer Morrow	
	potential for recompletion in a TA procedure is as follows:	more favorable economic e elease packer. POOH with s 7# casing. Set at 11,370' (4)	ame and 2-3/8" tbg. B' above current Ato <u>ka per</u> pressure test CIBP to 500 p	SP0+ 11883 WOC orations) T DSI. 10104	-11663 to a \$ tag.	from 7 one r Morrow must be onlir ubmitted,	
	potential for recompletion in a TA procedure is as follows: 1. Install 5K BOP and test. Re 2. RIH with CIBP for 5-1/2", 1 CIBP to verify plug is set. Loa	more favorable economic e elease packer. POOH with s 7# casing. Set at 11,370' (4 d casing with 2% KCL and p true and correct. Electronic Submission #35 For BO Committed to AFMSS for pro	ame and 2-3/8" tbg. ame and 2-3/8" tbg. B' above current Atoka post bressure test CIBP to 500 p After or p 0360 verified by the BLM We PCO LP, sent to the Carlsba bressing by DEBORAH MCK	SPot 1883 $\omega o c$ σc	- 11 6 6 3' to 6	must be onlir	
· · · · · · · · · · · · · · · · · · ·	potential for recompletion in a TA procedure is as follows: 1. Install 5K BOP and test. Re 2. RIH with CIBP for 5-1/2", 1 CIBP to verify plug is set. Loa 14. I hereby certify that the foregoing is Name (<i>Printed/Typed</i>) TRACIE J	more favorable economic e elease packer. POOH with s 7# casing. Set at 11,370' (4 d casing with 2% KCL and p true and correct. Electronic Submission #35 For BO Committed to AFMSS for pro CHERRY	environment. ame and 2-3/8" tbg. B' above current Atoka ped bressure test CIBP to 500 p After or p 0360 verified by the BLM We PCO LP, sent to the Carlsba bressing by DEBORAH MCK Title REGU	SPot 1883 000 0rations) T si. 0104 Informáticad INNEY on 09 ATORY AN	- 11 6 6 3' to 6	must be onlir	
	potential for recompletion in a TA procedure is as follows: 1. Install 5K BOP and test. Re 2. RIH with CIBP for 5-1/2", 1 CIBP to verify plug is set. Loa	more favorable economic e elease packer. POOH with s 7# casing. Set at 11,370' (4 d casing with 2% KCL and p s true and correct. Electronic Submission #35 For BO Committed to AFMSS for pro CHERRY Submission)	ame and 2-3/8" tbg. ame and 2-3/8" tbg. B' above current Ato <u>ka perfo</u> ressure test CIBP to 500 p After 0360 verified by the BLM We PCO LP, sent to the Carlsba bocessing by DEBORAH MCK Title REGU	SPot 1883 Woo contaitions) T Sol (Oloy) lans to F Ill Informátic ad INNEY on 09 LATORY AN 2016	- 11 6 6 3' to 6	must be onlir	
· · ·	potential for recompletion in a TA procedure is as follows: 1. Install 5K BOP and test. Re 2. RIH with CIBP for 5-1/2", 1 CIBP to verify plug is set. Loa 14. Thereby certify that the foregoing is Name (<i>Printed/Typed</i>) TRACIE J Signature (Electronic S	more favorable economic e elease packer. POOH with s 7# casing. Set at 11,370' (4 d casing with 2% KCL and p true and correct. Electronic Submission #35 For BO Committed to AFMSS for pro CHERRY Submission) THIS SPACE FOR	ame and 2-3/8" tbg. ame and 2-3/8" tbg. B' above current Ato <u>ka-ped</u> pressure test CIBP to 500 p After O 360 verified by the BLM We PCO LP, sent to the Carlsba pressing by DEBORAH MCK Title REGUI Date 09/08/2 R FEDERAL OR STATE	SPot 1883 000 Contaitions) T Dosi. (0/04 Informátic ad INNEY on 05 ATORY AN 2016 OFFICE t	- 11 6 6 3' to 6	must be onlir	
· · ·	potential for recompletion in a TA procedure is as follows: 1. Install 5K BOP and test. Re 2. RIH with CIBP for 5-1/2", 1 CIBP to verify plug is set. Loa 14. Thereby certify that the foregoing is Name (<i>Printed/Typed</i>) TRACIE J Signature (Electronic S	more favorable economic e elease packer. POOH with s 7# casing. Set at 11,370' (4 d casing with 2% KCL and p s true and correct. Electronic Submission #35 For BO Committed to AFMSS for pro CHERRY Submission)	ame and 2-3/8" tbg. ame and 2-3/8" tbg. B' above current Ato <u>ka-ped</u> pressure test CIBP to 500 p After O 360 verified by the BLM We PCO LP, sent to the Carlsba pressing by DEBORAH MCK Title REGUI Date 09/08/2 R FEDERAL OR STATE	SPot 1883 Woo contaitions) T Sol (Oloy) lans to F Ill Informátic ad INNEY on 09 LATORY AN 2016	- 11 6 6 3' to 6	must be onlir	
	potential for recompletion in a TA procedure is as follows: 1. Install 5K BOP and test. Re 2. RIH with CIBP for 5-1/2", 1 CIBP to verify plug is set. Loa 14. I hereby certify that the foregoing is Name (<i>Printed/Typed</i>) TRACIE J Signature (Electronic S	more favorable economic e elease packer. POOH with s 7# casing. Set at 11,370' (4 d casing with 2% KCL and p s true and correct. Electronic Submission #35 For BO Committed to AFMSS for pro CHERRY Submission) THIS SPACE FOR Auchlis Krueng d. Approval of this notice does no intable title to those rights in the su	ame and 2-3/8" tbg. B' above current Ato <u>ka-performent</u> B' above current Ato <u>ka-performent</u> Or P O360 verified by the BLM We O360 verified by the BLM We Date 09/08/2 Date 09/08/2 	SPot 1883 000 Contaitions) T Dosi. (0/04 Informátic ad INNEY on 05 ATORY AN 2016 OFFICE t	- 11 6 6 3' to 6	must be onlir ubmitted.	
•	potential for recompletion in a TA procedure is as follows: 1. Install 5K BOP and test. Re 2. RIH with CIBP for 5-1/2", 1 CIBP to verify plug is set. Loa 14. I hereby certify that the foregoing is Name (<i>Printed/Typed</i>) TRACIE J Signature (Electronic S Approved By Conditions of approval, if any, are attache certify that the applicant holds legal or equ	more favorable economic e elease packer. POOH with s 7# casing. Set at 11,370' (4 d casing with 2% KCL and p strue and correct. Electronic Submission #35 For BO Committed to AFMSS for pro CHERRY Submission) THIS SPACE FOR Muchlis Krueng d. Approval of this notice does no intable title to those rights in the st ict operations thereon. U.S.C. Section 1212, make it a crit	ame and 2-3/8" tbg. B' above current Atoka performer pressure test CIBP to 500 p After Or p 0360 verified by the BLM We PCO LP, sent to the Carlsba breessing by DEBORAH MCK Title REGUI Date 09/08/2 CEFEDERAL OR STATE Title Title Title Office	SPo+ 1883 000 orations) T osi (0/04 lans to F lans to F lans to F lans to F lans to F Color Col	- 11 6 6 3' to a \$ tag 2017 the well P & A must be s on'System 0/09/2016 () JALYST SEPROVEE UM ENGINEER	must be onlin ubmitted.	

Additional data for EC transaction #350360 that would not fit on the form


32. Additional remarks, continued

3. RIH with 4" bailer. Tag CIBP and dump bail 35' Class H cmt (+/- 3.5 sx) on top of CIBP. POOH with wireline and WOC 24 hrs.

4. Perform MIT - load hole and pressure test to 500 psi for 30 mins and chart.

NMOCD and BLM representatives will be notified of MIT 24 hrs prior to test.





BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, **placed with tubing**.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval <u>with well bore diagram</u> with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Big Eddy Unit 166 30-015-36019

- 1. Well may be approved to be TA/SI for a period of 12 months or until 10/04/2017 after successful MIT and subsequent report is submitted.
- **2.** This will be the last TA approval for this well.
- 3. Contact BLM 24 Hrs. prior to setting of plugs so as it may be witnessed.