4	Submit Copy To Appropriate DistrictState of New MexicoOfficeEnergy, Minerals and Natural Resources	Form C-103 Revised July 18, 2013	
	1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-015-28938	
	District III - (5/5) /476-1263OIL CONSERVATION DIVISION811 S. First St., Artesia, NM 882100IL CONSERVATION DIVISIONDistrict III - (505) 347-61781220 South St. Francis Dr.1000 Rio Brazos Rd., Aztec, NM 874101220 South St. Francis Dr.District IV - (505) 476-3460Santa Fe, NM 875051220 S. St. Francis Dr., Santa Fe, NM1220 South St. Francis Dr.	 5. Indicate Type of Lease STATE X FEE 6. State Oil & Gas Lease No. 	
	87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name OXY SPIKE	
	PROPOSALS.) 1. Type of Well: Oil Well Gas Well X Other	8. Well Number 1	
	2. Name of Operator BC OPERATING, INC.	9. OGRID Number 160825	
	3. Address of Operator P.O. BOX 50820	10. Pool name or Wildcat	
	MIDLAND, TX 79710	FRONTIER HILLS; STRAWN (GAS)	
4. Well Location Unit Letter H : 1980 feet from the NORTH line and 660 feet from the EAST line			
	Section 33 Township 23S Range 26E 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM EDDY County	
	12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
	NOTICE OF INTENTION TO: SUBS PERFORM REMEDIAL WORK ⊠ PLUG AND ABANDON □ REMEDIAL WORK TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DRIL PULL OR ALTER CASING □ MULTIPLE COMPL □ CASING/CEMENT DOWNHOLE COMMINGLE □ CLOSED-LOOP SYSTEM □ COMMENCE DRIL		
-	OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates including estimated date	
	of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
BC Operating, Inc. respectfully requests approval to re-cement the Oxy Spike #1.			
** See Attached procedure and Wellbore Diagrams**			
		NM OIL CONSERVATION ARTESIA DISTRICT	
		OCT 1 4 2016	
		RECEIVED	
	Spud Date: Rig Release Date:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Curah Dura TITLE REGULATORY ANALYST DATE 10.11.2016			
Type or print name SARAH PRESLEY			
APPROVED BY: Mart 2 Mal TITLE COMPLIANCE OFFICER DATE 10/17/16			
(Conditions of Approval (if any):		

Procedure

- Kill well.
- Remove wellhead.
- Unset and POH w/production packer.
- GIH w/ 5 1/2" retrievable bridge plug on tubing and set it at ± 9,800'.
- Dump 35' of sand on top of plug.
- GIH w/ perforating gun and shoot 4 squeeze holes at 5,000'.
- GIH w/ 5 1/2" packer and set it at ± 4,950'.
- Establish injection rate into squeeze perforations.
- GIH w/cement retainer and set it at ± 4,950'.
- Recement 5 ½" casing to surface as follows:
 - Pump 20 bbls mud flush.
 - > Mix and pump 450 sacks of 65/35 Class C.
 - > Mix and pump 200 sacks of 50/50 Class C.
 - Drillout cement retainer and cement.
- Test squeeze to 500 psi.
- Go in hole and cleanout sand off bridge plug.
- Retrieve RBP.


٠

- GIH w/ 5 1/2" production packer and set it at ± 9,800'.
- Install production equipment
- Return to production.

This document contains information that is confidential and proprietary to BC Operating, INC. and should not be disclosed to third parties without prior written permission from BC Operating, Inc..

BC PERATING, INC.

٤



BC PERATING, INC.

