Submit 1 Copy To Appropriate District Office State of New Me	
<u>District I</u> – (575) 393-6161 Energy, Minerals and Natu 1625 N. French Dr., Hobbs, NM 88240	ral Resources Revised July 18, 2013 WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION	DIVISION 30-015-31911
<u>District III</u> – (505) 334-6178 1220 South St. Fran	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	7505 6. State Oil & Gas Lease No. V-2705
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PL	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well ☑ Gas Well ☐ Other 2. Name of Operator	9. OGRID Number
EOG Y Resources, Inc.	9. OGRID Number 025575
3. Address of Operator 105 South Fourth Street, Artesia, NM 88210	10. Pool name or Wildcat Lost Tank; Delaware
4. Well Location Unit Letter C: 330 feet from the North line and 2310 feet from the West line	
Section 2 Township 22S Range 31E NMPM Eddy County	
11. Elevation (Show whether DR	
3514'GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐	REMEDIAL WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING	CASING/CEMENT JOB
CLOSED-LOOP SYSTEM	
OTHER:	OTHER:
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
EOG Y Resources, Inc. plans to plug and abandon this well as follows:	
1. MIRU all safety equipment as needed. NU BOP. TOH with production equipment. TIH with bit and scraper to 8251'. Load hole	
with plugging mud then spot 25 sx Class "H" cement plug from 8251'-8071', this will cover top of Bone Spring. 2. Set a 5-1/2" CIBP at 6898' then dump 35' Class "C" cement on top of CIBP. — WOL II HIS I TO L 3. Perforate 5-1/2" casing at 4354'. Spot 35 sx Class "C" cement inside and outside 5-1/2" casing from 4354'-4214', this will cover top	
of Bell Canyon.	
4. Spect 25 sx Class "C" cement plug from 4137'-3997', 8-5/8" casing shoe and DV tool. WOC and tag. — PEAF F SQ 5. Spect a continuous 320 sx Class "C" cement plug from 3997'-800', this will cover entire salt section and 13 3/8" casing shoe. WOC and tag SPEAF & 850' — ATTEMPT TO SQUEEZE— WOC FTMG— IF IT DOES MOT SQUEEZE—	
and taspent @ 850' - ATTEMPT TO SQUEEZE-	WOLFTAG-IFITDOES NOT SQUEEZE-
6. Spot a 10 sx Class "C" cement plug from 100' up to surface.7. Cut off wellhead, install dry hole marker and clean location.	SPOT PLUE FROM 950'(T SALT)
·	AM OIL COMSERVATION
Wellbore schematics attached	Plugging of well bore only. ARTESIA DISTRICT Plugging of well plugging) PEC 1 2 2016 DEC 1 2 2016
Approved for	plusging recained Well Probable of Well Probable of bond is recained Well Probable of bond is recained Well Probable of Well Page under
Spud Date: Rig Release Date:	Plugging of well bore of the plugging of the p
SELL MUST BE PLUCCED BY 12/18/17	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE	
Type or print name Tina Huerta E-mail address: tina huerta@eogresources.com PHONE: 575-748-4168 For State Use Only	
APPROVED BY: Shalat I kent TITLE COMPLIANCE OFFICER DATE 12/13/2016	
APPROVED BY: SEA ATTACHES CONPLIANCE OFFICER DATE 12/13/2016 Conditions of Approval (if any): & SEE ATTACHES COLD -5	

WELL NAME: Graham AKB State #5 FIELD: LOCATION: 330' FNL & 2310' FWL of Section 2-22S-31E Eddy Co., NM GL: 3,514' ZERO: KB: 3,532' **CASING PROGRAM** SPUD DATE: 5/8/02 COMPLETION DATE: 6/27/02 **COMMENTS**: API No.: 30-015-31911 13-3/8" 48# H-40 850' 8-5/8" 32# J-55 4,087 Current: 5-1/2" 15.5# & 17# J-55 8,406' **Formation Tops** 17 1/2" Hole 310' Rustler 13-3/8" @ 850' Cmt w/ 700 sx (circ) 908' T. Salt B. Salt 4,001' Bell Cnyn 4,304' 11" Hole Chrry Cnyn 5,374' Livngstn R. 6,924' Brshy Cnyn 7,094' DV Tool @ 4,016' Bone Sprng 8,201' 8-5/8" @ 4,087' Cmt w/ 1300 sx (circ) 7 %" Hole Sqz'd holes in casing @ 4,495'-4,527' Sqz'd holes in casing @ 5,422'-5,622' TOC @ 5,678' by CBL Livingston Ridge Perfs: 6,948'-6,992' (45) Not to Scale 5-1/2" @ 8,406' 10/24/16 TD: 8.406' Cmt w/ 1150 sx BAL PBTD: 8,363'

WELL NAME: Graham AKB State #5 FIELD: LOCATION: _330' FNL & 2310' FWL of Section 2-22S-31E Eddy Co., NM **GL**: 3,514' **ZERO**: **KB**: 3,532' **CASING PROGRAM** SPUD DATE: 5/8/02 COMPLETION DATE: 6/27/02 **COMMENTS**: API No.: 30-015-31911 13-3/8" 48# H-40 850' 8-5/8" 32# J-55 4,087' Proposed: 8,406' 5-1/2" 15.5# & 17# J-55 **Formation Tops** 17 1/2" Hole Rustler 310' PERF LSQ WORDTHE 13-3/8" @ 850' Cmt w/ 700 sx (circ) T. Salt 908' 4.001' B. Salt 10 sx cmt plug @ 100'-surface 4,304' Bell Cnyn IF NO SQ 11" Hole SPOT FROM Chrry Cnyn 5,374' 950'(+ SALT) 320 sx cmt plug @ 3,997'-800' Livngstn R. 6,924' Brshy Cnyn 7,094' 25 sx cmt plug @ 4,137'-3,997' DV Tool @ 4,016' Bone Sprng 8,201' PERF & SQUEEZE WULLTAR 8-5/8" @ 4,087' Cmt w/ 1300 sx (circ) 35 sx cmt plug @ 4,354'-4,214" WUL 4 HAS & TV & 7 1/8" Hole Sqz'd holes in casing @ 4,495'-4,527' Sqz'd holes in casing @ 5,422'-5,622' TOC @ 5,678' by CBL wer HHRS & TAR CIBP w/ 35' cmt @ 6,898' Livingston Ridge Perfs: 6,948'-6,992' (45) 25 sx cmt plug @ 8,251'-8,071' Not to Scale 5-1/2" @ 8,406' 10/24/16 TD: 8,406' Cmt w/ 1150 sx BAL PBTD: 8,363'

CONDITIONS FOR PLUGGING AND ABANDONMENT

District II / Artesia N.M.

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 7. Produced water will not be used during any part of the plugging operation.
- 8. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 9. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 10. Class 'C' cement will be used above 7500 feet.
- 11. Class 'H' cement will be used below 7500 feet.
- 12. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 13. All Casing Shoes Will Be Perforated and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing
- 14. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 15. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 16. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 17. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 18. Formations to be isolated with cement plugs are:
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 19. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County

(SPECIAL CASES)

AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)