Office <u>District [</u> – (575) 393-6161	State of New Mexico Energy, Minerals and Natural Resources				Form C-103 Revised July 18, 2013		
1625 N. French Dr., Hobbs, NM 88240					WELL API		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSER	VATION	DIVISION		30-015-0166	Type of Lease	
District III - (505) 334-6178 1000 Rio Brazos Rd , Aztec, NM 87410	1220 South St. Francis Dr.					TE [7] FEE [٦
District IV - (505) 476-3460	Santa F	⁵ e, NM 87	7505	ľ		& Gas Lease No.	<u> </u>
1220 S. St. Francis Dr., Santa Fe, NM 87505					647		
SUNDRY NO	TICES AND REPORTS O				7. Lease Na	ame or Unit Agreeme	nt Name
(DO NOT USE THIS FORM FOR PROP DIFFERENT RESERVOIR. USE "APPI PROPOSALS.)	OSALS TO DRILL OR TO DEE LICATION FOR PERMIT" (FOR	EPEN OR PLU RM C-101) FC	JG BACK TO A DR SUCH	•	·	Unit (309164)	<u> </u>
1. Type of Well: Oil Well	Gas Well 🗌 Other				8. Well Nu	mber 026B	
2. Name of Operator Apache Corporation					9. OGRID 1 873		
3. Address of Operator 303 Veterans Airpark Lane, Suite 1000 Midland, TX 79705					10. Pool name or Wildcat		
	1000 Midiand, IX /9/05				Empire; Abo	(22040)	
4. Well Location V Unit Letter K	: 1650 feet from the	South	line and	2310	fe	et from the West	line
Section 32	Township 17		nge 28E		NMPM	County Eddy	
	11. Elevation (Show w		RKB, RT, GR,	etc.)			
	• 3t	671' GL					:
12. Check	Appropriate Box to In	ndicate N	ature of Noti	ice, I	Report or O)ther Data	
			9				
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK D PLUG AND ABANDON							
			COMMENCE				
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEN	IENT	JOB		_
DOWNHOLE COMMINGLE							
CLOSED-LOOP SYSTEM]	п	OTHER:				
		the second se					<u> </u>
Describe proposed or com	pleted operations. (Clearl	lv state all n	pertinent details	. and	give pertinen	ut dates, including est	imated dat
 Describe proposed or com of starting any proposed y 	pleted operations. (Clearl vork). SEE RULE 19.15.7						
	vork). SEE RULE 19.15.7						
of starting any proposed v	vork). SEE RULE 19.15.7 ecompletion.						
of starting any proposed v proposed completion or re pache would like to perform the fol	vork). SEE RULE 19.15.7 ecompletion.						
of starting any proposed v proposed completion or re	vork). SEE RULE 19.15.7 ecompletion.						
of starting any proposed v proposed completion or re pache would like to perform the fol roducing Interval: 5,807-6,067' Objective: TA Wellbore. Currently pe	vork). SEE RULE 19.15.7 ecompletion. lowing work:	7.14 NMAC	2. For Multiple	Com	pletions: At	tach wellbore diagran	ı of
of starting any proposed v proposed completion or re pache would like to perform the fol roducing Interval: 5,807-6,067'	vork). SEE RULE 19.15.7 ecompletion. lowing work:	7.14 NMAC	2. For Multiple	Com	pletions: At	tach wellbore diagran	ı of
of starting any proposed w proposed completion or re pache would like to perform the fol roducing Interval: 5,807-6,067' Objective: TA Wellbore. Currently per bring it back to production.	vork). SEE RULE 19.15.7 ecompletion. lowing work:	7.14 NMAC	2. For Multiple	Com	pletions: At	tach wellbore diagran	ı of
of starting any proposed w proposed completion or re pache would like to perform the fol roducing Interval: 5,807-6,067' Objective: TA Wellbore. Currently per bold bring it back to production. Procedure: . POOH with rods and pump	vork). SEE RULE 19.15.7 ecompletion. lowing work: erforming geological and pe	7.14 NMAC	2. For Multiple	Com	pletions: At	tach wellbore diagran	ı of
of starting any proposed w proposed completion or re pache would like to perform the fol roducing Interval: 5,807-6,067' Objective: TA Wellbore. Currently per boring it back to production. Procedure: . POOH with rods and pump . Set a CIBP @ 5,780' and dump bo	vork). SEE RULE 19.15.7 completion. lowing work: erforming geological and pe ail 35' of cmt	7.14 NMAC	2. For Multiple	Com	pletions: At	tach wellbore diagran	ı of
of starting any proposed w proposed completion or re pache would like to perform the fol roducing Interval: 5,807-6,067' Objective: TA Wellbore. Currently per bold bring it back to production. Procedure: . POOH with rods and pump	vork). SEE RULE 19.15.7 ecompletion. lowing work: erforming geological and pe ail 35' of cmt asing to 500 psi	7.14 NMAC	2. For Multiple	Com	pletions: At	tach wellbore diagran	ı of
of starting any proposed w proposed completion or re pache would like to perform the fol roducing Interval: 5,807-6,067' bjective: TA Wellbore. Currently per bring it back to production. Procedure: . POOH with rods and pump . Set a CIBP @ 5,780' and dump b . Circulate fluid and pressure test c	vork). SEE RULE 19.15.7 ecompletion. lowing work: erforming geological and pe ail 35' of cmt asing to 500 psi	7.14 NMAC	2. For Multiple	Com	pletions: At	tach wellbore diagran	ı of
of starting any proposed w proposed completion or re apache would like to perform the foll producing Interval: 5,807-6,067' Objective: TA Wellbore. Currently performed bring it back to production. Procedure: . POOH with rods and pump . Set a CIBP @ 5,780' and dump b . Circulate fluid and pressure test c . Record the test on a chart and su	vork). SEE RULE 19.15.7 ecompletion. lowing work: erforming geological and pe ail 35' of cmt asing to 500 psi bmit to OCD for approval	7.14 NMAC	2. For Multiple	Com	pletions: At	tach wellbore diagran	ı of
of starting any proposed w proposed completion or re pache would like to perform the fol roducing Interval: 5,807-6,067' bjective: TA Wellbore. Currently per bring it back to production. Procedure: . POOH with rods and pump . Set a CIBP @ 5,780' and dump b . Circulate fluid and pressure test c	vork). SEE RULE 19.15.7 ecompletion. lowing work: erforming geological and pe ail 35' of cmt asing to 500 psi bmit to OCD for approval	7.14 NMAC	2. For Multiple	Com	pletions: At	tach wellbore diagran	ı of
of starting any proposed w proposed completion or re apache would like to perform the fol producing Interval: 5,807-6,067' Objective: TA Wellbore. Currently per bobring it back to production. Procedure: . POOH with rods and pump . Set a CIBP @ 5,780' and dump but . Circulate fluid and pressure test of . Record the test on a chart and sul	vork). SEE RULE 19.15.7 ecompletion. lowing work: erforming geological and pe ail 35' of cmt asing to 500 psi bmit to OCD for approval	7.14 NMAC	2. For Multiple	Com	pletions: At	tach wellbore diagran	ı of
of starting any proposed w proposed completion or re apache would like to perform the follow producing Interval: 5,807-6,067' Objective: TA Wellbore. Currently performing it back to production. Procedure: POOH with rods and pump Set a CIBP @ 5,780' and dump but Circulate fluid and pressure test of Record the test on a chart and sullow Spud Date: 03/13/1960	vork). SEE RULE 19.15.7 ecompletion. lowing work: erforming geological and pe ail 35' of cmt asing to 500 psi bmit to OCD for approval Rig	7.14 NMAC	2. For Multiple	e Com	pletions: Att	tach wellbore diagran	ı of
of starting any proposed w proposed completion or re apache would like to perform the fol producing Interval: 5,807-6,067' Objective: TA Wellbore. Currently per bobring it back to production. Procedure: . POOH with rods and pump . Set a CIBP @ 5,780' and dump but . Circulate fluid and pressure test of . Record the test on a chart and sul	vork). SEE RULE 19.15.7 ecompletion. lowing work: erforming geological and pe ail 35' of cmt asing to 500 psi bmit to OCD for approval Rig	7.14 NMAC	2. For Multiple	e Com	pletions: Att	tach wellbore diagran	ı of
of starting any proposed w proposed completion or re apache would like to perform the follow producing Interval: 5,807-6,067' Objective: TA Wellbore. Currently performing it back to production. Procedure: POOH with rods and pump Set a CIBP @ 5,780' and dump but Circulate fluid and pressure test of Record the test on a chart and sullow Spud Date: 03/13/1960	vork). SEE RULE 19.15.7 ecompletion. lowing work: erforming geological and pe ail 35' of cmt asing to 500 psi bmit to OCD for approval Rig n above is true and comple	7.14 NMAC etrophysical Release Da	2. For Multiple	e Com	pletions: Att	tach wellbore diagram	ating wellb
of starting any proposed w proposed completion or re apache would like to perform the follow producing Interval: 5,807-6,067' Objective: TA Wellbore. Currently performing it back to production. Procedure: POOH with rods and pump Set a CIBP @ 5,780' and dump but Circulate fluid and pressure test of Record the test on a chart and sullow Spud Date: 03/13/1960	vork). SEE RULE 19.15.7 ecompletion. lowing work: erforming geological and pe ail 35' of cmt asing to 500 psi bmit to OCD for approval Rig n above is true and comple	7.14 NMAC etrophysical Release Da	2. For Multiple	e Com	pletions: Att	tach wellbore diagran	ating wellb
of starting any proposed we proposed completion or respective of the second like to perform the following interval: 5,807-6,067' Descrive: TA Wellbore. Currently performing it back to production. Procedure: POOH with rods and pump Set a CIBP @ 5,780' and dump bills. Circulate fluid and pressure test of a chart and sulls Spud Date: O3/13/1960 I hereby certify that the informatio SIGNATURE	vork). SEE RULE 19.15.7 ecompletion. lowing work: erforming geological and pe ail 35' of cmt asing to 500 psi bmit to OCD for approval Rig n above is true and comple	7.14 NMAC etrophysical Release Da ete to the be TLE Regulat	2. For Multiple I studies to dete te:	e Com	pletions: Att	tach wellbore diagram	ating wellb
of starting any proposed we proposed completion or respective of the second like to perform the following interval: 5,807-6,067' Objective: TA Wellbore. Currently performing it back to production. Procedure: POOH with rods and pump Set a CIBP @ 5,780' and dump b. Circulate fluid and pressure test of a chart and sulf Spud Date: 03/13/1960 I hereby certify that the information SIGNATURE	vork). SEE RULE 19.15.7 ecompletion. lowing work: erforming geological and pe ail 35' of cmt asing to 500 psi bmit to OCD for approval Rig n above is true and comple	7.14 NMAC etrophysical Release Da ete to the be TLE Regulat	2. For Multiple	e Com	pletions: Att	tach wellbore diagram	ating wells
of starting any proposed we proposed completion or respective of the second like to perform the following interval: 5,807-6,067' Descrive: TA Wellbore. Currently performing it back to production. Procedure: POOH with rods and pump Set a CIBP @ 5,780' and dump bills. Circulate fluid and pressure test of a chart and sulls Spud Date: O3/13/1960 I hereby certify that the informatio SIGNATURE	vork). SEE RULE 19.15.7 ecompletion. lowing work: erforming geological and pe ail 35' of cmt asing to 500 psi bmit to OCD for approval Rig n above is true and comple	7.14 NMAC etrophysical Release Da ete to the be TLE Regulat	2. For Multiple I studies to dete te:	e Com	e feasibility fo and belief.	tach wellbore diagram	ating wellt ating wellt 8-1142
of starting any proposed we proposed completion or respective of the second like to perform the following interval: 5,807-6,067' Objective: TA Wellbore. Currently performing it back to production. Procedure: POOH with rods and pump Set a CIBP @ 5,780' and dump b. Circulate fluid and pressure test of a chart and sulf Spud Date: 03/13/1960 I hereby certify that the information SIGNATURE	vork). SEE RULE 19.15.7 ecompletion. lowing work: erforming geological and pe ail 35' of cmt asing to 500 psi bmit to OCD for approval Rig n above is true and comple	7.14 NMAC etrophysical Release Da ete to the be TLE Regulat	2. For Multiple I studies to dete te:	e Com	e feasibility fo and belief.	tach wellbore diagram	ating wellt ating wellt 8-1142



January 6, 2017


Empire ABO Unit # G-26 Legal Name: Empire ABO Unit #026B API # 30-015-01661 Eddy County, NM Producing Interval: **5,807-6,067'**

<u>Objective</u>: TA Wellbore. Currently performing geological and petrophysical studies to determine feasibility for recompletion. Evaluating wellbore to bring it back to production.

Procedure:

÷.

- 1. POOH with rods and pump
- 2. Set a CIBP @ 5,780' and dump bail 35' of cmt
- 3. Circulate fluid and pressure test casing to 500 psi
- 4. Record the test on a chart and submit to OCD for approval



(

(

ĺ