Submit 1 Copy To Appropriate District	State of	New Me	exico		Form C-103
Office <u>District 1</u> – (575) 393-6161	Energy, Minerals			Re	vised July 18, 2013
<u>District II</u> = (575) 595-0101 1625 N. French Dr., Hobbs, NM 88240 District II = (575) 748-1283				WELL API NO. 30-015-22307	
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	OIL CONSER			5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	1220 Sout	n St. Frai e, NM 8'			FEE
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Sama r	c , mivi o	1505	6. State Oil & Gas Lease	NO.
SUNDRY NOTIO	CES AND REPORTS O			7. Lease Name or Unit A	greement Name
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC				Bogle State Com	
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well 🔀 Other			8. Well Number 1	<u></u>
1. Type of Well: Oil Well 2. Name of Operator				9. OGRID Number	
· · · ·	N ENERGY PRODUCT	TION CON	APANY, LP.	6137	·
3. Address of Operator			OV 72102	10. Pool name or Wildcat Diamond Mound; Upper	
	EST SHERIDAN AVEN	UE, OKC	, OK 73102	Diamond Mound; Opper	renn (G)
4. Well Location Unit Letter : 2560	feet from the Nort	h lina an	d 660 feet	from the <u>East</u> line	
Unit Letter : 2560 Section 2	Township 16	h line an	ange 27E	NMPM Eddy, County	New Mexico
	11. Elevation (Show w		\sim		New Mexico
	3578'				
12. Check A	ppropriate Box to Ir	ndicate N	ature of Notice,	Report or Other Data	
NOTICE OF IN	TENTION TO		SUB	SEQUENT REPORT	OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK		
	CHANGE PLANS		COMMENCE DRI		A 🗌
	MULTIPLE COMPL		CASING/CEMENT	ГЈОВ 🗌	
DOWNHOLE COMMINGLE					
OTHER:			OTHER: Recomp	letion	\boxtimes
13. Describe proposed or compl					
of starting any proposed wor proposed completion or reco		.14 NMAG	C. For Multiple Cor	npletions: Attach wellbore	diagram of
proposed completion of reco	mpieuon.			ANP_	
			(2 COPY	
Devon Energy Production Compa	ny, LP Respectfully requ	ests Approv	val of SR to plug the	Wolfcamp and recomplete to	the Glorieta,
Verbal approval by Tim Gun (OC	D) on 12/29/14 for the rel	erenced w	ell as follows:		
Please see attached procedures and	d Wellbore Schematic for	the recom	pletion		
Attachment: Recompletion Proce	edures & Wellbore Schem	atic			
1					
I hereby certify that the information a	boye is true and comple	te to the b	est of my knowledge	e and belief.	
	lenan TIT				02.12.15
					<u></u>
Type or print and Erin Workman For State Use Only	E-mail address:	Erin.	workman@dvn.com	PHONE: <u>(4</u>	05)552-7970
·····		- ()			halia
APPROVED BY: <u>Peutono</u> // Conditions of Approval (if any):	vae Titi	ECOMP	LANCE Sh	ILEN DATE 3	27/17
The second secon					

DVN: Bogle St Com #1

API #30-015-22307

Lat/Long: 32° 57' 27.648" N, 103° 14' 32.064" W

Sec 2-T16S-R27E

Eddy County, NM

WBS: TBD

١

Purpose: Recomplete uphole

T.D. 8.780'	Well spud: 12/22/1977	PBTD: 6,440'
GLM: 3,578'	KBM: 3,590'	KB: 12

Casing and Tubing Data:

Size	Wt. lb/ft	Grade	Interval	(75% S.F.) Collapse	(75% S.F.) Burst	Drift	Capacity (bbls/ft)
13-3/8"	72	H-40	0 –345'	577	1,297	12.56"	-
8-5/8"	24	K-55	0 - 1632'	1,027	2,212	7.97	-
4-1/2"	11.6	K-55	0 - 1571'	3,720	4,012	3.875"	0.0155
4-1/2"	10.5	K-55	1571 - 6164'	3,007	3,592	3.927"	0.0159
4-1/2"	11.6	K-55	6164 - 8780'	3,720	4,012	3.875"	0.0155
2-3/8"	4.7	J-55	0 - 6340'	6,075	5,775	1.9"	.00387

Safety: All personnel will wear hard hats, safety glasses with side shields, and steel toed boots while on location. Assess wellhead working height for safety. If needed, use work platform or man-lift for fall protection.

Bogle St Com #1 Procedure:

1. Notify all regulatory agencies prior to initiation of work (if required) and Devon EHS personnel. Hold tailgate safety meetings prior to RU each morning and before each operational change or event.

- 2. ND Tree, NU 5K BOP, unset packer at 6275' and TOOH. LD pkr.
- 3. RU WL. RIH w/ CIPB for 4-1/2", 11.6# csg to 6320' and set. Dump 2 sx cmt.
- 4. TIH w/ 2-3/8" tbg (open ended) to ~6280' and tag TOC (should be at a minimum 6290, 30' above CIBP). Circulate the hole w/ 10# brine.

- 5. MIT casing to 500 psi for 30 min (calibrated to 1000 psi & 60 min) and report to NMOCD. If well does not MIT PU 4-1/2" 11.6# plug & packer and locate casing leak.
- 6. RU wireline w/ full lubricator & correlate gamma ray to open hole neutron log *Schlumberger Compensated Neutron-Formation Density dated 11/29/1977.* Shoot the Glorieta from 2,896'-2,911'w/ 3-1/8" slick guns @ 6 spf & 60° phasing.
- 7. PU 4-1/2" AS1X packer. RIH to ~2850' and set pkr. ND BOPE and NU wellhead and test per Devon guidelines.
- MIRU acid crew and test lines to 5,000 psi. Acid stimulate the Glorieta @ 2,896-2,911' with 2,000 gal 7.5% HCl NEFE w/ clay stabilizer & surfactant package. Max pressure is 3,500 psi. Pump job at max rate not to exceed 3,500 psi treating pressure. Flush with 1600 gal 2% KCl. Record ISIP, 5, 10, 15 min pressures. RD acid crew.
- 9. Flow Acid load back and flow well test. If necessary, RU swab equipment. Swab back acid u3.ntil load is recovered, fluid is clean, or the well kicks off. Record # of swab runs per hour, swabbed volume per hour, oil cut, and beginning and ending fluid levels.
- 10. RD swab, RDMO WSU. Tie in flow line and turn over to production.

Contact	Company	Office #	Mobile #
Ronnie Carre	Completions Foreman	(575)748-0179	(575)748-5528
Aaron Kidd	Completions Foreman	(575) 748-9936	(575) 513-1770
Brent Schroder	Engineer	(405) 552-4921	(405) 593-6714
Roy White	Production Foreman	(575)748-0194	(575)513-1741

