Submit I Copy To Appropriate District	State of New Mexico	Form C-103			
Office District [ ~ (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013			
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.			
District II - (575) 748-1283		30-015-21999			
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease			
District III ~ (505) 334-6178	1220 South St. Francis Dr.	STATE FEE X			
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505				
District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Sana i C, Mil 67565	6. State Oil & Gas Lease No.			
87505					
SUNDRY NOTI	7. Lease Name or Unit Agreement Name				
(DO NOT USE THIS FORM FOR PROPOS	CARLSBAD "13" COMM				
DIFFERENT RESERVOIR. USE "APPLIC	CARLSBAD 13 COMM				
PROPOSALS.)					
1. Type of Well: Oil Well	8. Well Number 1				
2. Name of Operator	9. OGRID Number 024471				
WADI PETROLEUM, INC., c/o Riddle Engineering Corp. Agent					
3. Address of Operator	10. Pool name or Wildcat				
PO Box 270130, CORPUS CHRIS	CARLSBAD MORROW, SOUTH				
4. Well Location					
Unit Letter G : 2040 feet from the EAST line and 1650 feet from the NORTH line					
Section 13	Township 22S Range 26E	NMPM County EDDY			
	11. Elevation (Show whether DR, RKB, RT, GR, etc. 3,144 GR	)			

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF IN PERFORM REMEDIAL WORK X TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE	DON CHANGE PLANS	SUBSEQUENT REPOR REMEDIAL WORK ALTER COMMENCE DRILLING OPNS. P AND CASING/CEMENT JOB	RING CASING
CLOSED-LOOP SYSTEM		OTHER:	

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

**OBJECTIVE: REPAIR TUBING/CASING COMMUNICATION** 

- 1. SET ISOLATION PLUG IN PACKER.
- 2. MOVE IN RIG UP WORKOVER RIG.
- 3. RIG DOWN TREE, RIG UP BOP. RELEASE ON-OFF TOOL.
- 4. PULL TUBING & ON-OFF OVERSHOT. SCAN TUBING WHILE PULLING OUT OF HOLE.
- 5. RUN BACK IN HOLE WITH REDRESSED ON-OFF OVERSHOT & TUBING, REPACLING BAD JOINTS.
- 6. RIG DOWN BOP, RIG UP TREE.
- 7. ACIDIZE, SWAB WELL IN AS NEEDED.
- 8. RETURN TO PRODUCTION.

Spud Date: 03/27/2017\_estimated

Rig Release Date: 03/31/2017 estimated

I hereby certify that the information above is true and somplete to the best of my knowledge and belief.						
SIGNATURE Educado 9 Redo	Le TITLE AGENT	DATE_ <u>03/23/2017</u>				
Type or print name EDUARDO A RIDDLE E-n	nail address: <u>e.a.riddle@riddle-eng.com</u>	PHONE: <u>(361) 452-2703</u>				
For State Use Only	. 1					
APPROVED BY: Conditions of Approval (if any):	MANADER	DATE_3-23-17				
Conditions of Approval (if any):						