
Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OII CONGERNATION PRINCIPAL	30-015-26299
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name Cooper AHH
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	8. Well Number
2. Name of Operator	Guo Mon Connec	9. OGRID Number
EOG Y Resources, Inc.		025575
3. Address of Operator	NIN	10. Pool name or Wildcat
104 South Fourth Street, Artesia, NM 88210 N. Seven Rivers; Glorieta-Yeso		
4. Well Location Unit Letter F:	1650 feet from the North line and	1650 feet from the West line
Section 1	Township 20S Range 24E	NMPM Eddy County
地名福格斯斯 斯图:	11. Elevation (Show whether DR, RKB, RT, GR, etc.,	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON A REMEDIAL WORL CHANGE PLANS COMMENCE DRI	
PULL OR ALTER CASING	<u> </u>	
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM	,	
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
RESUBMIT		
Yates Petroleum Corporation plans to plug and abandon this well as follows:		
1. MIRU all safety equipment as needed. NU BOP. Make a bit and scraper run to 2346'. 2. Set a 7" CIBP at 2336'. Spot a 25 sx Class "C" cement plug on top of CIBP. — WO E > THE PERF 3. Spot a 30 sx Class "C" cement plug from 1270'-1170' this will cover 9-5/8" casing shoe. WOC and tag. 4. Spot a 45 sx Class "C" cement plug from 150' up to surface. PROPOSE ALL SQ TIFE TE		
5. Remove all surface equipment and weld dry hole marker as per regulations.		
Wellbore schematics attached		
		only receipt
Spud Date:	Rig Release Date:	and believe with reserved west product.
	A 24 14 2 4 14 2 4 1 1 1 1 1 1 1 1 1 1 1	Justice of the state of the sta
WELL MUST BE PLUBBED BY 4/18 /18 /18 for phillips and the property of the prop		
I hereby certify that the information above is true and complete to the best of my knowledge and belief, the true to the best of my knowledge and belief to the best		
SIGNATURE TITLE Regulatory Specialist DATE April 18, 2017		
Type or print name Tina Huerta E-mail address: tina huerta@eogresources.com PHONE: 575-748-4168 For State Use Only		
APPROVED BY: //// Conditions of Approval (if any):	Hyul TITLE COMPLIANTE OFF	FICE DATE 4/18/17

SEE ATTACHED COA-S

NM OIL CONSERVATION

ARTESIA DISTRICT

APR 1 3 2015



NM OIL CONSERVATION

ARTESIA DISTRICT

APR 13 2015 WELL NAME: Cooper AHH #1 FIELD: N. Dagger Draw U. Penn LOCATION: 1,650' FNL & 1,650' FWL of Section 1-20S-24E Eddy, NM RECEIVED GL: 3,610' ZERO: **CASING PROGRAM** SPUD DATE: 5/6/90 COMPLETION DATE: 8/6/90 COMMENTS: API No.: 30-015-26299 9-5/8" 36# J55 STC 1,220 7" 26# N80 SB 7" 26# J55 SB/MV 2,854' 7" 23# J55 SB/MV 3,917" 45 sx cml plug @ 150-surface 7" 23# N80 MV 739ⁱ 7" 26# J55 MV 44' 8,134' 14-3/4" Hole **After** 30 ex cont plug @ 1,270:-1,170' - PERF L SQ - WOC J THG 9-5/8".@ 1,220 w/1100 sx (Clrc) CIBP w/ 25 sx cml @ 2,336' WCC+++C TOPS Yeso Perfs: 2,386-2,406' (21); 2,418-28' (11); 2,442-54' (15); 2,482'-2,510' (29) Glorieta 1,252' 2,2181 Yeso Cmt plug @ 3,541'-3,381' BS 3,491' Abo 4,832' Cmt plug @ 4,882'-4,722' WC 5.426' 8-3/4" Hole Canyon LS 7,598' Canyon Dolo 7,702' Cmt plug @ 5,376'-5,216' DV Tool @ 5,441' Cisco Shale Perfs: 7,480-7,550' (101) CIBP @ 7,651' w/ 35' of cement Squeezed Perfs: 7,715-17' (3); 7,783-7,791' (3); 7,808-16' (5) Szd w/750 bbls Marcli Gel Not to Scale Squeezed Perfs: 7,862-68' sqz'd w200 sx Class H Cmt 3/11/15 BAL TD: 8,150' 7" @ 8,134' w/ 1st Stage: 875 sx (Circ) 2nd Stage: 1225 sx (Circ)

CONDITIONS FOR PLUGGING AND ABANDONMENT

District II / Artesia N.M.

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 7. Produced water will not be used during any part of the plugging operation.
- 8. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 10. Class 'C' cement will be used above 7500 feet.
- 11. Class 'H' cement will be used below 7500 feet.
- 12. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 13. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing
- 14. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 15. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.

- 16. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 17. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 18. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - 1) Glorieta
 - J) Yates.
 - K) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 19. **If cement does not exist behind casing strings at recommended formation depths,** the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County

(SPECIAL CASES)

AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)