Submit 1 Copy To Appropriate District Office	State of They lyte	State of New Mexico	
<u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.
District II - (575) 748-1283	283 OH CONGERNATION DIVIGION		30-015-29123
811 S. First St., Artesia, NM 88210 <u>District III</u> — (505) 334-6178			5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 8741	Santa Fe, NM 87505		STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No. Federal NM-39635
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Mimosa Federal SWD 8. Well Number	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other SWD		3Y	
2. Name of Operator		9. OGRID Number	
EOG Y Resources, Inc.		025575	
3. Address of Operator 104 South Fourth Street, Artesia, NM 88210		10. Pool name or Wildcat	
4. Well Location		SWD; Devonian	
Unit Letter P: 635 feet from the South line and 330 feet from the East line			
Section 4 Township 20S Range 24E NMPM Eddy County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3795'GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
	INTENTION TO:		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRII			- :
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT			
OTHER: Plug back and add additional Devonian perforations OTHER: OTHER: OTHER: I3. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
EOG Y Resources, Inc. plans to plug back and add additional Devonian perforations:			
1. MIRU all safety equipment as needed.			
2. Release the packer and POOH with tubing. 3. RIH with GR/JB to 11,070 ft.			
4. Set a 7 inch CIBP at 11,050 ft.			
5. Tag top of CIBP and spot 100 sx Class H cement on top from 11,050 ft - 10,530 ft. WOC and tag, reset if necessary. 6. Set packer at 9000 ft. Conduct step rate test, do not exceed 1800 psi.			
7. If well has not lost significant disposal capacity skip to step 11.			
8. Perforate Devonian 9832 ft - 9954 ft (160). 9. Set the packer at 9780 ft.			
10. Pump 10,000g HCl acid with 240 ball sealers and flush acid with 65 bbls.			
11. POOH with work string and set a nickel plated packer and 3-1/2 inch plastic coated tubing at 9044 ft. Hydro test back in the hole.			
12. Load backside with packer fluid and test. Contact NMOCD to witness test. 13. Rig down and move out rig.			
Wellbore schematics attached			
Spud Date:	Rig Release Dat	to	
Spild Date.	Alg Release Dai	ie.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE TITLE Reporting Specialist DATE July 19, 2017			
Type or print name Tina Huerta E-mail address: tina huerta@eogresources.com PHONE: 575-748-4168 For State Use Only			
APPROVED BY: Person / NGE TITLE COMPLIANCE OFFICER DATE 7/19/17 Conditions of Approval (if any):			



