abandoned wen. Ose form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well 8. Ø Oil Well Gas Well Other 8. 2. Name of Operator Contact: CHEVRON USA INCORPORATED E-Mail: djvo@chevron.com 3a. Address 3b. Phone No. (include area code) 6301 DEAUVILLE BLVD Ph: MIDLAND, TX 79706 Ph:	HH SO 8 P2 5H							
1. Type of Well Gas Well Other 8. Image: Contact: Image: Contact: DORIAN K FUENTES 9. CHEVRON USA INCORPORATED E-Mail: djvo@chevron.com 9. 3a. Address 3b. Phone No. (include area code) 10 MIDLAND, TX 79706 Ph: 432-687-7631 10	Well Name and No. HH SO 8 P2 5H API Well No.	Name and/or No.						
Image: Contact: Ocher 2. Name of Operator Contact: DORIAN K FUENTES CHEVRON USA INCORPORATED E-Mail: djvo@chevron.com 9. 3a. Address 3b. Phone No. (include area code) 10 G301 DEAUVILLE BLVD Ph: 432-687-7631 10 MIDLAND, TX 79706 Ph: 432-687-7631 10	HH SO 8 P2 5H API Well No.							
CHEVRON USA INCORPORATED E-Mail: djvo@chevron.com 3a. Address 3b. Phone No. (include area code) 6301 DEAUVILLE BLVD Ph: 432-687-7631 MIDLAND, TX 79706 Ph: 432-687-7631		8. Well Name and No. HH SO 8 P2 5H						
6301 DEAUVILLE BLVD MIDLAND, TX 79706								
	10. Field and Pool or Exploratory Area WILDCAT							
	11. County or Parish, State							
Sec 17 T26S R27E SESW 255FNL 960FWL	EDDY COUNTY, NM							
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, RE	EPORT, OR OTHER I	DATA						
TYPE OF SUBMISSION TYPE OF ACTION								
Notice of Intent	(Start/Resume)	U Water Shut-Off						
□ Alter Casing □ Hydraulic Fracturing □ Reclamatio	n D	Well Integrity						
□ Subsequent Report □ Casing Repair □ New Construction □ Recomplete		Other						
□ Final Abandonment Notice □ Change Plans □ Plug and Abandon □ Temporaril □ Convert to Injection □ Plug Back □ Water Disp	y Abandon PD	Change to Original A PD						
 Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subseq following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, had determined that the site is ready for final inspection. Chevron respectfully request the ability to cement offline on the subject well. The summary provided is a brief description for drilling run casing, and cement offline; please refer to the attached. 	interval, a Form 3160-4 ma ave been completed and the	ust be filed once operator has						
should you have any questions to this request, please contact Rod @ 281-413-9794.	OIL CONSERVA ARTESIA DISTRICT	TION						
	AUG 09 2017							
	RECEIVED							
14. I hereby certify that the foregoing is true and correct. Electronic Submission #372989 verified by the BLM Well Information Sy For CHEVRON USA INCORPORATED, sent to the Carlsbad Committed to AFMSS for processing by DEBORAH MCKINNEY on 04/20/2017 (1	7DLM1431SE)							
Name (Printed/Typed) DORIAN K FUENTES Title REGULATORY SPEC	IALIST							
Signature (Electronic Submission) Date 04/17/2017								
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
_Approved By_OMAR_ALOMAR	R	Date 08/07/2017						
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Carlsbad								
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make the States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.	to any department or agenc	y of the United						

۰

+

(Instructions on page 2) ** BLM REVISED **

Delaware Basin Changes to APD for Federal Well



Well Names:

WELL NAME	WELL #	API NUMBER
<u>HH SO 8 P2</u>	<u>5H</u>	<u>30-015-43935</u>
<u>HH SO 8 P2</u>	<u>6H</u>	30-015-43934
<u>HH SO 8 P2</u>	<u>13H</u>	30-015-43933
<u>HH SO 8 P2</u>	<u>14H</u>	30-015-43931
<u>HH SO 8 P2</u>	<u>21H</u>	30-015-43927
<u>HH SO 8 P2</u>	<u>22H</u>	<u>30-015-43928</u>

Rig:

Patterson 815

CVX CONTACT:

RODERICK MILLIGAN DRILLING ENGINEER CHEVRON NORTH AMERICA EXPLORATION AND PRODUCTION CO. MIDCONTINENT SBU 1400 SMITH STREET HOU140/43120 HOUSTON, TX 77002 DIRECT:(713) 372-2011 MOBILE: (281) 413-9794 EMAIL: RODERICKMILLIGAN@CHEVRON.COM

Summary of Changes to APD Submission

Chevron respectfully request the ability to cement offline on the HH SO 8 P2 (5H,6H,13H,14H,21H,22H). The summary provided below is a brief description of the main operational sequences for drilling run casing, and cement offline the four wells listed above.

• Move rig to first well in the Drill Order.

Drill order for HH SO 8 P2 (5H,6H,13H,14H,21H,22H).)

T						SO 8									r		
	14HD1		<u>13H</u>	13HD 6HC		<u></u>	5HC			22HA			21HA				
S181auxt	Х		n. Di	Х	1787) 1797 - 1		Х	.]/		Х	as f Rife	e di Se Se Se je	Х			X	23)
Intermediate	X		<u>-</u>	х	4		х	43- <u>4</u> 25		Х	*. • • • •		Х	.4. 5	isens in Sector	Х	` `
्र Pilot Hole	X																
Laterals & Dichern	Х			Х		l Naji ki		o na k Ratio ya			n s Jan		Х	:		X	5
CS Diraterais	х	1		Х		1 	х			Х	ەر 11. 14.		1	. jeje		101 (M.)	

Sequencing by hole section.

- Surface Hole:
 - 1. Drill 17-1/2" surface hole with fresh water to planned casing set depth with 10' rat hole.
 - 2. Run casing as stated by approved APD, land out wellhead.
 - 3. Move the rig to next well (~2-3 hours) and cement previous well offline.
 - All sacks and volumes will remain the same.
 - 4. Dress out 13-5/8" 5M SH-2 wellhead and install/secure with temporary abandonment cap, and a pressure gauge will be installed.
 - 5. Skid to next well according to above "Drill Order"

Repeat 1 through 3 until all three surface holes are drilled, cased and cemented offline.

- Intermediate Hole:
 - 1. N/U, using an API approved Quick-Connect, and test 13-5/8" 5M Class IV BOP to 250 psi / 5,000 psi.
 - 2. Test casing to required pressure. Drill out shoe track and 10' of new formation. Perform FIT. Drill 12-1/4" intermediate hole to planned casing set depth with ~10' of rat hole.
 - 3. Run casing as stated by approved APD, land out hanger and cement offline.

Repeat 1 through 3 until all three intermediate holes are drilled, cased and cemented offline.

- Production Hole:
 - 1. Test casing to required pressure. Drill out shoe track and 10' of new formation. Perform FIT. Drill 8-1/2" vertical section, curve, and lateral as stated by approved APD.
 - 2. Run casing as stated by approved APD, land out hanger and cement offline.

- All sacks and volumes will remain the same.
- 3. Install back pressure valve and temporary abandonment cap.

Repeat steps in production hole until all wells are drilled, cased, and cemented offline.

Changes Summary

Summary: Variance to cement offline the Hayhurst pad not requested in original submittal. We will not abandon (move the rig off of the pad) the well without cementing and securing the well.

As Defined in APD:	As Planned on Well:				
Variance to cement offline not requested.	Chevron respectfully request the ability to cement offline on the HH SO 8 P2 (5H,6H,13H,14H,21H,22H).) The summary provided is a brief description of the main operational sequences for drilling, casing and cementing the wells listed above.				