## NM OIL CONSERVATION

Fam 3160-5 (April 20**0**4)


UNITED STATES
DEPARTMENT OF THE INTERIOR 2017

FORM APPROVED OM B He 1004-0137 Express March 31, 2007

CHAIRTY MOTIONA IND BERARRA ANDMERICA	S. Lease Serial Ho. 43524
SUNDRY NOTICES AND REPORTS ON FUELVED  Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals.	6. If Indian, Allottes or Tribe Name
SUBMIT IN TRIPLICATE- Other instructions on reverse side.	7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well Gas Well Other	8. Well Name and Ng
2 Name of Operator Peros River Operating 3a Address 130 Phone No Girclinia men codal	Edmonison Federal 1
3a Address 3b. Phone No. (include area code) 1755 Rosewell, nm. 88202 573-420-5067	
4. Location of Well Figures: Sec To R. J. or Survey Description	10. Ejeld and Pool, or Exploratory Area PLCOS SLOPE Abo
11375,25E	11. County or Parish, State  Chaves, NM
12-CHECK-APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, R	PORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION	
Notice of Intent  Acidiae  Deepen  Production (Star  Alter Casing  Fracture Treat  Reclamation	VResume) Water Shut-Off Well Integrity
Subsequent Report Casing Repair New Construction Recomplete Change Plans Plug and Abandon Temporarity Aba	Other
Final Absordonment Notice Convent to Injection Plug Back Water Disposal	
following completion of the involved operations. If the operation results in a multiple completion or recompletion in testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamate determined that the site is ready for final inspection.)  MIRU P3A UNIT	ion, have been completed, and the operator has
1. Set CIBP@ 38441. Cap W/ 205x woc TAg - 3400' 405x 1000 TOB	
	405x WOC TAG
1071 2400 SPD+ 105x WAC THE 2000'	HOSX WOR TAG
· PUH perf 1500', 40 5 k WOC THY. 2000'	
· PUH perf 1500', 40 5 k WOC THY. 2000'	
1071 2400 SPD+ 105x WAC THE 2000'	WOC.TAG.
PUH perf 1500', 40 5 k WOCTAG. 2000'  1. put perf 1500', 40 5 k WOCTAG. 1200'.  1. put perf 250' circ 405x 4'/2 -85/8 700  14. I hereby certify that the foregoing is true and correct  Name-Printed Contract	WOC.TAG.
PUH perf 1500', 40 5 k WOCTAG. 2000'  1. put perf 1500', 40 5 k WOCTAG. 1200'.  1. put perf 250' circ 405x 4'/2 -85/8 700  14. I hereby certify that the foregoing is true and correct  Name-Printed Contract	WOC.TAG.
PUH perf 1500', 40 5 k WOCTAG 1200'.  1. putl perf 250' circ 405x 4'/2 - 85/8 700  1. putl perf 250' circ 4'/2 - 85/8 500  14. Thereby certify that the foregoing is true and correct  Name (Arthred Chyped)  Signatur New Line William  Signatur New Line William  Dute 08/01/17	woc. TAG. 8054 verify Cm1 cealed confection
PUH perf 1500', 40 5 k WOCTAG, 2000'  PUH perf 1500', 40 5 k WOCTAG, 1200'.  PUH perf 250' Circ 405x 4'/2 -85/8 700  14. I hereby certify that the foregoing is true and correct  Name (Printed Typed)  LESTIC SIMMON  Signal THIS SPACE FOR FEDERAL OR STATE OFFICE US  THIS SPACE FOR FEDERAL OR STATE OFFICE US	WOC. TAG. 805X Verity Cm1 Scealed Colleged 101 18001
PUH perf 1500', 40 5 k WOCTAG, 1200'.  PUH perf 1500', 40 5 k WOCTAG, 1200'.  PUH perf 250' circ 405x 4'/2 -85/8 700  PUH perf 250' circ 4'/2 -85/8 SUSFACE.  14. Thereby certify that the foregoing is true and correct  Name-(Printed Typed)  LEGIC SINUTY  Signatur New Picture  Title P3A Special Control of the Control of t	WOC. TAG. 805X Verity Cm1 Scealed Colleged 101 18001
PUH perf 1500', 40 5 k WOCTAG: 1200'.  1. putl perf 250' circ 405x 4'/2 - 85/8 700  1. putl perf 250' circ 4'/2 - 85/8 8 Usface.  14. I hereby certify that the foregoing is true and correct  Name (Printed Typed)  Lestic Signature Control  This space for Federal or State Office Using State Office Using State Office Using Space For Federal Or State Office Using Spac	WOC. TAG.  8054 Verity Cmy  Ceallet  Ceallet  SE

APPROVED FOR 3 MONTH PERIOD NOV 0 3 2017 ENDING \_

SEE ATTACHED FOR CONDITIONS OF APPROVAL



## BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 627-0272

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90<sup>th</sup> day provide the BLM Roswell Field Office (RFO), prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when the BLM Roswell Field Office can expect the well to be plugged. Failure to do so will result in enforcement action. Unless the well has been properly plugged, the rig shall not be removed from over the hole without prior approval.
- 2. <u>Notification:</u> Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.
- 3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

- 6. <u>Dry Hole Marker:</u> All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10 feet in length, 4 feet above the ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to the BLM Roswell Field Office. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

Following the submittal and approval of the Subsequent Report of Abandonment, a Notice of Intent for Final Abandonment with the proposed surface restoration procedure must be submitted for approval.