Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NM OIL CONSERVATION OR GED-ARTIESIA

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

OCT 2 0 2017

5. Lease Serial No. NMNM074939

SOMPLIM	DITCES AND KELOK 12 ON MEETS
Do not use this:	form for proposals to drill or to re-enter an
abandoned well.	Use form 3160-3 (APD) for such proposals

abandoned we	6. If Indian, Allottee	or Tribe Name				
SUBMIT IN	7. If Unit or CA/Agre	7. If Unit or CA/Agreement, Name and/or No.				
1. Type of Well	8. Well Name and No GISSLER B 36					
Ø Oil Well ☐ Gas Well ☐ Oth 2. Name of Operator	9. API Well No.					
BURNETT OIL CO. INC.	30-015-34022					
3a. Address BURNETT PLAZA - SUITE 15 FORT WORTH, TX 76102	76102 10. Field and Pool or CEDAR LAKE	10. Field and Pool or Exploratory Area CEDAR LAKE GLORIETTA YESO				
4. Location of Well (Footage, Sec., 7	11. County or Parish,	11. County or Parish, State				
Sec 14 T17S R30E Mer NMP	EDDY COUNT	Y, NM				
12. CHECK THE A	PPROPRIATE BOX(ES) TO	INDICATE NATURE O	F NOTICE, REPORT, OR OT	HER DATA		
TYPE OF SUBMISSION	TYPE OF SUBMISSION · TYPE OF ACTION					
Notice of Intent ■ Notice of Intent Notice of Inten	☐ Acidize	□ Deepen	☐ Production (Start/Resume)	□ Water Shut-Off		
_	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	□ Well Integrity		
☐ Subsequent Report	Casing Repair	☐ New Construction	☐ Recomplete	Other		
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon			
	Convert to Injection	Plug Back	☐ Water Disposal			
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a pen in the property of the filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamabilities from the operator has determined that the site is ready for final inspection. APPROVAL BY STATE Below is the water flow shut off procedure that Burnett proposes for this well: 1. MIRU cementing company 2. Pressure up on 9-5/8? x 5-1/2? casing annulus with fresh water; a. If annulus pressures up to 250 psig, hold for 30 minutes and call BLM b. If pressure will not hold, establish injection rate, limiting surface injection pressure to 250 psig. SEE ATTACHED FOR						
3. If EIR established, mix and	pump 100 sx 14.7 ppg, limit	surface pressure to	CONDITIONS OF			
300 psig. NOTE that the calculated hole volume to 50? below the surface casing WITNESS						
14. I hereby certify that the foregoing is Name (Printed/Typed) LESLIE (Electronic Submission #378 For BURNETT Committed to AFMSS for pro-	OIL CO. INC sent to the Ca	arisbad NNEY on A6/13/2017D (\\[C	ED		
Signature (Electronic	Submission)	Date 06/08/20	017			
-	THIS SPACE FOR	FEDERAL OR STATE	OFFICE USE			
Approved By Aud R	1,0/0	2/2017 TOE	T	a ma a m		
certify that the applicant holds legal or eq which would entitle the applicant to cond Title 18 U.S.C. Section 1001 and Title 43	uct operations thereon.	oject lease Office	BUREAU OF LAND MANA CARLSBAD FIELD OF	FICE		

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #378399 that would not fit on the form

32. Additional remarks, continued

shoe calls for 55 sx.

4. Shut down, RDMO cementing company.

Conditions of Approval

Burnett Oil Company, Inc. Gissler B - 36, API 3001534022 T17S-R30E, Sec 14, 1650FNL & 1650FWL October 02, 2017

- 1. Begin wellbore operations within 90 days of these conditions of approval for the processed Electronic Submission #378399 notice of intent or request an extension.
- 2. Operator is required to have the BLM approved NOI procedure with applicable conditions of approval on location for this workover operation.
- 3. Subject to like approval by the New Mexico Oil Conservation Division.
- 4. Before adding, replacing, or repairing casing or a liner, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 5. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 6. Surface disturbance beyond the existing pad shall have prior BLM approval.
- 7. Functional H₂S monitoring equipment shall be on location.
- 8. Blow Out Prevention Equipment 2000 (2M) to be used. All BOPE and workover procedures shall establish fail safe well control. Ram(s) for the work string(s) used is required equipment. Manual BOP closure system including a blind ram and pipe ram(s) designed to close on all (hand wheels or automatic locking devices) equipment installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) employed when needed for reasonable well control requirements.
- 9. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created during work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Portojohns and trash containers will be on-location during fracturing operations or any other crewintensive operations.
- 10. Notify BLM 575-361-2822 Eddy Co. as work begins. Some procedures witnessed. If there is no response, leave a voice mail with the API#, workover purpose, and a call back phone number.
- 11. The BLM PET witness is to run tbg tally and agree to cement volumes and placement.

 Sample each plug for cement curing time and tag and/or pressure test as requested by BLM PET witness.

- 12. Set a plug within 100' of the top perf 4978' and perform a charted casing integrity test of 500psig minimum. Document the pressure test on a one hour full rotation calibrated (within 6 months) recorder chart registering within 35 to 85 per cent of its full range. Verify all annular casing vents plumbed to the surface and open during this pressure test. Call BLM 575-361-2822 Eddy Co., and arrange for a BLM witness of that pressure test. Include a copy of the chart with the subsequent sundry for this workover.
- 13. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from the plug within 100' of the top perf taken with 0psig casing pressure to TOC. Attach the CBL to a <u>pswartz@blm.gov</u> email.
- 14. Run an acoustic log designed to determine the water flow entry depth behind pipe and reevaluate procedure.
- 15. Squeeze cement in the 5 ½ annulus to cover the Top of Salt and 9 5/8" shoe. Perf the 5 1/2" csg at 480' or below, open the 5 ½" x 9 5/8" csg vent, establish an injection rate, and squeeze 55 to 60sx Class "C" neat cmt mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water through a packer circulating cement to surface out the 5 1/2" x 9 5/8" annulus. Close the 5 ½" x 9 5/8" csg vent and WOC.
- 16. Drill out all cement below the 480' perfs and test $5 \frac{1}{2}$ ' csg to 500psig. Test $5 \frac{1}{2}$ ' x 9 5/8'' csg annulus to 200psig.
- 17. Monitor wellhead for continued water flow.
- 18. File **subsequent sundry** Form 3160-**5** within 30 days of workover procedures. Include (dated daily) descriptions of the well work, i.e. procedure descriptions and setting depths of each plug in the subsequent sundry.
- 19. The subsequent report is to include stimulation injection pressures. Report maximum/minimum injection rate (BPM) and max/min stimulation injection pressures.
- 20. Submit a (BLM Form 3160-5 subsequent report describing (dated daily) all wellbore activity and the Mechanical Integrity Test. File intermediate Form 3160-5 within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.
- 21. A BLM Well Recompletion Form 3160-4 and a NMOCD Form C-102 "Well Location and Acreage Dedication Plat" with updated information is necessary with the subsequent package when recompletion changes a well's Pool designation.
- 22. File intermediate **subsequent sundry** Form 3160-**5** within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.

An inactive/shut-in well bore is a non-producing completion that is capable of "beneficial use" i.e. production in **paying quantities** or of service use.

- 23. Submit evidence to support your determination that the well is in active "beneficial use" for BLM approval on the Sundry Notice Form 3160-5 within 90 days of this sundry's approval date.
- 24. Should "beneficial use" not be achieved submit for BLM approval a plan for plug and abandonment.




Diagram last updated: 09/28/2017