State of New Mexico **Energy Minerals and Natural Resources**

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141 DEC **1 8 2017** Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC. Revised April 3, 2017

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED

					anon		orrective A	CHOI	1	
NHB1	1360	56440)			OPERA	ГOR		🛛 Initia	al Report 🔲 Final Report
Name of Co	mpany De	evon Energy	Producti	on Company 💋			on Kidd; Foren			
Address 6488 Seven Rivers Hwy Artesia, NM 88210 Facility Name Parkway West SWD 1						Telephone No. 575-513-1770				
Facility Nar	ne Parkwa	iy west Sw1	<u> </u>		1	Facility Typ	e Salt Water Di	isposal		
Surface Owner State Mineral Owner						tate			API No	.30-015-40835
				LOCA	TION	N OF REI	LEASE			
Unit Letter $D \neq E$	Section 27	Township 19S	Range 29E	Feet from the	North/S	South Line	Feet from the	East/	West Line	County Eddy
	· ·	•	L	atitude_32.635	17 Lo	ongitude - 1	04.06970_NAI	D83		· · · · · · · · · · · · · · · · · · ·
				NAT	URE	OF REL	EASE			
Type of Release Produced water release						Volume of Release 99 BBLS Volume Recovered (
ource of Re	lease suction	on hose				Date and Hour of Occurrence 12.04.2017 @ 1:02 PM MST			Date and Hour of Discovery 12.04.17 @ 1:02 PM MST	
Was Immedia	ate Notice (Yes 🗌] No 🗌 Not Re	equired	If YES, To				
By Whom? Mike Shoemaker; EHS Professional						Date and H OCD: 12.0	lour)4.17 @ 4:58 PM	I MST		
Was a Watercourse Reached?						If YES, Vo N/A	olume Impacting	the Wat	ercourse.	
	ırse was Im	pacted, Descr	ibe Fully.'	*						
N/A Describe Cau The north H- produced wat	use of Probl pump disch ter to drain	em and Reme harge check va out of the tan	dial Actio lve failed c onto the	n Taken.* causing high pres	id. The p	ad overflowe	ed and produced v	water ra	n off the so	ted from the fitting causing uth side of the location. The el pipe.
N/A Describe Cau The north H- produced wat Horizontal pu Describe Are 09 BBLS of p pad and ran i	use of Probl pump disch ter to drain ump was im a Affected produced w n a souther	em and Reme harge check va out of the tanl hmediately shu and Cleanup / vater was relea n direction int	dial Actio Ive failed c onto the at in to pre Action Tal sed. 60 Bl o the ditch	n Taken.* causing high pres concrete pump pa vent any further r ten.* BLS of produced	nd. The p release. T water wa pad. Tot	ad overflowe The suction h s recovered tal approxim	ed and produced v ose was replaced via vacuum truck	water ra with a s . The re	n off the so stainless ste lease origin	uth side of the location. The
V/A Describe Cau The north H- roduced wat Iorizontal pu Describe Are 9 BBLS of p ad and ran i ontractor wi hereby certi egulations al public health hould their co or the environ	tse of Probl pump disch ter to drain ump was im a Affected produced w n a souther ill be contac ify that the ll operators or the envi operations h nment. In a	em and Reme harge check va out of the tanh hmediately shu and Cleanup A vater was relea in direction int cted to assist v information gi are required t ronment. The have failed to a	dial Actio lve failed c onto the at in to pre Action Tal sed. 60 Bl o the ditch with deline iven above o report an acceptance adequately OCD accept	n Taken.* causing high press concrete pump pa vent any further r sen.* BLS of produced about 40 feet off ation and remedia is true and comp nd/or file certain r ce of a C-141 report investigate and r	ad. The p release. T water wa pad. Tot ation effo dete to the release no ort by the remediate	ad overflowe The suction h as recovered tal approxim orts. The best of my otifications a the NMOCD m the contamination	ed and produced voise was replaced via vacuum truck ate size of the aff knowledge and und perform correct barked as "Final Rion that pose a thi	water ra with a s . The re ected ar understa ctive act Report" or reat to g	n off the so stainless ste lease origin ea is about and that purs tions for rel does not rel round wate	uth side of the location. The el pipe. ated from the south side of the
V/A Describe Cau The north H- produced wat forizontal pu Describe Are 19 BBLS of p pad and ran i ontractor wi hereby certi egulations al public health hould their co or the environ	tse of Probl pump disch ter to drain ump was im a Affected produced w n a souther ill be contac ify that the ll operators or the envi operations h nment. In a	em and Remenarge check va out of the tanl amediately shu and Cleanup A vater was relea in direction intercted to assist v information giver are required to ronment. The bave failed to a addition, NMC	dial Actio lve failed c onto the at in to pre Action Tal sed. 60 Bl o the ditch with deline iven above o report an acceptance adequately OCD accept	n Taken.* causing high press concrete pump pa vent any further r sen.* BLS of produced about 40 feet off ation and remedia is true and comp nd/or file certain r ce of a C-141 report investigate and r	ad. The p release. T water wa pad. Tot ation effo dete to the release no ort by the remediate	ad overflowe The suction h as recovered tal approxim orts. The best of my otifications a the NMOCD m the contamination	ed and produced vose was replaced via vacuum truck ate size of the aff knowledge and und perform correct parked as "Final R ion that pose a the ve the operator of	water ra with a s . The re ected ar understa ctive act Report" (reat to g respons	n off the so stainless ste lease origin ea is about and that purs tions for rel does not rel round wate sibility for c	uth side of the location. The el pipe. ated from the south side of the 40' x 10'. An environmental suant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health
N/A Describe Cau The north H- boroduced wat Horizontal pu Describe Are 09 BBLS of p bad and ran i contractor wi hereby certi egulations al bublic health should their co or the environ ederal, state,	tse of Probl pump disch ter to drain ump was im a Affected produced w n a southern ill be contact ify that the ll operators or the envi operations h nment. In a , or local lar	em and Reme harge check va out of the tan hmediately shu and Cleanup / vater was relea in direction int cted to assist v information gi are required t fronment. The have failed to addition, NMC ws and/or regu	dial Actio lve failed c onto the at in to pre Action Tal sed. 60 Bl o the ditch with deline iven above o report an acceptance adequately OCD accept	n Taken.* causing high press concrete pump pa vent any further r sen.* BLS of produced about 40 feet off ation and remedia is true and comp nd/or file certain r ce of a C-141 report investigate and r	id. The p elease. T water wa pad. Too tion effo elete to the elease no ort by the emediate report do	ad overflowe The suction h as recovered tal approxim- orts. The best of my otifications a the NMOCD m the contaminations oes not relieve	ed and produced voise was replaced via vacuum truck ate size of the affect of the affect of the affect of the size of the operator of OIL CON	water ra with a s . The re ected ar understa ctive act Report" reat to g respons	n off the so stainless ste lease origin ea is about ind that purs tions for rel does not rel round wate sibility for c	uth side of the location. The el pipe. ated from the south side of the 40' x 10'. An environmental suant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other
I/A Describe Cau The north H- roduced wat Iorizontal pu Describe Are 9 BBLS of J ad and ran i ontractor wi hereby certi egulations al ublic health hould their of r the environ ederal, state,	use of Probl pump disch ter to drain ump was im a Affected produced w n a southern ill be contact ify that the ll operators or the envi operations h nment. In a , or local la	em and Reme harge check va out of the tanl imediately shu and Cleanup / vater was relea in direction int cted to assist v information gi are required t ronment. The have failed to a addition, NMC ws and/or regu n	dial Actio lve failed c onto the at in to pre Action Tal sed. 60 Bl o the ditch with deline iven above o report an acceptance adequately OCD accept	n Taken.* causing high press concrete pump pa vent any further r sen.* BLS of produced about 40 feet off ation and remedia is true and comp nd/or file certain r ce of a C-141 report investigate and r	id. The p elease. T water wa pad. Too tion effo elete to the elease no ort by the emediate report do	ad overflowe The suction h as recovered tal approxim- orts. The best of my otifications a the NMOCD m the contaminations oes not relieve	ed and produced vose was replaced via vacuum truck ate size of the aff knowledge and und perform correct parked as "Final R ion that pose a the ve the operator of	water ra with a s . The re ected ar understa ctive act Report" reat to g respons	n off the so stainless ste lease origin ea is about ind that purs tions for rel does not rel round wate sibility for c	uth side of the location. The el pipe. ated from the south side of the 40' x 10'. An environmental suant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other
V/A Describe Cau The north H- produced wal forizontal pu Describe Are 19 BBLS of p ad and ran in ontractor wi hereby certi- egulations al public health hould their co- ederal, state, Signature: <i>Ta</i> Printed Name	tise of Probl pump disch ter to drain ump was im a Affected produced w n a southern ill be contact ify that the ll operators or the envi operations h nment. In a , or local la	em and Reme harge check va out of the tanl imediately shu and Cleanup / vater was relea n direction int cted to assist v information gt are required t ronment. The have failed to a addition, NMC ws and/or regu <i>n</i> Robison	dial Actio lve failed c onto the at in to pre Action Tal sed. 60 Bl o the ditch with deline iven above o report an acceptance adequately OCD accept	n Taken.* causing high press concrete pump pa vent any further r sen.* BLS of produced about 40 feet off ation and remedia is true and comp nd/or file certain r ce of a C-141 report investigate and r	ad. The p elease. T water wa pad. Too ation effo blete to th elease no ort by the emediate report do	ad overflowe The suction h as recovered tal approxim- orts. The best of my otifications a the NMOCD m the contaminations oes not relieve	ed and produced voise was replaced via vacuum truck ate size of the affective size of the operator of <u>OIL CON</u> Environmental S	water ra with a s . The re ected ar understa ctive act Report" (respons Specialis	n off the so stainless ste lease origin ea is about and that pur- tions for rel does not rel round wate sibility for c ATION st: CM	uth side of the location. The el pipe. ated from the south side of the 40' x 10'. An environmental suant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other
N/A Describe Cau The north H- produced wat Horizontal pu Describe Are 99 BBLS of J pad and ran in contractor wi I hereby certi regulations al public health should their of or the envirous federal, state, Signature: <i>Ta</i> Printed Name	use of Probl pump disch ter to drain ump was im a Affected produced w n a southern ill be contact ify that the ll operators or the envi operations h nment. In a or local la	em and Reme harge check va out of the tanl imediately shu and Cleanup / vater was relea n direction int cted to assist v information gt are required t ronment. The have failed to a addition, NMC ws and/or regu <i>n</i> Robison	dial Actio lve failed c onto the at in to pre- Action Tal sed. 60 Bl o the ditch vith deline iven above o report an adequately DCD accept alations.	n Taken.* causing high press concrete pump pa vent any further r sen.* BLS of produced about 40 feet off ation and remedia is true and comp nd/or file certain r ce of a C-141 report investigate and r	ad. The p elease. T water wa pad. Too tion effore lete to the elease no ort by the emediate report do	ad overflowd The suction h is recovered tal approxim orts. The best of my otifications a te NMOCD m te contaminations to contaminations to contaminations Approved by Approval Da Conditions o	ed and produced vose was replaced via vacuum truck ate size of the affective in the size of the affective in that pose a the verthe operator of <u>OIL CON</u> Environmental S te: 12 24 1	water ra with a s . The re ected ar understa ctive act Report" (respons Specialis	n off the so stainless ste lease origin ea is about and that pur- tions for rel does not rel round wate sibility for c ATION st: CM	uth side of the location. The el pipe. ated from the south side of the 40' x 10'. An environmental suant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other DIVISION

Operator/Responsible Party,

The OCD has received the form C-141 you provided on **12/18/17** regarding an unauthorized release. The information contained on that form has been entered into our incident database and remediation case number $\underline{AP.4520}$ has been assigned. Please refer to this case number in all future correspondence.

It is the Division's obligation under both the Oil & Gas Act and Water Quality Act to provide for the protection of public health and the environment. Our regulations (19.15.29.11 NMAC) state the following,

The responsible person shall complete <u>division-approved corrective action</u> for releases that endanger public health or the environment. The responsible person shall address releases in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with 19.15.30 NMAC. [emphasis added]

Release characterization is the first phase of corrective action unless the release is ongoing or is of limited volume and all impacts can be immediately addressed. Proper and cost-effective remediation typically cannot occur without adequate characterization of the impacts of any release. Furthermore, the Division has the ability to impose reasonable conditions upon the efforts it oversees. As such, the Division is requiring a workplan for the characterization of impacts associated with this release be submitted to the OCD District II office in Artesia on or before 1/18/18. If and when the release characterization workplan is approved, there will be an associated deadline for submittal of the resultant investigation report. Modest extensions of time to these deadlines may be granted, but only with acceptable justification.

The goals of a characterization effort are: 1) determination of the lateral and vertical extents along with the magnitude of soil contamination. 2) determine if groundwater or surface waters have been impacted. 3) If groundwater or surface waters have been impacted, what are the extents and magnitude of that impact. 4) The characterization of any other adverse impacts that may have occurred (examples: impacts on vegetation, impacts on wildlife, air quality, loss of use of property, etc.). To meet these goals as quickly as possible, the following items must, at a minimum, be addressed in the release characterization workplan and subsequent reporting:

• Horizontal delineation of soil impacts in each of the four cardinal compass directions. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. This is not an exclusive list of potential contaminants. Analyzed parameters should be modified based on the nature of the released substance(s). Soil sampling must be both within the impacted area and beyond.

• Vertical delineation of soil impacts. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. As above, this is not an exclusive list of potential contaminants and can be modified. Vertical characterization samples should be taken at depth intervals no greater than five feet apart. Lithologic description of encountered soils must also be provided. At least ten vertical feet of soils with contaminant concentrations at or below these values must be demonstrated as existing above the water table.

• Nominal detection limits for field and laboratory analyses must be provided.

• Composite sampling is not generally allowed.

• Field screening and assessment techniques are acceptable (headspace, titration, EC [include algorithm for validation purposes], EM, etc.), but the sampling and assay procedures must be clearly defined. Copies of field notes are highly desirable. A statistically significant set of split samples must be submitted for confirmatory laboratory analysis, including the laterally farthest and vertically deepest sets of soil samples. Make sure there are at least two soil samples submitted

for laboratory analysis from each borehole or test pit (highest observed contamination and deepest depth investigated). Copies of the actual laboratory results must be provided including chain of custody documentation.

•Probable depth to shallowest protectable groundwater and lateral distance to nearest surface water. If there is an estimate of groundwater depth, the information used to arrive at that estimate must be provided. If there is a reasonable assumption that the depth to protectable water is 50 feet or less, the responsible party should anticipate the need for at least one groundwater monitoring well to be installed in the area of likely maximum contamination.

• If groundwater contamination is encountered, an additional investigation workplan may be required to determine the extents of that contamination. Groundwater and/or surface water samples, if any, must be analyzed by a competent laboratory for volatile organic hydrocarbons (typically Method 8260 full list), total dissolved solids, pH, major anions and cations including chloride and sulfate, dissolved iron, and dissolved manganese. The investigation workplan must provide the groundwater sampling method(s) and sample handling protocols. To the fullest extent possible, aqueous analyses must be undertaken using nominal method detection limits. As with the soil analyses, copies of the actual laboratory results must be provided including chain of custody documentation.

• Accurately scaled and well-drafted site maps must be provided providing the location of borings, test pits, monitoring wells, potentially impacted areas, and significant surface features including roads and site infrastructure that might limit either the release characterization or remedial efforts. Field sketches may be included in subsequent reporting, but should not be considered stand-alone documentation of the site's layout. Digital photographic documentation of the location and fieldwork is recommended, especially if unusual circumstances are encountered.

Nothing herein should be interpreted to preclude emergency response actions or to imply immediate remediation by removal cannot proceed as warranted. Nonetheless, characterization of impacts and confirmation of the effectiveness of remedial efforts must still be provided to the OCD before any release incident will be closed.

Jim Griswold OCD Environmental Bureau Chief 1220 South St. Francis Drive Santa Fe, New Mexico 87505 505-476-3465 jim.griswold@state.nm.us