Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2			OM Expire	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM58024 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or N NMNM72611	
			NMNM5802		
1. Type of Well			8. Well Name and MARCH AMT	No. FEDERAL COM 1	
2. Name of Operator EOG Y RESOURCES, INC.	or Contact: TINA HUERTA DURCES, INC. E-Mail: tina_huerta@eogresources.com			6	
3a. Address 104 SOUTH FOURTH STREE ARTESIA, NM 88210	STREET 3b. Phone No. (include area cod Ph: 575-748-4168		10. Field and Pool or Exploratory Area WILDGAT; WOLFCAMP GAS Dagger Draw		
4. Location of Well (Footage, Sec., T.		11. County or Part			
Sec 25 T19S R24E SESW 660		EDDY COU			
12. CHECK THE AP	PROPRIATE BOX(ES) TO	O INDICATE NATURE C	DF NOTICE, REPORT, OR C	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
🛛 Notice of Intent	 Acidize Alter Casing 	 Deepen Hydraulic Fracturing 	Production (Start/Resume)	Water Shut-(
Subsequent Report	Casing Repair	□ New Construction	☐ Recomplete	C Other	
Final Abandonment Notice	 Change Plans Convert to Injection 	Plug and Abandon Plug Back	Temporarily Abandon Water Disposal		
Attach the Bond under which the worl following completion of the involved testing has been completed. Final Abid determined that the site is ready for fin EOG Y Resources, Inc. plans to 1. MIRU all safety equipment is hole as necessary with fresh w 2. Set a CIBP at 7630 ft and c Canyon perforations. WOC and 3. Perforate Wolfcamp 6182 ft	operations. If the operation result andonment Notices must be filed al inspection. o plug back and recomplete as needed. WSU. ND Wellt ater. ap it with 25 sx Class H cer d test the casing to 2000 ps	is in a multiple completion or rec only after all requirements, include e this well as follows: nead NU BOP. POOH with ment. This will place a plug si.	ompletion in a new interval, a Form ding reclamation, have been complet Accepted for in the packer. Load the over the	t be filed within 30 days 3160-4 must be filed ond ed and the operator has 	
degree. 4. Swab test and evaluate ser 5. Acidize with 5000g 15 perce	d samples to lab for analys ant NEFE acid. Flush to the	is. bottom perf with treated w	ARTF vater. Shut JA	ISIA DISTRICT	
well in for one hour to allow the lab for analysis	e acid to spend. Swab, flow	test and evaluate and sen	d samples to	ECEIVED	
14. I hereby certify that the foregoing is	true and correct.				
	Electronic Submission #399	9720 verified by the BLM We SOURCES, NC., sent to the	ll Information System Carlsbad		
Name (Printed/Typed) TINA HUE	RTA	Title REGUL	ATORY SPECIALIST		
Signature (Electronic S	ubmission)	Date 01/05/2	2018		
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE USE		
Approved By				Date	
Conditions of approval, if any, are attached certify that the applicant holds legal or equ	table title to those rights in the su	bject lease			
which would entitle the applicant to condu	et operations thereon.	Office			

Additional data for EC transaction #399720 that would not fit on the form

32. Additional remarks, continued

6. Perforate Wolfcamp 6150 ft - 6158 ft (9) with deep penetrating charges using 1 jspf with 90 degree phasing.
7. Swab test and evaluate send samples to lab for analysis.
8. Straddle perfs and acidize with 1500g 15 percent NEFE acid. Flush to the bottom perf with

treated water. Shut well in for one hour to allow the acid to spend. Swab, flow test and evaluate 9. Perforate Wolfcamp 6122 ft - 6130 ft (9) with deep penetrating charges using 1 jspf with 90

degree phasing.

 Swab test and evaluate send samples to lab for analysis.
 Straddle perfs and acidize with 1500g 15 percent NEFE acid. Flush to the bottom perf with treated water. Shut well in for one hour to allow the acid to spend. Swab, flow test and evaluate

and send samples to lab for analysis 12. Perforate Wolfcamp 6038 ft - 6064 ft (27) with deep penetrating charges using 1 jspf with 90 degree phasing.

 Swab test and evaluate send samples to lab for analysis.
 Straddle perfs and acidize with 3000g 15 percent NEFE acid. Flush to the bottom perf with treated water. Shut well in for one hour to allow the acid to spend. Swab, flow test and evaluate and send samples to lab for analysis

15. TIH with packer and set it at +/- 5,938?. ND BOP NU WH and swab the well in and turn over to production.

Wellbore schematics attached



