



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT


GARY E. JOHNSON
Governor
Betty Rivera
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

*Buckskin OFF
OF Curry Comb*

OK to release

DOMINION OKLAHOMA TEXAS EXPL. & PROD. INC
14000 Quil SPRINGS PKWY
STE 600
OKLAHOMA CITY, OK 73134-2600



Form C-103 Report of Plugging for your State A Well # 1, F-24-19-28.API 30-015-02300

Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- 1. All pits have been filled and leveled.
- 2. Rat hole and cellar have been filled and leveled.
- 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- 5. The dead men and tie downs have been cut and removed.
- 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

[Signature]
Name

Van Barton
Field Rep. II

[Signature]
Title

Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1940, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

DISTRICT II P.O. Drawer DD, Artesia, NM 88210


Santa Fe, New Mexico 87504-2088

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-015-02300

5. Indicate Type of Lease STATE [X] FEE []

6. State Oil & Gas Lease No.



7. Lease Name or Unit Agreement Name

State A

8. Well No. 1

9. Pool name or Wildcat Yates SE QN SA-East

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL [X] GAS WELL [] OTHER []

2. Name of Operator Louis Dreyfus Natural Gas Corp.

3. Address of Operator 14000 Quail Springs Parkway, Suite 600, Oklahoma City,

4. Well Location Unit Letter F : 1980' Feet From The North OK 73134 Line and 1980' Feet From The West Line Section 24 Township 19S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data. NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK [] PLUG AND ABANDON [] TEMPORARILY ABANDON [] CHANGE PLANS [] PULL OR ALTER CASING [] OTHER: [] SUBSEQUENT REPORT OF: REMEDIAL WORK [] ALTERING CASING [] COMMENCE DRILLING OPNS. [] PLUG AND ABANDONMENT [X] CASING TEST AND CEMENT JOB [] OTHER: []

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 11-04-02 Set 4-1/2" CIBP @ 2075', cap w/ 35' cmt. 11-05-02 Perf 4 holes @ 840', set pkr. @ 500', sqz 35 sx cmt. & tag plug @ 730'. 11-05-02 Perf 4 holes @ 348', set pkr. @ 90', sqz 35 sx cmt. 11-06-02 Tag plug @ 213'. 11-06-02 Perf 4 holes @ 60'. 11-06-02 Pump 25 sx cmt. down 4-1/2" csg. to surface out of annulus. Leave 4-1/2" csg. full of cmt. 11-06-02 Cut off wellhead, install dry hole marker. Clean location. RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE [Signature] TITLE Agent DATE 11-12-02 TYPE OR PRINT NAME Roger Massey TELEPHONE NO. 915-530-0907

(This space for State Use) APPROVED [Signature] DATE JUL 3 2003 APPROVED BY [Signature] TITLE DATE CONDITIONS OF APPROVAL, IF ANY: