	Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
	Office District I – (575) 393-6161	Energy, Minerals and Natural Resource	ces Revised July 18, 2013
	1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
	District II - (575) 748-1283	OIL CONSERVATION DIVISIO	N 30-015-30941
	811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
	1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE
	<u>District IV</u> – (505) 476-3460	Sama re, INIVI 6/303	6. State Oil & Gas Lease No.
	1220 S. St. Francis Dr., Santa Fe, NM 87505		E-742
		TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	Committee of the commit	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	
	PROPOSALS.)	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	8. Well Number 9
	1. Type of Well: Oil Well	Gas Well Other	
	2. Name of Operator	Out Well State	9. OGRID Number
	COG Operating, LLC		229137
	3. Address of Operator		10. Pool name or Wildcat
	600 W. Illinois Ave, Midland, T	X 79701	Empire; Glorieta-Yeso, East 96610
	4. Well Location		
	Unit Letter D	: 890 feet from the N line at	nd480feet from theWline
	Section 20	Township 17S Range 29I	
		11. Elevation (Show whether DR, RKB, RT, C	JK, etc.)
	AND THE RESIDENCE OF THE PROPERTY OF THE PROPE	202 34 37	and the state of t
	10. 01. 1. 4		
	12. Check	Appropriate Box to Indicate Nature of N	lotice, Report or Other Data
	NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
	PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐		
	TEMPORARILY ABANDON PULL OR ALTER CASING		ICE DRILLING OPNS. P AND A CEMENT JOB
			CEMENT JOB
	CLOSED-LOOP SYSTEM OTHER:	□ OTHER:	П
			tails, and give pertinent dates, including estimated date
	of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
	proposed completion or re		
	-		open
- 4	Not fr Nmoco 24hrs before 15 FR4 4390 Ports 4440-520. 1. Set 5 1/2" CIBP @ 3835. Circulate hole w/ MLF. Pressure test csg. Spot 35 sx cmt @ 3835-3546. WOC & Tag (DV Tool).		
4" 1. Set 5 1/2" CIBP @ 3835". Circulate hole w/ MLF. Pressure test csg. Spot 35 sx cmt @ 3835-3546. WOC			nt @ 3835-354 6. WOC & Tag (DV Too l).
	2. Spot 25 sx cmt @ 1722-1522'. (Queen) 1390' CTBP@ 3835 253k, C.t. woc-74) 3. Perf & Sqz 50 sx cmt @ 865-700'. WOC & Tag (8 5/8" Shoe , Yates, B/Salt)		
			NM OIL CONSERVATION
5. Cut off well head, verify cmt to surface, weld on Dry Hole Maker.		surface, weld on Dry Hole Maker.	ARTESIA DISTRICT
			APR 09 2006
			VIII A D 5000
			See the second of the Post
			RECEIVED
	Spud Date:	Rig Release Date:	
		1 0 - 1	
_	* See Attachel	(COA) Must	- he Placed by 4-10-19
1	Thereby certify that the information	n above is true and complete to the best of my kn	
	10 0 MA	1	11111111
	SIGNATURE CHIQUE	onlarnery) TITLE Agent	DATE 4/6/18
		abbymabcmand	
	Type or print name Abiaco Y	Nontagnery E-mail address:	PHONE: 432-580-7161
	For State Use Only	\(\text{\text{X}} \)	
	- 1-	- A	11 :0
	APPROVED BY:	TITLE STATE MY	DATE 4-10-18
	Conditions of Approval (if any):		