

SUNDRY Do not use thi	PARTMENT OF THE IN UREAU OF LAND MANAG	JEMENI		MOC		0. 1004-0137 nuary 31, 2018	
Do not use this abandoned we	NOTICES AND REPOR	RTS ON WELLSMA	Y. 07	Artesia	NMNM20965		
abandoned we	NOTICES AND REPOR is form for proposals to II. Use form 3160-3 (APL TRIPLICATE - Other inst	) for such proposal	5.	2018	6. If Indian, Allottee or		
SUBMIT IN	TRIPLICATE - Other inst	ructions on page 2	THIES	A O.C.D.	7. If Unit or CA/Agree	ment, Name and/or	
. Type of Well		8. Well Name and No. RDX FEDERAL 17 019					
. Name of Operator RKI EXPLORATION & PROD	Contact: UCTIONE-Mail: caitlin.ohair	CAITLIN O'HAIR @wpxenergy.com			9. API Well No. 30-015-41249		
a. Address 3500 ONE WILLIAMS CENTE TULSA, OK 74172		10. Field and Pool or Exploratory Area BRUSHY DRAW; DELAWARE,					
Location of Well (Footage, Sec., 7	., R., M., or Survey Description,	)	1		11. County or Parish, State		
Sec 17 T26S R30E SWSW 66 32.037029 N Lat, 103.909217	30FSL 880FWL 'W Lon				EDDY COUNTY	, NM	
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE NAT	URE O	F NOTICE,	REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION		]	YPE OF	FACTION			
	□ Acidize	Deepen		Producti	on (Start/Resume)	U Water Shut-	
Notice of Intent	Alter Casing	Hydraulic Fra	cturing	Reclama	tion	U Well Integr	
□ Subsequent Report	Casing Repair	New Constru	ction	Recomp	Recomplete D Other		
Final Abandonment Notice	Change Plans	Plug and Aba	ndon		arily Abandon		
	Convert to Injection				r Disposal y proposed work and approximate duration the		
Abandonment Status for 5 ye The well is currently down du pump conversion workover in producing in paying quantities	e to a grounded ESP. The the current price environ	production (7bopd) d	oes not all should	justify a rod d be capable	arily e of Accepted for r	Sca.	
Attached is a current and pro		procedure to MIT.	SEI	E ATTA	CHED FOR	ROVAL	
all has been	, Shutin W	Interno			1	26	
14. I hereby certify that the foregoing i	is true and correct		/			( ) /	
	For RKI EXPLOR Committed to AFMSS for	412420 verified by the ATION & PRODUCTION processing by JENNIF Title	ER SAN	CHEZ on 04/2	d 23/2018 ()		
Name (Printed/Tuned) CAITLIN	UTAIN				DOVER	XII	
Name (Printed/Typed) CAITLIN			04/19/2	2018	AUVEN_		
	Submission)	Date		OFFICE U	SE / /		
		Date		1/		1h	
Signature (Electronic	THIS SPACE FO			APF		Date	
Signature (Electronic Approved By onditions of approval, if any, are attach rrtify that the applicant holds legal or en hich would entitle the applicant to conc	THIS SPACE For the additional of this notice does quitable title to those rights in the duct operations thereon.	S not warrant or e subject lease Office	STATE	BUREXU OF	LAND MANAGEMEN		
Signature (Electronic Approved By onditions of approval, if any, are attach	THIS SPACE For the additional of this notice does quitable title to those rights in the duct operations thereon.	S not warrant or e subject lease Office	STATE	APF BUREAU OF CAPLSB	LAND MANAGEMEN		
Signature (Electronic Approved By onditions of approval, if any, are attach ertify that the applicant holds legal or ea hich would entitle the applicant to cond itle 18 U.S.C. Section 1001 and Title 4. States any false, fictitious or fraudulen	THIS SPACE For the additional of this notice does quitable title to those rights in the duct operations thereon.	S not warrant or e subject lease office a crime for any person know s to any matter within its ju	<b>STATE</b> kingly and	APF BUREAU OF CAPISE	2018 LAND MANAGEMEN AD EIEID OFFICE ake to any department or	agency of the Unit	
Signature (Electronic Approved By onditions of approval, if any, are attach ertify that the applicant holds legal or ea hich would entitle the applicant to cond itle 18 U.S.C. Section 1001 and Title 4. States any false, fictitious or fraudulen	THIS SPACE FO ed. Approval of this notice doe quitable title to those rights in th duct operations thereon. 3 U.S.C. Section 1212, make it a t statements or representations a	S not warrant or e subject lease office a crime for any person know s to any matter within its ju	<b>STATE</b> kingly and	APF BUREAU OF CAPISE	2018 LAND MANAGEMEN AD EIEID OFFICE ake to any department or	agency	







# MIT Workover Procedure

Well: RDX 17-19 Location: Eddy, NM Date: April 19, 2018 Objective: Mechanical Integrity Test

## EH&S Notes:

- ✓ Personnel Safety is the number one job, no exceptions.
- ✓ Please follow appropriate WPX Energy contractor protocols for this job plan. (Please see your WPX Energy Business Representative if you have any questions; Contractor protocols can be found in the WPX Energy Contractor Guide.)
- ✓ Continuous personal H2S monitoring is required. Any H2S alarms or other indications above 10ppm will require work to stop and the situation to be evaluated
- ✓ A Safety meeting shall be held each morning before work and subsequent "tailgate" safety meetings are to be held during the day when operation objectives shift in nature and intent. Please ensure these are documented per the WPX Contractor Guide.

## Prior to Job:

- Schedule Workover Rig
- Test anchors if not done so recently
- Verify location is ok for rig operations
- Ensure all flowlines on surface are clear and lease operator has installed proper tags

Current Wellbore Status: Vertical Completion in Delaware.

## Procedure:

- Spot equipment; MIRU
- Blow down casing. If necessary pump water down casing to kill well.
- TOOH with tbg and ESP.

212	- 2 7/8 L-80 Jts						
	2 7/8 Seat Nipple						
1-	2 7/8 L-80 Jt						
1-	2 7/8 Drain Valve						
1-	2 7/8 L-80 Jt						
1-	DY330 ESP, Accelerate	i w/	Shroud				
1-	2 7/8 Cavins DeSander	Int-	6,945				
4-	2 7/8 Mud Jts	EOF	P- 7,005				
1-	2 7/8 Bull Plug	BP-	7,113				

1



- RU Wireline and run gauge ring down to 50' above top perf.
- RIH with RBP and set no more than 100' above top perf.
- Set 6 sacks of sand on top of plug.
- Load hole with clean water.
- Open Casing valves and note any flow before pressure testing.
- Close casing and apply 500 psi at surface and hold for 30 minutes.
  - Make sure to chart the pressure test with a recorder that has a maximum two hour clock and maximum 1000 pound spring.
  - Insure the unit has been calibrated within the last six months.
  - Please Ensure to have both the Consultant on location and Rig Tool Pusher sign the chart.
  - Note any flow during test
- If the well drops below 450 psi (10%) within the 30 minutes then it is considered to have failed the test.
  - In the event of a failed test please notify WPX Engineer so the NMOCD can be notified and proper actions taken.
- If the well does not drop below 450 psi (10%) within the 30 minutes then it is considered a successful test. The signed chart can be turned into the WPX field office.
- Open Casing valves back up and note for flow.
- Top hole off with water and leave set.
- RDMO

2

#### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

# Approved for a period of 12 months ending 04/23/2019 subject to conditions of approval.

# Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with wellbore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

# **RDX Federal 17 19**

- 1. Well is approved to be TA/SI for a period of 12 months or until 04/23/2019
- 2. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 04/23/2019
- 3. COA's met at this time.