

Form 3160-5	UNITED STAT	'ES OCD Artesia		FORM APPROVED	
	DEPARTMENT OF THE BUREAU OF LAND MAN	EINTERIOR	5. Lease Serial No.	OMB No. 1004-0137 Expires: July 31, 2010	
	Y NOTICES AND REP		NMNM99040 6. If Indian, Allotte	o or Tribo Nomo	
Do not use th	nis form for proposals	to drill or to re-enter an APD) for such proposals.	0. 11 Indian, Anota	e of 1110e ivailie	
	BMIT IN TRIPLICATE - Othe	er instructions on page 2.	7. If Unit of CA/A	greement, Name and/or No.	
1. Type of Well Image: Oil Well Image: Oil Well Image: Other			8. Well Name and RANGER 17 FE	8. Well Name and No. RANGER 17 FEDERAL 1	
2. Name of Operator DEVON ENERGY PRODUCTION COMPANY, LP			9. API Well No. 30-015-30119		
3a. Address 333 West Sheridan Avenue, Oklahoma City, OK 73102-5015		3b. Phone No. <i>(include area code)</i> 405-552-4615		or Exploratory Area DNE SPRING, NW (O)	
4. Location of Well <i>(Footage, Sea</i> 780' FSL 660' FWL Sec 17 T19S R31E	., T.,R.,M., or Survey Descriptio		11. Country or Par EDDY, NM	ish, State	
12. (CHECK THE APPROPRIATE B	BOX(ES) TO INDICATE NATURE O	DF NOTICE, REPORT OR O	THER DATA	
TYPE OF SUBMISSION		TYPE	OF ACTION		
✓ Notice of Intent	Acidize	Deepen Fracture Treat	 Production (Start/Resume Reclamation) Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
Final Abandonment Notice	Change Plans	Plug and Abandon Plug Back	Temporarily Abandon Water Disposal		
Attach the Bond under which following completion of the i testing has been completed. I determined that the site is rea 1. MIRU P&A unit. POOH w/rc	the work will be performed or p nvolved operations. If the opera Final Abandonment Notices must dy for final inspection.) ad pump assembly and 2-7/8"	provide the Bond No. on file with BLM tion results in a multiple completion of t be filed only after all requirements, i production tubing from 8,953'.	M/BIA. Required subsequent or recompletion in a new inte	hs of all pertinent markers and zones. reports must be filed within 30 days rval, a Form 3160-4 must be filed once	
Attach the Bond under which following completion of the i testing has been completed. I determined that the site is rea 1. MIRU P&A unit. POOH w/rd 2. Spot 30 sx (240') CI H from 6 3. Set CIBP @ 8,800'. Tag. Cir 4. Spot 25 sx (200') CI H @ 8,8 5. Spot 25 sx (250') CI C @ 6,5	the work will be performed or p nvolved operations. If the operat- final Abandonment Notices must dy for final inspection.) ad pump assembly and 2-7/8" existing PBD of 10,145' to 9,90 culate 10# salt gel mud. (Bor 600' - 8,600'. 570' - 6,320'. (T.Bone Spring 6	provide the Bond No. on file with BLN tion results in a multiple completion of the filed only after all requirements, in production tubing from 8,953'. 05'. (T.Wolfcamp 10038') he Spring open perfs 8848' - 8888' 6512')	M/BIA. Required subsequent or recompletion in a new inte including reclamation, have b) SEE A	hs of all pertinent markers and zones. reports must be filed within 30 days rval, a Form 3160-4 must be filed once been completed and the operator has	
Attach the Bond under which following completion of the i testing has been completed. I determined that the site is rea 1. MIRU P&A unit. POOH w/rc 2. Spot 30 sx (240') CI H from 6 3. Set CIBP @ 8,800'. Tag. Cir 4. Spot 25 sx (200') CI H @ 8,8 5. Spot 25 sx (250') CI C @ 6,5 6. Spot 25 sx (250') CI C @ 4,9 7. Spot 25 sx (250') CI C @ 3,5 8. Spot 30 sx (300') CI C @ 2,3 9. Perf 5-1/2" csg @ 1,980'. Put	the work will be performed or p nvolved operations. If the opera Final Abandonment Notices must dy for final inspection.) ad pump assembly and 2-7/8" existing PBD of 10,145' to 9,90 culate 10# salt gel mud. (Bor 600' - 8,600'. 670' - 6,320'. (T.Bone Spring 0 (25' - 4,675'. (T.Delaware 487 670' - 3,320'. Tag. (9-5/8 shoe 000' - 2,000'. (T.Yates 2248') mp 60 sx (200') CI C in/out @	provide the Bond No. on file with BLM tition results in a multiple completion of the filed only after all requirements, in production tubing from 8,953'. (05'. (T.Wolfcamp 10038') the Spring open perfs 8848' - 8888' (6512') (4') te 3520') (2,1,980' - 1,780'. Tag. (B.Salt 1964)	M/BIA. Required subsequent or recompletion in a new inte including reclamation, have b) SEE A COND	hs of all pertinent markers and zones. reports must be filed within 30 days rval, a Form 3160-4 must be filed once been completed and the operator has	
Attach the Bond under which following completion of the i testing has been completed. I determined that the site is rea 1. MIRU P&A unit. POOH w/rc 2. Spot 30 sx (240') CI H from 6 3. Set CIBP @ 8,800'. Tag. Cir 4. Spot 25 sx (200') CI H @ 8,8 5. Spot 25 sx (250') CI C @ 6,5 6. Spot 25 sx (250') CI C @ 4,9 7. Spot 25 sx (250') CI C @ 3,5 8. Spot 30 sx (300') CI C @ 2,3 9. Perf 5-1/2" csg @ 1,980'. Put	the work will be performed or p nvolved operations. If the opera Final Abandonment Notices must dy for final inspection.) ad pump assembly and 2-7/8" existing PBD of 10,145' to 9,90 culate 10# salt gel mud. (Bor 100' - 8,600'. (70' - 6,320'. (T.Bone Spring 0 125' - 4,675'. (T.Delaware 487 570' - 3,320'. Tag. (9-5/8 shoe 500' - 2,000'. (T.Yates 2248') mp 60 sx (200') CI C in/out @ mp 60 sx (200') CI C in/out @ mp 45 sx CI C in/out to surface	provide the Bond No. on file with BLN tition results in a multiple completion of the filed only after all requirements, in production tubing from 8,953'. 05'. (T.Wolfcamp 10038') the Spring open perfs 8848' - 8888' 6512') (4') the Saturdian open perfs 8848' - 8888' (5512') (4') (5512') (4') (5512') (4') (5512') (4') (5512') (5512') (5512') (4') (5512') (M/BIA. Required subsequent or recompletion in a new inte including reclamation, have b) SEE A COND	hs of all pertinent markers and zones. reports must be filed within 30 days rval, a Form 3160-4 must be filed once been completed and the operator has TTACHED FOR ITIONS OF APPROVA RECEIVED	
Attach the Bond under which following completion of the i testing has been completed. I determined that the site is rea 1. MIRU P&A unit. POOH w/rc 2. Spot 30 sx (240') CI H from 6 3. Set CIBP @ 8,800'. Tag. Cir 4. Spot 25 sx (200') CI H @ 8,8 5. Spot 25 sx (250') CI C @ 6,5 6. Spot 25 sx (250') CI C @ 4,9 7. Spot 25 sx (250') CI C @ 3,5 3. Spot 30 sx (300') CI C @ 2,3 9. Perf 5-1/2" csg @ 1,980'. Pu 10. Perf 5-1/2" csg @ 140'. Pun 11. Perf 5-1/2" csg @ 140'. Pun	the work will be performed or p nvolved operations. If the opera Final Abandonment Notices must dy for final inspection.) ad pump assembly and 2-7/8" existing PBD of 10,145' to 9,90 culate 10# salt gel mud. (Bor 100' - 8,600'. (70' - 6,320'. (T.Bone Spring 0 125' - 4,675'. (T.Delaware 487 570' - 3,320'. Tag. (9-5/8 shoe 500' - 2,000'. (T.Yates 2248') mp 60 sx (200') CI C in/out @ mp 60 sx (200') CI C in/out @ mp 45 sx CI C in/out to surface	provide the Bond No. on file with BLN tition results in a multiple completion of the filed only after all requirements, in production tubing from 8,953'. 05'. (T.Wolfcamp 10038') the Spring open perfs 8848' - 8888' 6512') (4') the Saturdian open perfs 8848' - 8888' (5512') (4') (5512') (4') (5512') (4') (5512') (4') (5512') (5512') (5512') (4') (5512') (M/BIA. Required subsequent or recompletion in a new inte including reclamation, have to SEE A COND	hs of all pertinent markers and zones. reports must be filed within 30 days rval, a Form 3160-4 must be filed once been completed and the operator has TTACHED FOR ITIONS OF APPROVA RECEIVED MAY 1 6 2018	
Attach the Bond under which following completion of the i testing has been completed. I determined that the site is rea 1. MIRU P&A unit. POOH w/rc 2. Spot 30 sx (240') CI H from 6 3. Set CIBP @ 8,800'. Tag. Cir 4. Spot 25 sx (200') CI H @ 8,8 5. Spot 25 sx (250') CI C @ 6,5 6. Spot 25 sx (250') CI C @ 4,9 7. Spot 25 sx (250') CI C @ 3,5 3. Spot 30 sx (300') CI C @ 2,3 9. Perf 5-1/2" csg @ 1,980'. Pu 10. Perf 5-1/2" csg @ 140'. Pun 11. Perf 5-1/2" csg @ 140'. Pun	the work will be performed or p nvolved operations. If the opera Final Abandonment Notices must dy for final inspection.) ad pump assembly and 2-7/8" existing PBD of 10,145' to 9,90 culate 10# salt gel mud. (Bor 100' - 8,600'. (70' - 6,320'. (T.Bone Spring 0 125' - 4,675'. (T.Delaware 487 570' - 3,320'. Tag. (9-5/8 shoe 500' - 2,000'. (T.Yates 2248') mp 60 sx (200') CI C in/out @ mp 60 sx (200') CI C in/out @ mp 45 sx CI C in/out to surface	provide the Bond No. on file with BLM tition results in a multiple completion of the filed only after all requirements, in production tubing from 8,953'. (05'. (T.Wolfcamp 10038') the Spring open perfs 8848' - 8888' (6512') (4') te 3520') (2,1,980' - 1,780'. Tag. (B.Salt 1964 (615' - 415'. Tag. (T.Salt 562')	M/BIA. Required subsequent or recompletion in a new inte including reclamation, have to SEE A COND	hs of all pertinent markers and zones. reports must be filed within 30 days rval, a Form 3160-4 must be filed once been completed and the operator has TTACHED FOR ITIONS OF APPROVA RECEIVED MAY 1 6 2018	
Attach the Bond under which following completion of the i testing has been completed. I determined that the site is rea 1. MIRU P&A unit. POOH w/rc 2. Spot 30 sx (240') CI H from 6 3. Set CIBP @ 8,800'. Tag. Cir 4. Spot 25 sx (200') CI H @ 8,8 5. Spot 25 sx (250') CI C @ 6,5 6. Spot 25 sx (250') CI C @ 4,9 7. Spot 25 sx (250') CI C @ 3,5 3. Spot 30 sx (300') CI C @ 2,3 9. Perf 5-1/2" csg @ 1,980'. Pu 10. Perf 5-1/2" csg @ 140'. Pun 11. Perf 5-1/2" csg @ 140'. Pun	the work will be performed or p nvolved operations. If the opera Final Abandonment Notices must dy for final inspection.) ad pump assembly and 2-7/8" existing PBD of 10,145' to 9,90 culate 10# salt gel mud. (Bor 100' - 8,600'. (70' - 6,320'. (T.Bone Spring 0 125' - 4,675'. (T.Delaware 487 570' - 3,320'. Tag. (9-5/8 shoe 500' - 2,000'. (T.Yates 2248') mp 60 sx (200') CI C in/out @ mp 60 sx (200') CI C in/out @ mp 45 sx CI C in/out to surface	provide the Bond No. on file with BLN tition results in a multiple completion of the filed only after all requirements, in production tubing from 8,953'. (05'. (T.Wolfcamp 10038') the Spring open perfs 8848' - 8888' (6512') (4') the 3520') (2) 1,980' - 1,780'. Tag. (B.Salt 1964 (615' - 415'. Tag. (T.Salt 562') the.	M/BIA. Required subsequent or recompletion in a new inte including reclamation, have to SEE A COND	hs of all pertinent markers and zones. reports must be filed within 30 days rval, a Form 3160-4 must be filed once been completed and the operator has TTACHED FOR ITIONS OF APPROVA RECEIVED	
Attach the Bond under which following completion of the i testing has been completed. I determined that the site is rea 1. MIRU P&A unit. POOH w/rc 2. Spot 30 sx (240') CI H from 6 3. Set CIBP @ 8,800'. Tag. Cir 4. Spot 25 sx (200') CI H @ 8,8 5. Spot 25 sx (250') CI C @ 6,5 6. Spot 25 sx (250') CI C @ 4,9 7. Spot 25 sx (250') CI C @ 3,5 3. Spot 30 sx (300') CI C @ 2,3 9. Perf 5-1/2" csg @ 1,980'. Pu 10. Perf 5-1/2" csg @ 140'. Pun 11. Perf 5-1/2" csg @ 140'. Pun	the work will be performed or p nvolved operations. If the opera Final Abandonment Notices must dy for final inspection.) ad pump assembly and 2-7/8" existing PBD of 10,145' to 9,90 culate 10# salt gel mud. (Bor 100' - 8,600'. 770' - 6,320'. (T.Bone Spring (125' - 4,675'. (T.Delaware 487 570' - 3,320'. Tag. (9-5/8 shoe 500' - 2,000'. (T.Yates 2248') mp 60 sx (200') CI C in/out @ mp 45 sx CI C in/out to surface et dry hole marker.	provide the Bond No. on file with BLN tition results in a multiple completion of the filed only after all requirements, in production tubing from 8,953'. (05'. (T.Wolfcamp 10038') the Spring open perfs 8848' - 8888' (6512') (4') the 3520') (2) 1,980' - 1,780'. Tag. (B.Salt 1964 (615' - 415'. Tag. (T.Salt 562') the.	M/BIA. Required subsequent or recompletion in a new interincluding reclamation, have to SEE A COND (') R') COND DIS MacKer	TTACHED FOR TTACHED FOR TTACHED FOR TTONS OF APPROVA RECEIVED MAY 1 6 2018	
Attach the Bond under which following completion of the i testing has been completed. I determined that the site is rea 1. MIRU P&A unit. POOH w/rc 2. Spot 30 sx (240') CI H from (2 3. Set CIBP @ 8,800'. Tag. Cir 4. Spot 25 sx (200') CI H @ 8,8 5. Spot 25 sx (250') CI C @ 4,9 7. Spot 25 sx (250') CI C @ 4,9 7. Spot 25 sx (250') CI C @ 4,9 8. Spot 30 sx (300') CI C @ 2,3 9. Perf 5-1/2" csg @ 1,980'. Pu 10. Perf 5-1/2" csg @ 140'. Pu 11. Perf 5-1/2" csg @ 140'. Pu 12. Cut wellhead off 3' BGL. Se	the work will be performed or p nvolved operations. If the opera Final Abandonment Notices must dy for final inspection.) ad pump assembly and 2-7/8" existing PBD of 10,145' to 9,90 culate 10# salt gel mud. (Bor 100' - 8,600'. 770' - 6,320'. (T.Bone Spring (125' - 4,675'. (T.Delaware 487 570' - 3,320'. Tag. (9-5/8 shoe 500' - 2,000'. (T.Yates 2248') mp 60 sx (200') CI C in/out @ mp 45 sx CI C in/out to surface et dry hole marker.	orovide the Bond No. on file with BLN tition results in a multiple completion of the filed only after all requirements, in production tubing from 8,953'. (05'. (T.Wolfcamp 10038') the Spring open perfs 8848' - 8888' (6512') (4') the Spring open perfs 8848' - 8888' (6512') the Spring open perfs 8848' - 8888' (6512') (4') the Spring open perfs 8848' - 8888' (6512') the Spring open perfs 8848' - 8888'	M/BIA. Required subsequent or recompletion in a new interincluding reclamation, have b SEE A COND (1)	hs of all pertinent markers and zones. reports must be filed within 30 days rval, a Form 3160-4 must be filed once been completed and the operator has TTACHED FOR ITIONS OF APPROVA RECEIVED MAY 1 6 2018	
Attach the Bond under which following completion of the i testing has been completed. I determined that the site is rea 1. MIRU P&A unit. POOH w/rc 2. Spot 30 sx (240') CI H from 6 3. Set CIBP @ 8,800'. Tag. Cir 4. Spot 25 sx (200') CI H @ 8,8 5. Spot 25 sx (250') CI C @ 6,8 6. Spot 25 sx (250') CI C @ 4,8 7. Spot 25 sx (250') CI C @ 4,8 7. Spot 25 sx (250') CI C @ 4,8 7. Spot 25 sx (250') CI C @ 3,5 8. Spot 30 sx (300') CI C @ 2,3 9. Perf 5-1/2" csg @ 1,980'. Pu 10. Perf 5-1/2" csg @ 140'. Pu 11. Perf 5-1/2" csg @ 140'. Pu 12. Cut wellhead off 3' BGL. Se 14. I hereby certify that the foregoir Name (Printed/Typed) Max Lubitz	the work will be performed or p nvolved operations. If the opera Final Abandonment Notices must dy for final inspection.) ad pump assembly and 2-7/8" existing PBD of 10,145' to 9,90 culate 10# salt gel mud. (Bor 100' - 8,600'. 125' - 4,675'. (T.Bone Spring 0 125' - 4,675'. (T.Delaware 487 70' - 3,320'. Tag. (9-5/8 shoe 00' - 2,000'. (T.Yates 2248') mp 60 sx (200') CI C in/out @ mp 60 sx (200') CI C in/out @ mp 60 sx (200') CI C in/out @ mp 45 sx CI C in/out to surface at dry hole marker.	brovide the Bond No. on file with BLN tition results in a multiple completion of the filed only after all requirements, if production tubing from 8,953'. (05'. (T.Wolfcamp 10038') the Spring open perfs 8848' - 8888' (6512') (4') the Spring open perfs 8848' - 8888' (6512') (4') (5512') (4') (5520') (5512	M/BIA. Required subsequent or recompletion in a new interincluding reclamation, have b () SEE A COND ()) COND ()) DIS MACCO DIS MACKAC	hs of all pertinent markers and zones. reports must be filed within 30 days rval, a Form 3160-4 must be filed once been completed and the operator has TTACHED FOR ITIONS OF APPROVA RECEIVED MAY 1 6 2018	
Attach the Bond under which following completion of the i testing has been completed. I determined that the site is rea 1. MIRU P&A unit. POOH w/rc 2. Spot 30 sx (240') CI H from 6 3. Set CIBP @ 8,800'. Tag. Cir 4. Spot 25 sx (200') CI H @ 8,8 5. Spot 25 sx (250') CI C @ 6,8 6. Spot 25 sx (250') CI C @ 4,8 7. Spot 25 sx (250') CI C @ 4,8 7. Spot 25 sx (250') CI C @ 4,8 7. Spot 25 sx (250') CI C @ 3,5 8. Spot 30 sx (300') CI C @ 2,3 9. Perf 5-1/2" csg @ 1,980'. Pu 10. Perf 5-1/2" csg @ 140'. Pu 11. Perf 5-1/2" csg @ 140'. Pu 12. Cut wellhead off 3' BGL. Se 14. I hereby certify that the foregoir Name (Printed/Typed) Max Lubitz	the work will be performed or p nvolved operations. If the opera Final Abandonment Notices must dy for final inspection.) ad pump assembly and 2-7/8" existing PBD of 10,145' to 9,90 culate 10# salt gel mud. (Bor 100' - 8,600'. 125' - 4,675'. (T.Bone Spring 0 125' - 4,675'. (T.Delaware 487 70' - 3,320'. Tag. (9-5/8 shoe 00' - 2,000'. (T.Yates 2248') mp 60 sx (200') CI C in/out @ mp 60 sx (200') CI C in/out @ mp 60 sx (200') CI C in/out @ mp 45 sx CI C in/out to surface at dry hole marker.	brovide the Bond No. on file with BLN tition results in a multiple completion of the filed only after all requirements, if production tubing from 8,953'. (05'. (T.Wolfcamp 10038') the Spring open perfs 8848' - 8888' (6512') (4') a 3520') (1,980' - 1,780'. Tag. (B.Salt 1964 (615' - 415'. Tag. (T.Salt 562') the.	M/BIA. Required subsequent or recompletion in a new interincluding reclamation, have b () SEE A COND ()) COND ()) DIS MACCO DIS MACKAC	hs of all pertinent markers and zones. reports must be filed within 30 days rval, a Form 3160-4 must be filed once been completed and the operator has TTACHED FOR ITIONS OF APPROVA RECEIVED MAY 1 6 2018 TRICT II-ARTESIA O.C.D. Suited E I.D. I.C.	
Attach the Bond under which following completion of the i testing has been completed. I determined that the site is rea 1. MIRU P&A unit. POOH w/rc 2. Spot 30 sx (240') CI H from (2 3. Set CIBP @ 8,800'. Tag. Cir 4. Spot 25 sx (200') CI H @ 8,8 5. Spot 25 sx (250') CI C @ 4,9 7. Spot 25 sx (250') CI C @ 4,9 7. Spot 25 sx (250') CI C @ 4,9 7. Spot 25 sx (250') CI C @ 2,3 8. Spot 30 sx (300') CI C @ 2,3 9. Perf 5-1/2" csg @ 1,980'. Pu 10. Perf 5-1/2" csg @ 140'. Pu 11. Perf 5-1/2" csg @ 140'. Pu 12. Cut wellhead off 3' BGL. Se 14. 1 hereby certify that the foregoir Name (Printed/Typed) Max Lubitz	the work will be performed or p nvolved operations. If the opera final Abandonment Notices must dy for final inspection.) ad pump assembly and 2-7/8" existing PBD of 10,145' to 9,90 culate 10# salt gel mud. (Bor 100' - 8,600'. 570' - 6,320'. (T.Bone Spring 0 125' - 4,675'. (T.Delaware 487' 770' - 3,320'. Tag. (9-5/8 shoe 100' - 2,000'. (T.Yates 2248') mp 60 sx (200') CI C in/out @ mp 60 sx (200') CI C in/out @ mp 45 sx CI C in/out to surface at dry hole marker. THIS SPACE	brovide the Bond No. on file with BLM tition results in a multiple completion of the filed only after all requirements, if production tubing from 8,953'. (05'. (T.Wolfcamp 10038') the Spring open perfs 8848' - 8888' (6512') (4') the Spring open perfs 8848' - 8888' (6512') (4') (515' - 415'. Tag. (T.Salt 562') the Spring open perfs 8848' - 8888' (5512') (515' - 415'. Tag. (T.Salt 562') the Spring open perfs 8848' - 8888' (5512') (515' - 415'. Tag. (T.Salt 562') the Spring open perfs 8848' - 8888' (5512') (515' - 415'. Tag. (T.Salt 562') the Spring open perfs 8848' - 8888' (5512') (515' - 415'. Tag. (T.Salt 562') (515' - 415'. Tag. (T.Salt 562'. Tag. (T.Salt 562'.	M/BIA. Required subsequent or recompletion in a new interincluding reclamation, have b () SEE A COND ()) COND ()) DIS MACCO DIS MACKAC	hs of all pertinent markers and zones. reports must be filed within 30 days rval, a Form 3160-4 must be filed once been completed and the operator has TTACHED FOR ITIONS OF APPROVA RECEIVED MAY 1 6 2018 TRICT II-ARTESIA O.C.D. Smithed Sciences	





BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Below Ground Level Cap (Lesser Prairie-Chicken Habitat)</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u> From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted

ί