Form 3160-5 (June 2015)


## UNITED STATES DEPARTMENT OF THE INTERIOR 2015 DOO HIELD BUREAU OF LAND MANAGEMENT 2015 DOO HIELD


	FORM APPROVED
Torres .	OMB NO. 1004-0137
MANAG	OMB NO. 1004-0137 Expires: January 31, 2015

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

5. Lease Serial No. NMNM911

abandoned well. Use form 3160-3 (APD) for such proposals.								
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. SRM1118			
Type of Well     Oil Well					8. Well Name and No. EL PASO FEDERAL 3H			
Name of Operator     FASKEN OIL & RANCH LIMITED     Contact: ADDISON GUELKER     E-Mail: addisong@forl.com					9. API Well No. 30-015-21307-00-S2			
3a. Address 6101 HOLIDAY HILL ROAD MIDLAND, TX 79707			(include area code) -1777		10. Field and Pool or Exploratory Area BURTON FLAT			
4. Location of Well (Footage, Sec., T.			11. County or Parish,	State				
Sec 1 T21S R26E Lot 8					EDDY COUNTY, NM			
12. CHECK THE AF	PPROPRIATE BOX(ES) T	O INDICAT	E NATURE OF	F NOTICE,	REPORT, OR OTI	HER D	ATA	
TYPE OF SUBMISSION TYPE OF ACTION								
Notice of Intent	☐ Acidize ☐ Deeper		en	☐ Production (Start/Resum		☐ Water Shut-Off		
Notice of Intent     ■	☐ Alter Casing	☐ Hydr	aulic Fracturing	☐ Reclam	ation			
☐ Subsequent Report	☐ Casing Repair ☐ New		Construction	☐ Recomp	lete		ther	
☐ Final Abandonment Notice	□ Change Plans	Plug	and Abandon		arily Abandon			
	☐ Convert to Injection	Plug	Back	☐ Water I	Disposal			
Fasken Oil and Ranch, Ltd. re current and proposed wellbore	equests a temporary aband e diagram and procedures.	onment on th	Accep	Attached are NMOCD 5/3	MA ecord DISTRIC	ECENT LY 2 S	<b>2018</b> ITESIA O.C.D.	
14. I hereby certify that the foregoing is	s true and correct. Electronic Submission #4	10117 vorific	l by the RI M Wel				- <u>-</u>	
	For FASKEN OIL	. & RANCH L	VIŤED, sent to tl	he Carlsbad	_			
Committed to AFMSS for processing by PRIS  Name (Printed/Typed) ADDISON GUELKER				· · · · · · · · · · · · · · · · · · ·				
Traine(1.1 anear 1990a) ADDIOON OULLINE			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
Signature (Electronic	Submission)		Date 05/07/20	018				
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE		: /	
Approved By /s/ Jonathon Shepard			Title PE	05/10/2018				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Cf	<u> </u>				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a c statements or representations as t	rime for any pe to any matter wi	rson knowingly and thin its jurisdiction.	willfully to m	ake to any department o	г agency	of the United	





### Fasken Oil and Ranch, Ltd El Paso Federal No. 3 1664' FNL and 660' FEL Sec 1, T21S, R26E

Eddy County, New Mexico

OBJECTIVE:

Temporarily Abandon

API:

30-15-21307

Completed:

9-26-74 Rig released

**WELL DATA:** 

13-3/8" 54.5&61#/ft H-40 casing:

Set at 350' KB Cmt 200sx Howco Lite+100sx "C" w/2% cacl2 to 125'.

Cmt to surface with 16 cubic yards ready mix.

8-5/8" 24&32# J55 casing:

Set at4666' KB, Cmt 1400sx Howco Lite+200sx Thickset+160sx "C"

w/2% cacl2 to 1600'. Filled to 75' with 1050 sx in 5 stgs.

4-1/2" 11.6&13.5# N-80 casing:

(13.5#/ft btm 24jts 946.97'):

Set at 11,295' KB, Cmt 650 "C" w/7.6# kcl/sk +1% Halad-9. TOC

7720' by Temp.

Tubing and Packer2:

Arrowset 1X 10K packer (19k compression) w/ with 2-3/8" TOSSD 1.81" "F" PN (7.45'), X-over EUE to CS Hydril (0.63'), 305 jts 2-3/8" N-80 CS Hydril tubing (9,336.18'), X-over EUE to CS Hydril (0.63'), 8 jts 2-3/8" 4.7#/ft EUE 8rd N-80 tbg (253.47'). EOT 9,611.86' KB.

NOTE: Tubing is perforated above packer for plunger lift.

Perfs:

Strawn 2/94: 9,714'-20' (7h), 9,733'-39' (7h),9,750'-52' (3h), 9,755'-58' (4h), 9,768'-70' (3h), 9,783'-90' (8h), 9,798'-9,801' (4h), 9,875'-79'

(5h). Total 42 holes.

Strawn 7/76: 9,971'-89' (16h)

Packer1:

Otis Perma-lach @ 10,515.83' w/ "N" profile nipple in top of packer

with "N" plug run 7-11-76.

Perfs:

Morrow (Inactive, 10/74): 10,983'-90' (37 hls)

TD:

11,450'

PBTD:

11,226'

Last Tubing Pull:

2-25-94

Current status:

SI ACO

1. Test mast anchors.

- 2. Set rig matting boards and half-frac open top workover tank. RUPU.
- 3. RU pump truck. Kill well down tubing with 40 bbls fresh water containing biocide, oxygen scavenger, and corrosion inhibitor.
- 4. NDWH and NU manual BOP.
- 5. Release Arrowset 1X 10k packer (19k compression) @ 9604'. NOTE: Bring two new EUE 8rd x CS Hydril crossovers in case of problems with threads.
- POW with 8 jts 2-3/8" 4.7#/ft EUE 8rd N-80 tbg (253.47'), X-over EUE to CS Hydril (0.63'), 305 jts 2-3/8" N-80 CS Hydril tubing (9,336.18'), X-over EUE to CS Hydril (0.63'), Arrowset 1X 10K packer (19k compression) w/ with 2-3/8" TOSSD 1.81" "F" PN (7.45'). Send packer in for repair and storage.
- 7. Receive 1,100' 2-3/8" 4.7#/ft EUE 8rd N-80 tubing.
- 8. PU and RIW with 4-1/2" 13.5#/ft tubing set CIBP, X-over EUE to CS Hydril, 2-3/8" N-80 CS Hydril tubing, X-over CS Hydril to EUE, 8 jts 2-3/8" EUE 8rd 4.7 #/ft tubing with +/-30 jts extra 2-3/8" 4.7#/ft EUE 8rd N-80 tubing to Otis Perma-lach packer at 10,515.83'.

# Carisbad Field Office2 OCD Artesia

- 9. Lightly tag the "N" profile nipple on top of Otis Perma-lach packer, pull tubing up 5' and set CIBP.
- 10. RU cement mixer pump truck. Pull tubing 5' and spot the following:
  - A. 8 bbls (10160'-9650') 9.5# brine with 2sx gel (required 25 sx/100 bbls), then,
  - B. Fresh water spacer, then
  - C. 25 sx Class "H" cement, then
  - D. Fresh water spacer.
- 11. POW with tubing laying down +/-30 extra jts 2-3/8" N-80 EUE 8rd 4.7#/ft tubing.
- 12. RUWL. RIW with gauge ring and junk basket to PBTD. RIW and set 6K 4-1/2" CIBP (11.6#/ft) @ 9650' and cap with 35' of Class "H" cement for PBTD 9615'. RDWL.
- 13. RIW with 2-3/8" N-80 CS Hydril tubing, X-over CS Hydril to EUE, 8 jts 2-3/8" EUE 8rd 4.7 #/ft tubing to +/-9600'.
- 14. RU pump truck and circulate well with fresh water containing biocide, oxygen scavenger, and corrosion inhibitor. Test casing to 500 psi.
- 15. ND BOP and NUWH.
- 16. Call BLM representative and set up a MIT test time and date. Run MIT test on casing to 500 psi for 30 minutes with chart recorder. Release pressure. Shut well in as Temporarily Abandoned.

cwb

5-2-18

#### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972



### Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
  - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
  - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
  - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
  - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
  - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provide justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.