Form 3160-5 (June 2015)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

BUREAU OF LAND MANAGEMENT SPACE FIELD OF Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELL Do not use this form for proposals to drill or to 6. If Indian, Allottee or Tribe Name abandoned well. Use form 3160-3 (APD) for such propos If Unit or CA/Agreement, Name and/or No. NMNM88525X SUBMIT IN TRIPLICATE - Other instructions on page 2 Well Name and No. BURCH KEELY UNIT 965H 1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other Name of Operator Contact: SANDY BALLARD API Well No. COG OPERATING LLC 30-015-40973-00-S1 E-Mail: sballard@concho.com 10. Field and Pool or Exploratory Area
BURCH KEELY-GLORIETA-UPR YESC 3a. Address 3b. Phone No. (include area code) 600 W ILLINOIS AVENUE Ph: 432-686-4373 MIDLAND, TX 79701 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State Sec 19 T17S R30E SENE 2350FNL 493FEL EDDY COUNTY, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION □ Water Shut-Off ☐ Acidize Deepen ☐ Production (Start/Resume) ■ Notice of Intent ☐ Alter Casing ☐ Hydraulic Fracturing □ Reclamation ■ Well Integrity Subsequent Report □ Casing Repair ☐ New Construction ☐ Recomplete Other Venting and/or Flari Plug and Abandon ☐ Final Abandonment Notice □ Change Plans ☐ Temporarily Abandon Convert to Injection ☐ Plug Back ■ Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Burch Keely Unit 965H Burch Keely 19A Battery Actual gas flared for this battery for 1/31/18 to 5/1/18 is as follows: (Permit approval: Electronic Submission (#402257) **OIL CONSERVATION** Total for Battery = 0 MCF ARTESIA DISTRICT Feb Total for Battery = 0 MCF March Total for Battery = 0 MCF April RECEIVED 14. I hereby certify that the foregoing is true and correct Electronic Submission #445353 verified by the BLM Well Information System For COG OPERATING LLC, sent to the Carlsbad
Committed to AFMSS for processing by PRISCILLA PEREZ on 11/29/2018 (19PP0466SE) Title SENIOR ADMINISTATIVE ASSISTANT Name (Printed/Typed) SANDY BALLARD (Electronic Submission) 11/28/2018 Signature Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE MULLIEU FOR NEWOND Approved By Title Date 7s/ Jonathon Shepard Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease NOV 3 0 2018

which would entitle the applicant to conduct operations thereon.

Office

VARESDAD FILLD VITTUL

## Additional data for EC transaction #445353 that would not fit on the form

## 32. Additional remarks, continued

Total for Battery = 235 mcf

Number of wells to flare: (13)
BURCH-KEELY UNIT 238 30-015-28331
BURCH-KEELY UNIT 418 30-015-36183
BURCH-KEELY UNIT 626 30-015-40276
BURCH-KEELY UNIT 643 30-015-39570
BURCH-KEELY UNIT 644 30-015-39571
BURCH-KEELY UNIT 651 30-015-40278
BURCH-KEELY UNIT 654 30-015-40280
BURCH-KEELY UNIT 656 30-015-40280
BURCH-KEELY UNIT 657 30-015-39567
BURCH-KEELY UNIT 788 30-015-40706
BURCH-KEELY UNIT 788 30-015-40300
BURCH-KEELY UNIT 964H 30-015-44149
BURCH-KEELY UNIT 965H 30-015-44173

Reason for flare: UNPLANNED MIDSTREAM CURTAILMENT DUE TO HLP OR PLANT MAINTENANCE OR HLP