

District I - (575) 393-6161

1625 N. French Dr., Hobbs, NM 88240

District II - (575) 748-1283

811 S. First St., Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Rd., Aztec, NM 87410

District IV - (505) 476-3460

1220 S. St. Francis Dr., Santa Fe, NM 87505

Energy, Minerals and Natural Resources

JAN 28 2019

OIL CONSERVATION DIVISION

DISTRICT II-ARTESIA CLOTO South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30-015-22218

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
KEYSTONE

8. Well Number 1

9. OGRID Number

229137

10. Pool name or Wildcat

BURTON FLAT; BONE SPRING

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

COG OPERATING, LLC

3. Address of Operator

600 W. ILLINOIS AVE, MIDLAND, TX 79701

4. Well Location

Unit Letter G : 1980 feet from the NORTH line and 1980 feet from the EAST lineSection 32 Township 20S Range 28E NMPM County EDDY

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3212' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐DOWNHOLE COMMINGLE ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ P AND A ☐CASING/CEMENT JOB ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

BCM respectfully submits for an extension to Plug & Abandon Keystone #1 on behalf of COG Operating, LLC

1. Tag cmt plug @ 6725'.

2. Set 4 1/2" CIBP @ 6170'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 6170-5900'. WOC & Tag

3. Perf & Sqz 40 sx cmt @ 5050-4050' WOC & Tag. (Bone Spring)

4. Perf & Sqz 40 sx cmt @ 3060-2960'. WOC & Tag. (8 5/8 Shoe)

5. Perf & Sqz 40 sx cmt @ 1950-1850'. WOC & Tag(T. Anhy)

6. Perf & Sqz 40 sx cmt @ 670-565'. WOC & Tag (13 3/8 Shoe, Yates)

7. Perf & Sqz 40 sx cmt @ 200'-Surface.

8. Cut off well head, verify cmt to surface, weld on Dry Hole Marker.

ENTERED
4-1-30-19

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Abigail Anderson TITLE Agent DATE 1/25/19
Type or print name Abigail Anderson E-mail address: abbym@bcmassociates.com PHONE: 432-586-7161
For State Use OnlyAPPROVED BY: [Signature] TITLE Staff Wg. DATE 1/30/19
Conditions of Approval (if any):