
	UNITED STATES		 ·			FORM APPROVED OMB No 1004-0137
(August 2007) DE	PARTMENT OF THE INTERIOR REAU OF LAND MANAGEMENT		OCD Artesia			Expires: July_31, 2010
BUF					5. Lease Serial No. NMNM0542015	
SUNDRY NOTICES AND REPORTS ON WE Do not use this form for proposals to drill or to r abandoned well. Use Form 3160-3 (APD) for such			re-enter an		6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.	
. Type of Well					8. Well Name and N	0.
[X]Oil Well [] Gas Well []Other					South Culebra Bluff 7	
Name of Operator CHEVRON USA INC					9. API Well No. 30-015-23811-00	
a. Address 301 DEAUVILLE BLVD. RM. N4707 MDLAND, TX: 79706		3b. Phone No. (1 432-687-7786	include area coi	de)	10. Field and Pool or Loving; Brushy Ca	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 14, T23S, R2BE, NWNE, 660 FNL, 1740 FEL					11. Country or Parisl Eddy County, NM	h, State
12. CHE	CK THE APPROPRIATE BO	K(ES) TO INDIC	CATE NATURI	E OF NOTI	CE, REPORT OR OT	HER DATA
TYPE OF SUBMISSION			TY	PE OF ACT	ION	
Notice of Intent	Acidize	Deeper	1	Prod	uction (Start/Resume)	Water Shut-Off
	Alter Casing		e Treat	_	amation	Well Integrity
Subsequent Report	Casing Repair	_	onstruction	_	omplete	Other
Final Abandonment Notice	Change Plans	I Plug ar ☐ Plug B	nd Abandon		porarily Abandon er Disposal	
following completion of the invo testing has been completed. Fina determined that the site is ready f Chevron USA, Inc respectfully req 1. Notify BLM 24 hours prior to Mil	Ived operations. If the operation of Abandonment Notices must b for final inspection.) puests to abandon this well as RU, in accordance with appli	n results in a mu e filed only after s follows:	ltiple completion	on or recom	pletion in a new interv	eports must be filed within 30 days al, a Form 3160-4 must be filed once en completed and the operator has
following completion of the invo testing has been completed. Fina determined that the site is ready f Chevron USA, Inc respectfully req 1. Notify BLM 24 hours prior to Mil 2. MIRU, pull rods, NU BOP, pull t 3. Set CIBP @ 4670', circulate free 4. Spot 25 sx CL C cement f/ 4670 insuccessful, WOC, tag, & pressu 5. Spot 45 sx CL C cement f/ 2667 5. Spot 60 sx CL C cement f/ 550' 7. Cut off wellhead 3' below grade	Ived operations. If the operation Abandonment Notices must b for final inspection.) uests to abandon this well as RU, in accordance with appli- shwater, pressure test casin of t/ 4443' (Brushy Canyon). ure test to 500 psi for 10 mini 7' t/ 2268' (Bell Canyon, Dela t/ surface (Shoe, T. Salt, Fre , Verify Cement To Surface,	n results in a mu e filed only after s follows: icable COAs ig to 500 psi for If pressure tes utes - if succes iware, B. Salt) esh Water) install required	Itiple completion rall requirement rall minutes - t in Step 3 was sful, spot MLF	on or recom its, including if successf s successfu ; if unsucce	oletion in a new interv reclamation, have be ul, spot MLF ul, do not WOC & tag sssful, contact engin	al, a Form 3160-4 must be filed once en completed and the operator has g. If pressure test in Step 3 was heer & BLM
following completion of the invo testing has been completed. Fina determined that the site is ready f Chevron USA, Inc respectfully req 1. Notify BLM 24 hours prior to Mil 2. MIRU, pull rods, NU BOP, pull t 3. Set CIBP @ 4670', circulate fres 4. Spot 25 sx CL C cement f/ 4670 unsuccessful, WOC, tag, & pressu 5. Spot 45 sx CL C cement f/ 2667 6. Spot 60 sx CL C cement f/ 550' 7. Cut off wellhead 3' below grade	Ived operations. If the operation Abandonment Notices must b for final inspection.) uests to abandon this well as RU, in accordance with appli- shwater, pressure test casin of t/ 4443' (Brushy Canyon). ure test to 500 psi for 10 mini 7' t/ 2268' (Bell Canyon, Dela t/ surface (Shoe, T. Salt, Fre , Verify Cement To Surface,	n results in a mu e filed only after s follows: icable COAs ig to 500 psi for If pressure tes utes - if succes iware, B. Salt) esh Water) install required	Itiple completion rall requirement rall minutes - t in Step 3 was sful, spot MLF	on or recom its, including if successf s successf ; if unsucci ker as per (oletion in a new interv reclamation, have be ul, spot MLF ul, do not WOC & tag sssful, contact engin	al, a Form 3160-4 must be filed once en completed and the operator has g. If pressure test in Step 3 was heer & BLM reclamation.
following completion of the invo testing has been completed. Fina determined that the site is ready f Chevron USA, Inc respectfully req 1. Notify BLM 24 hours prior to Mil 2. MiRU, pull rods, NU BOP, pull t 3. Set CIBP @ 4670', circulate free 4. Spot 25 sx CL C cement f/ 4670 unsuccessful, WOC, tag, & pressu 5. Spot 45 sx CL C cement f/ 2667 5. Spot 60 sx CL C cement f/ 550' 7. Cut off wellhead 3' below grade	Ived operations. If the operation Abandonment Notices must b for final inspection.) uests to abandon this well as RU, in accordance with appli- shwater, pressure test casin of t/ 4443' (Brushy Canyon). ure test to 500 psi for 10 mini 7' t/ 2268' (Bell Canyon, Dela t/ surface (Shoe, T. Salt, Fre , Verify Cement To Surface,	n results in a mu e filed only after s follows: icable COAs ig to 500 psi for If pressure tes utes - if succes iware, B. Salt) esh Water) install required	Itiple completion rall requirement rall minutes - t in Step 3 was sful, spot MLF	on or recom its, including if successf s successfu ; if unsucce ker as per (SEE	pletion in a new interv reclamation, have be ul, spot MLF ul, do not WOC & tag essful, contact engin COA's, turn over to r	al, a Form 3160-4 must be filed once en completed and the operator has g. If pressure test in Step 3 was heer & BLM reclamation.
following completion of the invo testing has been completed. Fina determined that the site is ready f Chevron USA, Inc respectfully req 1. Notify BLM 24 hours prior to Mil 2. MiRU, pull rods, NU BOP, pull t 3. Set CIBP @ 4670', circulate free 4. Spot 25 sx CL C cement f/ 4670 unsuccessful, WOC, tag, & pressu 5. Spot 45 sx CL C cement f/ 2667 5. Spot 60 sx CL C cement f/ 550' 7. Cut off wellhead 3' below grade All cement plugs will be class "C" of 14. 1 hereby certify that the foregoing is	Ived operations. If the operation Abandonment Notices must b for final inspection.) nuests to abandon this well as RU, in accordance with appli- ubing sh water, pressure test casin 0' t/ 4443' (Brushy Canyon). are test to 500 psi for 10 minu 7' t/ 2268' (Bell Canyon, Dela t/ surface (Shoe, T. Salt, Fre , Verify Cement To Surface, or "H" with a closed loop sys	n results in a mu e filed only after s follows: icable COAs ig to 500 psi fo If pressure tes utes - if succes ware, B. Salt) esh Water) install required tem used.	Itiple completion rall requirement rall minutes - t in Step 3 was sful, spot MLF	on or recom its, including if successf s successfu ; if unsucce ker as per (SEE	pletion in a new interv reclamation, have be ul, spot MLF ul, do not WOC & tag essful, contact engin COA's, turn over to r	al, a Form 3160-4 must be filed once en completed and the operator has g. If pressure test in Step 3 was heer & BLM reclamation.
following completion of the invo testing has been completed. Fina determined that the site is ready f Chevron USA, Inc respectfully req 1. Notify BLM 24 hours prior to Mil 2. MiRU, pull rods, NU BOP, pull t 3. Set CIBP @ 4670', circulate free 3. Spot 25 sx CL C cement f/ 4670 unsuccessful, WOC, tag, & pressu 5. Spot 45 sx CL C cement f/ 2667 5. Spot 60 sx CL C cement f/ 550' 7. Cut off wellhead 3' below grade All cement plugs will be class "C" of 14. Thereby certify that the foregoing is	Ived operations. If the operation Abandonment Notices must b for final inspection.) nuests to abandon this well as RU, in accordance with appli- ubing sh water, pressure test casin 0' t/ 4443' (Brushy Canyon). are test to 500 psi for 10 minu 7' t/ 2268' (Bell Canyon, Dela t/ surface (Shoe, T. Salt, Fre , Verify Cement To Surface, or "H" with a closed loop sys	n results in a mu e filed only after s follows: icable COAs ig to 500 psi fo If pressure tes utes - if succes ware, B. Salt) esh Water) install required tem used.	Itiple completion rall requirement rall minutes - t in Step 3 was sful, spot MLF	if successf s successf s successf if unsucce ker as per (SEE CON	pletion in a new interv reclamation, have be ul, spot MLF il, do not WOC & tag essful, contact engin COA's, turn over to r COA's, turn over to r	al, a Form 3160-4 must be filed once en completed and the operator has g. If pressure test in Step 3 was heer & BLM reclamation.
following completion of the invo testing has been completed. Fina determined that the site is ready f Chevron USA, Inc respectfully req 1. Notify BLM 24 hours prior to Mil 2. MiRU, pull rods, NU BOP, pull t 3. Set CIBP @ 4670', circulate free 4. Spot 25 sx CL C cement f/ 4670' unsuccessful, WOC, tag, & pressu 5. Spot 45 sx CL C cement f/ 2667 5. Spot 60 sx CL C cement f/ 550' 7. Cut off wellhead 3' below grade All cement plugs will be class "C" of 14. 1 hereby certify that the foregoing is	Ived operations. If the operation Abandonment Notices must b for final inspection.) nuests to abandon this well as RU, in accordance with appli- ubing sh water, pressure test casin 0' t/ 4443' (Brushy Canyon). are test to 500 psi for 10 minu 7' t/ 2268' (Bell Canyon, Dela t/ surface (Shoe, T. Salt, Fre , Verify Cement To Surface, or "H" with a closed loop sys	n results in a mu e filed only after s follows: icable COAs ig to 500 psi fo If pressure tes utes - if succes ware, B. Salt) esh Water) install required tem used.	Itiple completion rall requirement t in Step 3 wat sful, spot MLF	if successf s successf s successf if unsucce ker as per (SEE COI	pletion in a new interv reclamation, have be ul, spot MLF il, do not WOC & tag essful, contact engin COA's, turn over to r COA's, turn over to r	al, a Form 3160-4 must be filed once en completed and the operator has g. If pressure test in Step 3 was heer & BLM reclamation.
following completion of the invo testing has been completed. Fina determined that the site is ready f Chevron USA, Inc respectfully req 1. Notify BLM 24 hours prior to MII 2. MIRU, pull rods, NU BOP, pull t 3. Set CIBP @ 4670', circulate fres 4. Spot 25 sx CL C cement f/ 4670 unsuccessful, WOC, tag, & pressu 5. Spot 45 sx CL C cement f/ 2667 6. Spot 60 sx CL C cement f/ 2667 7. Cut off wellhead 3' below grade All cement plugs will be class "C" of Nick Glann	Ived operations. If the operation Abandonment Notices must b for final inspection.) nuests to abandon this well as RU, in accordance with appli- ubing sh water, pressure test casin 0' t/ 4443' (Brushy Canyon). are test to 500 psi for 10 minu 7' t/ 2268' (Bell Canyon, Dela t/ surface (Shoe, T. Salt, Fre , Verify Cement To Surface, or "H" with a closed loop sys	n results in a mu e filed only after s follows: icable COAs ig to 500 psi foi ff pressure tes utes - if succes ware, B. Salt) install required tem used.	Title P&A En Date 04/12/2	if successf s successf s successf if unsucce ker as per (SEE COI ngineer/Pro	elect Manager	al, a Form 3160-4 must be filed once en completed and the operator has g. If pressure test in Step 3 was heer & BLM reclamation.
following completion of the invo testing has been completed. Fina determined that the site is ready f Chevron USA, Inc respectfully req 1. Notify BLM 24 hours prior to MII 2. MIRU, pull rods, NU BOP, pull t 3. Set CIBP @ 4670', circulate fres 4. Spot 25 sx CL C cement f/ 4670 unsuccessful, WOC, tag, & pressu 5. Spot 45 sx CL C cement f/ 2667 6. Spot 60 sx CL C cement f/ 550' 7. Cut off wellhead 3' below grade All cement plugs will be class "C" of Nick Glann	Ived operations. If the operation of Abandonment Notices must b for final inspection.) ruests to abandon this well as RU, in accordance with appli- ubing sh water, pressure test casin 0' t/ 4443' (Brushy Canyon). ure test to 500 psi for 10 mino 7' t/ 2268' (Bell Canyon, Dela t/ surface (Shoe, T. Salt, Fre , Verify Cement To Surface, or "H" with a closed loop sys s true and correct. Name (Primied	n results in a mu e filed only after s follows: icable COAs ig to 500 psi foi ff pressure tes utes - if succes ware, B. Salt) install required tem used.	Itiple completion rall requirement rall requirement t in Step 3 was sful, spot MLF I dry hole mark dry hole mark Title P&A Ent Date 04/12/2 RAL OR ST	if successf s successf s successf if unsucce ker as per (SEE COI ngineer/Pro	ect Manager	al, a Form 3160-4 must be filed once en completed and the operator has g. If pressure test in Step 3 was heer & BLM reclamation. ED FOR OF APPROVAL
following completion of the invo testing has been completed. Fina determined that the site is ready f Chevron USA, Inc respectfully req 1. Notify BLM 24 hours prior to MII 2. MIRU, pull rods, NU BOP, pull t 3. Set CIBP @ 4670', circulate fres 4. Spot 25 sx CL C cement f/ 4670 unsuccessful, WOC, tag, & pressu 5. Spot 45 sx CL C cement f/ 2667 6. Spot 60 sx CL C cement f/ 2667 7. Cut off wellhead 3' below grade All cement plugs will be class "C" of 14. 1 hereby certify that the foregoing is Nick Glann	Ived operations. If the operation of Abandonment Notices must b for final inspection.) ruests to abandon this well as RU, in accordance with appli- ubing sh water, pressure test casin 0' t/ 4443' (Brushy Canyon). ure test to 500 psi for 10 mint 7' t/ 2268' (Bell Canyon, Dela t/ surface (Shoe, T. Salt, Fre , Verify Cement To Surface, or "H" with a closed loop sys s true and correct. Name (Primed THIS SPACE	n results in a mu e filed only after s follows: icable COAs g to 500 psi fou lf pressure tes utes - if succes ware, B. Salt) esh Water) install required tem used.	r 10 minutes - t in Step 3 was sful, spot MLF I dry hole mark Tule P&A En Date 04/12/2 RAL OR S1	if successf s successf s successf if unsucce ker as per (SEE COI ngineer/Pro	ect Manager	al, a Form 3160-4 must be filed once en completed and the operator has g. If pressure test in Step 3 was heer & BLM reclamation. ED FOR OF APPROVAL

.

- •

.



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>minety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer 1s used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.