Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELL OCD Artesia

5. Lease Serial No. NMLC028775A

	form for proposals to drill or to re-enter an
abandoned well.	Use form 3160-3 (APD) for such proposals.

abandoned well. Use form 3160-3 (APD) for such proposals.				ttee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2				Agreement, Name and/or No.	
1. Type of Well				i No.	
Oil Well Gas Well Other: INJECTION 2. Name of Operator Contact: ABIGAIL ANDERSON					
COG OPERATING LLC E-Mail: abbym@bcmandassociates.com				65-00-S1	
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701	h: 432-580-7161		10. Field and Pool or Exploratory Area GRAYBURG		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Pa	11. County or Parish, State	
Sec 34 T17S R29E NENE Tract 1A 660FNL 654FEL				EDDY COUNTY, NM	
12. CHECK THE AF	PPROPRIATE BOX(ES) TO	INDICATE NATURE OF	F NOTICE, REPORT, OR	OTHER DATA	
TYPE OF SUBMISSION	ION TYPE OF ACTION				
Notice of Intent ■	☐ Acidize	☐ Deepen	☐ Production (Start/Resum	e)	
	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	☐ Well Integrity	
☐ Subsequent Report	Casing Repair	☐ New Construction	☐ Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Temporarily Abandon		
	Convert to Injection	☐ Plug Back	■ Water Disposal	•	
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 1. Set 7" CIBP @ 2875'. Spot 25 sx cmt on top. Circulate hole w/ MLF. 2. Set 7" CIBP @ 2500'. Spot 25 sx cmt on top. Pressure test csg. to 500 psi. Circulate hole w/ MLF. 3. Perf & Sqz 58 sx @ 480-580. WOC & Tag. 315 4. Perf & Sqz 45 sx @ 60' to surface. 5. Cut off wellhead and weld on Below Ground Dry Hole Marker. SEE ATTACHED FOR CONDITIONS OF APPROVAL JUL 2 3 2019					
14. I hereby certify that the foregoing is true and correct. Electronic Submission Particle Confidence of the Carlsbad Committed to AFMSS for processing by DEBO RAH MCKINNEY on 05/01/2019 (19DLM0456SE) Name (Printed/Typed) ABIGAIL ANDERSON Title AGENT					
Signature (Electronic Submission) Date 05/01/2019					
(Licenoffic S		FEDERAL OR STATE (
	20			6	
Approved By Conditions of approval if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct the applicant to conduct the second that is the second to the second that is the second to the second that is t	d. Approval of this notice does not uitable title to those rights in the subct operations thereon. U.S.C. Section 1212, make it a crim	ject lease Office Office	willfully to make to any departme	ent or agency of the United	
States arry taise, neutrous or traudulent s	materierus or representations as to a	ny matter within its jurisdiction.			

COG Operating LLC

Lease & Well # **RJ Unit #124** 30-015-03765 Spud: 10/9/47 Elevation - 3558 1 KB -Top of cmt est @ 120' \ Msalt 365 Blat 750 8 1/4" csg @ 430', 50 sx cmt. Red Sd op of cmt est @ 1,200 272/ 2 3/8" IPC tbg set @ 2850" San Andres 2550-66, 2592-2600, 18 holes Squeezed off w/ 200 sx, January, 1992. re-acidized w/3,000 gal 15% HCL, December 12, 2002 ""Notice of intent to perf & re-acidize squeezed perfs @ 2550-2600 submitted to BLM, 12/12/02. No field tickets from Mack or Vintage to comfirm, Baker Loc-set - 2850' no subsequent report filed. BJ field ticket indicates this zone acidized ??? 7" 20# csg @ 2922'. Cmt w/100 sx. -San Andres OH 2922 - 30931. Acidized w/1000 gal HCL + 4,000 gal LCA Acid Converted to injection well, January, 1992.

6" OH to 30931

Tubing and packer information taken from "proposed condition" wellbore diagram by Meridian, not dated.

COG Operating LLC

Lease & Well # **RJ Unit #124** 30-015-03765 Spud: 10/9/47 Elevation - 3558 ' KB -@ Pulis 35 5+ 0 66 - SWACE 3 Pay 3512 555-50 C 480-380 WOC TAS 8 1/4" csg @ 430', 50 sx cmt. 2 3/8" IPC tbg set @ 2850" D 7" CINC 2500 W/2554 San Andres 2550-66, 2592-2600, 18 holes Squeezed off w/ 200 sx, January, 1992. re-acidized w/3,000 gal 15% HCL, December 12, 2002 97" CTBPE 2875 W/ 255 ***Notice of Intent to perf & re-acidize squeezed perfs @ 2550-2600 submitted to BLM. 12/12/02. No field tickets from Mack or Vintage to comfirm, Baker Loc-set - 2850' no subsequent report filed. BJ field ticket indicates this zone acidized ??? 7" 20# csg @ 2922' Cmt w/100 sx. San Andres OH 2922 - 3093'. Acidized w/1000 gal HCL + 4,000 gal LCA Acid Converted to injection well, January, 1992

Tubing and packer information taken from "proposed condition" wellbore diagram by Meridian, not dated.

6" OH to 3093"

32.7964401 -104.0561371

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells' Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

- Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.
 - 6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted