_				(
Submit Office	Copy To Appropriate District	State of	New Me	exico			Form C-103	
District 1625 N	<u>1</u> (575) 393-6161 French Dr., Hobbs, NM 88240	Energy, Minerals	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.			
District 811 S F	$\underline{II} = (575) 748 - 1283$ irst St. Artesia NM 88210	OIL CONSER			30-015-30164			
District	$\frac{111}{10} - (505) 334-6178$	1220 South St. Francis Dr.			5. Indicate Type of Lease			
District	$\frac{10}{10} = (505) 476-3460$	Santa F	Santa Fe, NM 87505			6. State Oil & Gas Lease No.		
1220 S. 87505	05. St. Francis Dr., Santa Fe, NM 05							
(DO NC	SUNDRY NOTICES AND REPORTS ON WELLS OO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A IFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH ROPOSALS)				7. Lease Name or Unit Agreement Name			
DIFFER					South Culebra Bluff 23			
1. Typ	Type of Well: Oil Well Gas Well X Other SWD				8. Well Numb	oer 013		
2. Nai	lame of Operator Chevron USA Inc.				9. OGRID Number 4323			
3. Ad	dress of Operator				10. Pool name or Wildcat			
	6301 Deauville BLVD, Midland, TX 79706					SWD Brushy Canyon		
4. We	Il Location	cation It latter F 1650 feet from the North line and				C (I V	Vost I:	
Unit Letter : 1050 teet from the 105111 line and 1650 feet from the West li Section 23 Township 235 Pange 285 NIMPM								
11. Elevation (Show whether DR, RKB, RT, GR, etc.)								
3026 GL								
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data								
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							OF:	
PERF	PERFORM REMEDIAL WORK PLUG AND ABANDON I REMEDIAL WO EMPORARILY ABANDON CHANGE PLANS COMMENCE D PULL OR ALTER CASING MULTIPLE COMPL CASING/CEME					RK		
PULL								
DOWN	HOLE COMMINGLE		_					
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of 							ing estimated date	
							iagram of	
	proposed completion or	a completion or recompletion.						
Chevron USA INC respectfully request to abandon this well as follows:								
Provide 24 hour notice to NMOCD prior to operations.								
1. MIRU, test tubing t/ 1000 psi for 5 minutes, pull rods, N/U BOP, pull tubing								
2. Set CIBP @ 5646', spot 25 sx Class C CMT f/ 5646' to 5418' (BC Perfs), Pressure Test @ 1000 psi for								
10 minutes - WOU, & lag 3 Shot 30 ex of Class C CMT from 4804' to 4654' (Brushy Conver)								
4. Spot 30 sx of Class C CMT from 3517' to 3364' (Cherry Canyon)								
5. Spot 60 sx Class C CMT from 2700 to 2296' (Bell Canvon, Lamar LS, B Salt)								
6. Spot 70 sx Class C CMT from 600' to surface (Shoe, T. Salt, Fresh Water) - Pert @600 were and a surface (Shoe, T. Salt, Fre								
7. Verify cement to surface and turn over to surface group for site reclamation								
÷	CIBP @ 6,	180' w/25 5	× Ce.	-c-t -w	0 - 4 7 4 .	D AUG	1 4 2019 ° V ²	
						DISTRICTI	ARTESIAO.C.D.	
111	- <u>A</u> (1 1)						,)	
X)e	e Attached	COA;		Must 6	e Plugg	ed by	8/15/20	
I nereby certify that the information above is true and complete to the best of my knowledge and belief.								
alcu		(1-			M	D 1 D D	8/13/2010	
SIGN		<u> </u>	ILE <u>W</u>	en ræa rroject	wanager	DATE	0/10/2017	
Туре	or print name <u>Ricky</u>	Villanueva E	-mail addr	ess: <u>ryqg@ch</u>	evron.com	_ PHONE: _	432-488-7448	
For S	tate Use Only		_	\sim			11	
APPROVED BY: DATE 8/15/19								
	/	-		. /		/	,	





Note: This schematic is not to scale. For display purposes only.

CONDITIONS FOR PLUGGING AND ABANDONMENT

District II / Artesia N.M.

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If the well is not plugged within 1
- 7. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 8. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 9. Produced water will not be used during any part of the plugging operation.
- 10. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 11. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 12. Class 'C' cement will be used above 7500 feet.
- 13. Class 'H' cement will be used below 7500 feet.
- 14. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 15. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing