Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS	,	J
o not use this form for proposals to drill or to re-enter an	- 1	
andoned well. Use form 3160-3 (APD) for such proposals.		6


SUNDRY	NOTICES AND REPO	RTS ON WE	LLS	,	NMNM196	09	
abandoned wel	is form for proposals to II. Use form 3160-3 (AP	D) for such p	roposals.	Ī	6. If Indian, Allo	ottee or Tri	be Name
SUBMIT IN	TRIPLICATE - Other ins	tructions on	page 2		7. If Unit or CA	/Agreemen	t, Name and/or No.
1. Type of Well Oil Well Gas Well Oth	ner				8. Well Name an HOLLY FED		!
Name of Operator WPX ENERGY PERMIAN, LL	Contact: C E-Mail: abbym@bo	ABIGAIL AN	DERSON es.com		9. API Well No. 30-015-249		
3a. Address 3500 ONE WILLIAMS CENTE TULSA, OK 74172	R MD-35	3b. Phone No Ph: 432-58	. (include area code) 0-7161		10. Field and Po BRUSHY D	ol or Explo DRAW- D	oratory Area ELAWARE
4. Location of Well (Footage, Sec., T.	., R., M., or Survey Description)			11. County or Pa	arish, State	•
Sec 26 T26S R29E 1980FNL 32.014373 N Lat, 103.957038					EDDY CO	COUNTY	, NM
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE, I	REPORT, OR	OTHER	DATA
TYPE OF SUBMISSION			TYPE OF	ACTION			
■ Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Production	on (Start/Resum	e) 🗖	Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclama	tion		Well Integrity
	□ Casing Repair	☐ New	Construction	☐ Recompl	ete		Other
☐ Final Abandonment Notice	☐ Change Plans	🛛 Plug	and Abandon	☐ Tempora	rily Abandon		
13. Describe Proposed or Completed Ope	Convert to Injection	Plug		☐ Water Di	•		
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fi 1. Tag existing 4 1/2" CIBP @ 2. Set 4 1/2" CIBP @ 4930'. C 3. Spot 25 sx cmt @ 3000-265 4. Perf & Sqz 25 sx cmt @ 124*deep penetrating shots throug 5. Perf & Sqz 80 sx cmt @ 51	operations. If the operation revariandonment Notices must be filmal inspection. 5160'. irculate hole w/ MLF. Pre 60'. WOC & Tag (B/Salt & 40-1090'. WOC & Tag (T/oth 4 1/2 & 8 5/8"	sults in a multipled only after all resoure test cso 8 5/8" Shoe) Salt)	e completion or reco requirements, includ	empletion in a no ing reclamation	ew interval, a Forr , have been compl	n 3160-4 n leted and th	nust be filed once e operator has
*deep penetrating shots throug 6. Cut off well head, verify cmt	ah 4 1/2 & 8 5/8"		/ Hole Marker.		EE ATTAC		
		,		C(ONDITION	IS OF	APPROVAL
							SERVATION
14. I hereby certify that the foregoing is	Electronic Submission #4 For WPX ENER Committed to AFMSS fo	RGY PERMIAN	, LLC, sent to the by PRISCILLA PE	e Carlsbad REZ on 07/02/	System /\	UG 2 I	
Name (Printed/Typed) ABIGAIL /	ANDERSON		Title REGUL	ATORY	·		156
Signature (Electronic S	ubmission)		Date 07/02/20	019		RECEI	AEIJ
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE US	E		
Approved By	, Q. Com	≥	Title SA	ET			8-7-17 Date
Conditions of approval, if any, are attached certify that the applicant holds legal or equ hich would enable the applicant to condu	itable title to those rights in the	not warrant or subject lease	Office CFC			,	
title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1001 and Title 40 U.S.C. Section 1001 and	J.S.C. Section 1212, make it a tatements or representations as	crime for any pe to any matter wi	rson knowingly and thin its jurisdiction.	willfully to mak	te to any departme	ent or agend	cy of the United

(Instructions on page 2)

^{**} OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

WPX EN	ERGY		
Author:	BCM & Associates, INC		
Well Name	Holly A Federal	Well No.	#2
Field	Stateline-Brushy Draw	API#:	30-015-24949
County	Eddy	Prop #:	
State	New Mexcio	Zone:	Delaware
Spud Date	12/14/1984	-	Sec 26, T26S, R29E
GL	2892	-	1980'FNL 1980'FEL

Description	O.D.	Grade	Weight	Depth	Hole	Cmt Sx	TOC
Surface Csg	13 3/8	77#	?	460	17 1/2	500	Circ'd
Inter Csg	8 5/8	32#	K-55	2,750	11	150	1971
Prod Csg	4 1/2	10.5#	J-55	6,250	7 7/8	1,150	Circ'd



PBTD @ 6210' TD @ 6250' 13 3/8 77# ? CSG @ 460 5. Perf & Sqz 80 sx cmt @ 510 to surface. (13 3/8" Shoe) *deep penetrating shots through 4 1/2 & 8 5/8"

4. Perf & Sqz 25 sx cmt @ 1240-1090'. WOC & Tag (T/Salt) *deep penetrating shots through 4 1/2 & 8 5/8"

8 5/8 32# K-55 CSG @ 2,750

3. Spot 25 sx cmt @ 3000-2650'. WOC & Tag (B/Salt & 8 5/8" Shoe)


2. Set 4 1/2" CIBP @ 4930'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 4930-4580'.

Perfs @ 4979-5062'

1. Tag existing 4 1/2" CIBP @ 5160'.

Perfs @ 6095-6218'

4 1/2 10.5# J-55 CSG @ 6,250



Date: 6/26/2019 NLF CURRENT

TD @ 5.250" (MD)
PBTD @ 6.210" (MD)
(6.250" TVD)

32.0143738

That soo-103.9570389

Black 2908

Del. 2860

Charry 3760

Boushy 5155

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.