

(June 2015)	DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OCD Artesi				tesia	OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS						NMNM88134		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2						7. If Unit or CA/Agreement, Name and/or No		
1. Type of Well SQ Oil Well Gas Well Other						8. Well Name and No. H B 11 FEDERAL 2		
2. Name of Operator Contact: ARMON RADFAR DEVON ENERGY PRODUCTION COM-Mail: Armon.Radfar@dvn.com						9. API Well No. 30-015-29248-00-S1		
3a. Address 333 WEST SI OKLAHOMA,	HERIDAN AVEN OK 73102	3b. Phone No. (include area code) Ph: 405-552-5014			10. Field and Pool or Exploratory Area PIERCE CROSSING			
4. Location of Well	l (Footage, Sec., T				11. County or Parish, State			
Sec 11 T24S	R29E NWSW 16	ь.			EDDY COUNTY, NM			
12. 0	CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE NA	TURE OF	NOTICE,	REPORT, OR OTI	HER DATA	
TYPE OF SU	BMISSION	TYPE OF ACTION						
Notice of In	tent	Acidize	Acidize Deepen P		Product	ion (Start/Resume)	U Water Shut-O	
_	□ Alter Casing		🗖 Hydraulic F	racturing	🗖 Reclam	ation	🗖 Well Integrity	
Subsequent	Report	Casing Repair	🗖 New Constr	uction	□ Recomplete		Other	
🗖 Final Aband	ndonment Notice   Change Plans		🛛 Plug and Abandon		Temporarily Abandon			
		Convert to Injection	Plug Back		Water Disposal date of any proposed work and approx			
3. Tag CIBP (	production tubin @ 7750'. Circ 10	# salt gel. Spot 25 sx Cl C	; from 6850'-6600'. (	Top Bone S	Spring @ 6	AUG	2 1 2019	
4. Spot 25 sx	CI C from 4250'-	-4000'. (Spacer plug) -2850'. WOC & tag. (Top I				, 	CEIVED	
6. Perf @ 650 7. Perf @ 140	)'. Pump 35 sx C	x Cl C from 650'-340'. WC I C in/out to surface. et dry hole marker.	C & tag. (T. Salt @ 5/22/1 cepted for record		÷ ,	TTACHED	FOR	
Δι	(	Ad	,	,	COND	TIONS OF	APPROVA	
F	ground that the foregoing is	level dry	role mar	Kor	requi	red	<u></u>	
The field y bonny		Electronic Submission #4	Y PRODUCTION CON	LP, sent to	o the Caris	bad		
Name (Printed/T			Title	ENGINEE				
	(Electronic S	Submission)	Date	08/01/201	9			
Signature				STATE O	FFICE U	SE		
Signature		THIS SPACE FO						
SignatureApproved By	Jame	THIS SPACE FO		SA	ÉT		8-4-1 Date	
Approved By Conditions of approve	Jame al, jr any, are attached and holds legal or equ	d. Approval of this notice does uitable title to those rights in the		SA	ÉT		J-4-19 Date	
Approved By Conditions of approva certify that the applica which would entitle th Title 18 U.S.C. Sectio	al, it any, are attached and holds legal or equ the applicant to condu	d. Approval of this notice does uitable title to those rights in the	not warrant or subject lease Office crime for any person kno	S A CFO wingly and w	ET illfully to ma	ike to any department or		

X



Devon - Internal



## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.