Submit 1 Copy To Appropriate District State of New Mex	
District I - (575) 393-6161 NM OIEnergy SMinerals and Natura	al Resources Revised August 1, 20
1625 N. French Dr., Hobbs, NM 88240 ARTESIA DISTRICT. <u>District II</u> - (575) 748-1283	WELL API NO. 30-015-35511
811 S. First St., Artesia, NM 88210 OPTL2904 ERVATION I	DIVISION 5 Indicate Type of Lassa
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. France	$SIS Dr.$ STATE \Box FEE \boxtimes
District IV - (505) 476-3460 BECEIN Santa Fe, NM 875	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUC DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR	
PROPOSALS.)	Souli Culebra Blull 25
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other	8. Well Number: 18
2. Name of Operator Chevron USA Inc.	9. OGRID Number
3. Address of Operator	4323 10. Pool name or Wildcat
6301 DEAUVILLE BLVD., MIDLAND, TX 79706	Loving; Brushy Canyon, East
4. Well Location	
Unit Letter <u>E</u> : 1883 feet from the North	line and <u>1052</u> feet from the West line
	ange 28E NMPM County Eddy
11. Elevation (Show whether DR, I	
3,030' GL, 3,047.4' KB	and the second
TEMPORARILY ABANDON CHANGE PLANS	REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS P AND A CASING/CEMENT JOB
_	
	OTHER: TEMPORARILY ABANDON
 Describe proposed or completed operations. (Clearly state all performed of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. 8-5/8" @ 335' TOC Surf. 6,220'. 	For Multiple Completions: Attach wellbore diagram of
Chevron USA INC respectfully request to abando	on this well as follows:
1. Call and notify NMOCD 24 hrs before operations begin.	
 Can and notify NNIOCD 24 ms before operations begin. MIRU slickline unit. 	
3. Run gauge ring t/ locate 1.43 F Nipple at 6,057'. Run tubin	
4. Pressure test casing and tubing t/ 1,000 psi f/ 15 minutes ea	
5. MIRU pulling unit, check well pressures, perform bubble t intends to Zonite or cut and pull casing after the well after NMOCD and Chevron.	
6. Unlatch from on-off tool and spot MLF as per the guidance a. Discuss with engineer on standing back tubing if it	
7. Spot 25 sx CL "C" cmt f/ 6,057' t/ 5,810', discuss w/ NMC test (Perfs).	OCD on waiving WOC and tag if casing passed a press
8. Spot 25 sx CL "C" cmt f/ 4,730' t/ 4,484' (Brushy Canyon)).
9. Spot 35 sx CL "C" cmt f/ 3,541' t/ 3,195' (Cherry Canyon)	
10. Spot 40 sx CL "C" cmt f/ 2,690' t/ 2,295' (Bell Canyon, Lamar LS, B.Salt).	
11. Spot 50 sx CL "C" cmt f/ 471' t/ Surface (Shoe, FW, T.Sal	
12.Cut all casings & anchors & remove 3' below grade. Verify	
diameter, 4' tall). Clean location. Note: All cement plugs class "C" (<7,500') or "H" (>7,500') w	vith closed loop system used, and MLF spotted between
plugs. hereby certify that the information above is true and complete to the best SIGNATURE M TITLE <u>P&A Engineer</u> , Attorney	
ITTLE F&A Lighter, Allofiley	<u>III IAU</u> DATE <u>10/21/17</u>

-

•

Type or print name _	<u>Howie</u>	Lucas
For State Use Only		

!

٦[.]

APPROVED BY:	TITLE	DATE
Conditions of Approval (if any):		



