nit-1 Copy To Appropr	iate District	State of I	New Me	exico			Form C-103	
District 1 – (575) 393-6161 Energy, Minerals and Natural Reso				ral Resources			Revised July 18, 2013	
1635 N. French Dr., Hobbs					WELL API NO.			
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION					30-015-21901 5. Indicate Type of Lease			
District III – (505) 334-6178 1220 South St. Francis Dr.					STATE FEE			
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 Santa Fe, NM 87505					6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM								
87505 SUNDRY NOTICES AND REPORTS ON WELLS					7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A						Old Indian Draw Unit		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH						old materials out		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other					8. Well Number 14			
2. Name of Operator					9. OGRID Number			
Chevron USA INC					168489			
3. Address of Operator					10. Pool name or Wildcat			
6301Deauville BLVD, Midland, TX 79706					Indian Draw Delaware			
4. Well Location				-				
Unit Letter	N : 330	feet from the	South	line and	1650	feet from the	West line	
Section	7			inge 28E	NMPM	Coun		
	11. Ele			RKB, RT, GR, etc.				
		·			, 			
				, , , , , , , , , , , , , , , , , , , ,				
12	2. Check Appropr	riate Box to Inc	licate N	ature of Notice.	Report or	Other Data		
					-			
					SEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR								
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A) A 📙	
PULL OR ALTER CAS		PLE COMPL		CASING/CEMEN	I JOB	<u>L_l</u> i		
DOWNHOLE COMMIN								
CLOSED-LOOP SYST OTHER:	EM 🗌		П	OTHER:			П	
	osed or completed ope	erations. (Clearly	state all r		d give pertin	ent dates, inclu	iding estimated date	
	proposed work). SEI							
	oletion or recompletio							
	Chevron US	SA INC respectful	ly reques	t to abandon this w	ell as follow	s:		
1011 1 25 NR 60	CD 241 1 C	. At a sea to be a trans						
1.Call and notify NMO	-	rations begin.						
2.Move in rig and rig up 3.RIH and set CIBP @		1000 psi for 10 r	nimutes			1.0		
4.Spot 30 sx CL "C" cm	of f/3104't/2830' de	, 1000 p31 101 10 1 - not-WOC & tag :	if casing i	passed a pressure te	est (perfs.)	ンノベン		
5.Spot 60 sx of Class C					(P • 115,)			
6 Spot 55 sx f/ 450't/ St	ırface' (TSalt,Shoe,W	/B).	_	•				
7.Cut all casings & ancl	nors & remove 3' belo	ow grade. Verify o	ement to	surface & weld on	dry hole ma	rker as per, NM	40CD	
7.Cut all casings & anch requirements. Clean loc	cation. Not a	tederal	Well -	-Please S.	Amit P	Apermost	+01	
		shut in	Stat~	1 - NOI +	Susebm	ent Report		
01	. 1 7 0	1 .	٥		2 1			
Please 5 I hereby certify that the	ulmil (u	rrent t	1ROP	25e 2 W/	s ()			
I hereby certify that the	information above is	true and complete	to the be	est of my knowledg	e and belief.			
	1							
SIGNATURE	1/2(1=	TITI	F W	ell P&A Project Ma	anager	DATE	10/1/2019	
SIGNATURE	<i>/</i>	1112.	L					
Type or print name	Ricky Villanueva	E-ma	il address	: ryqg&chevro	on.com	PHONE:	432-687-7786	
For State Use Only				Fire and		GC.		
	DENIE			DENIED	i.			
APPROVED BY:		TITLE	Ε	- and the last	y 	DATE		
Conditions of Approval	(if any):							