Submit 1 Copy To Appropriate State of New Mexico Office	Form C-103
Pherov Minerals and Nanital Reso	ources Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240B 2 1 2000 District II – (575) 748-1283 FEB 2 1 2000	20.045.27500
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVIS	1.5 Indicate Type of Lease
District III – (505) 33 67 1 1 1000 Rio Brazos Rd., Editor CD ARTES South St. Francis Dr. District IV – (505) 476-3460 Santa Fe, NM 87505	STATE X FEE
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Elk Wallow 11 State
1. Type of Well: Oil Well	8. Well Number 001H
Name of Operator XTO Energy, Inc	9. OGRID Number 5380
3. Address of Operator 6401 Holiday Hill, Rd #5	10. Pool name or Wildcat
Midland, Tx 79707	Pierce Crossing, Bone Spring, East
4. Well Location	1 407
	ne and 467 feet from the West line
Section 11 Township 25S Range 2	9E NMPM County Eddy
3039' GR	7, OK, etc.)
12. Check Appropriate Box to Indicate Nature of	f Notice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
	DIAL WORK ALTERING CASING
	IÈNCE DRILLING OPNS. □ P AND A □ □ G/CEMENT JOB □
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	
OTHER: OTHER	
13. Describe proposed or completed operations. (Clearly state all pertinent of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For M	
proposed completion or recompletion.	. Attach wendere diagram of
XTO Energy, Inc respectfully requests to TA well, for frac protect purposes. With the following	procedure:
API# 30-015-37588	
 MIRU plugging company. Set open top steel pits for plugging operations. 	
 POOH laying down rods and pump. ND WH, NU 3K manual BOP. Unseat 5.5" pacl MIRU WL lubricators. RIH w/ 5.5" gauge ring & junk basket. Contact the engineer J 	ker and POOH laying down 2-7/8" J-55 tbg.
POOH w/ 5.5" gauge ring & junk basket (5.5" drift is 4.89").	
4) RIH WL w/ 5.5" CIBP and dump bailer to 7900' MD. Set CIBP and dump 35' cemer	nt over plug. WOC and Tag at least 7865' MD. POOH
& RDMO WL. 5) RIH 2-3/8" workstring, Load csg w/ 2% KCI with biocide and pressure test csg to 50	0 psi for 30 minutes. Notify BLM of result. POOH w/
2-3/8" workstring.	status may be granted after a
6) RDMO PU, transport trucks, and pump truck. TA 7) Pull fluid from steel tank and haul to disposal. Release steel tank. Su	iccessful MIT test is performed.
C.	ontact the OCD to schedule the test
	it may be witnessed.
Spud Date: Rig Release Date: SSC	1
I hereby certify that the information above is true and complete to the best of my	knowledge and belief
Thereby certify that the information above is true and complete to the best of my	, who wiedge and benef.
SIGNATURE Caso & Wars TITLE Regulatory Ana	alyst DATE 02/20/2020
For State Use Only	e evans@xtoenergy.com PHONE: 432.218.3671
APPROVED BY: Da Dwolf TITLE Conflictions of Approval (if any):	en officer DATE 2-21-20

Хто

Schematic - Vertical - Proposed

Well Name: ELK WALLOW 11 STATE 001H

