Office <u>District I</u> 1625 N. French Dr., Hobbs, NM 88  District II		State 0.	f New Me	Xico			Form C	-103
	I	Energy, Mineral	s and Natu	ral Resources	FT-00		May 27,	2004
Dietrict	240				WELL API NO.			
1301 W. Grand Ave., Artesia, NM	88210	OIL CONSER	VATION	DIVISION	30-015-33822	CT		
District III	•	1220 Sout	th St. Fran	cis Dr.	5. Indicate Type STATE		E 🛛	ì
1000 Rio Brazos Rd., Aztec, NM 8' District IV	7410	Santa I	Fe, NM 87	505	6. State Oil & G			
1220 S. St. Francis Dr., Santa Fe, N	M				o. State On & O	as Lease IVO	,,	
87505	Nomices	NE PEROPES						
SUNDRY (DO NOT USE THIS FORM FOR		AND REPORTS (			7. Lease Name of	or Unit Agre	ement Na	me
DIFFERENT RESERVOIR. USE					Harroun 15			
PROPOSALS.)					8. Well Number	17		
1. Type of Well: Oil Well	⊠ Gas W	Vell Other	REC	EIVED				
2. Name of Operator Pogo Producing Company			.11.11	1 7 2006	9. OGRID Num 017891	ber		
3. Address of Operator		OPPINATEON			10. Pool name or Wildcat			
P. O. Box 10340, Midland,	ГХ 79702-73	40		AS IESN	Pierce Crossing		East	
4. Well Location								
Unit Letter M	: 660	feet from th	ne South	line and	330 feet from the	ne West	line	
Section 15		Township		Range 29E	NMPM	Eddy	Count	,
Section 13	- 11 1	Elevation (Show v				Lady	Count	y ************************************
<b>从一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个</b>		Dievacion (Bilon)	memer Bre,	1012, 111, 011, 01	1.0. <i>)</i>			525
Pit or Below-grade Tank Applicati	ion 🗌 or Closu	re 🔲	1	,				
Pit typeDepth to G	roundwater	Distance from n	earest fresh w	ater well D	Distance from nearest sur	face water		
Pit Liner Thickness:	mil Be	elow-Grade Tank: V	olume	bbls;	Construction Material			
12 Cl	ack Annro	printe Boy to I	Indicate No	ature of Notice	e, Report or Other	r Data		
12. Cl	icck Appro	priate box to i	ilidicate in	ature or riotics	c, report of Office	Data		
NOTICE (	OF INTEN	TION TO:		SU	<b>BSEQUENT RE</b>	PORT O	F:	
PERFORM REMEDIAL WOI			N 🗆	REMEDIAL WO		ALTERING		; 🗆
TEMPORARILY ABANDON	☐ CHA	NGE PLANS		COMMENCE D	RILLING OPNS.	P AND A		] .
PULL OR ALTER CASING	☐ MUL	TIPLE COMPL		CASING/CEME	NT JOB 🔲			
			_					_
				OTHER:				1 1
OTHER:	1 4 1	. (01	1 4.4 11	4141.41	1	1 1.	<del></del>	<u> </u>
13. Describe proposed or								
13. Describe proposed or of starting any propo								
13. Describe proposed or								
13. Describe proposed or of starting any propo								
13. Describe proposed or of starting any propo								
13. Describe proposed of of starting any propo or recompletion.	sed work). S	EE RULE 1103.	For Multipl	le Completions:	Attach wellbore diag	ram of prop	osed comp	oletion
13. Describe proposed of of starting any propo or recompletion.  Spud & Set Surface Csg – MI	sed work). S	EE RULE 1103.	For Multipl  @ 04:30 hrs	le Completions:	Attach wellbore diag	ram of proportion	osed comp	oletion 5 hrs
13. Describe proposed of of starting any proposed or recompletion.  Spud & Set Surface Csg - MI 07/10/06. Ran 8 jts 13-3/8" 4	sed work). S  RU Patterson 8# L/S ST&C	#78. Spud well C csg. Cmt'd w/	For Multipl  @ 04:30 hrs 180 sks Cl "	le Completions: s 07/09/06. Drld H" + add @ 14.6	Attach wellbore diag	ram of proportion of the reacher POZ C + 26	osed comp ed @ 14:1 % CaCl2 (	5 hrs 0 12.8
13. Describe proposed of of starting any proposed of of starting any proposed or recompletion.  Spud & Set Surface Csg – MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "6"	RU Patterson 8# L/S ST&C C" + 2% CaC	#78. Spud well C csg. Cmt'd w/ 12 @ 14.8 ppg. F	For Multipl  @ 04:30 hrs 180 sks CI " Plug down @	e Completions:  s 07/09/06. Drld H" + add @ 14.6  2 21:00 hrs 07/10	Attach wellbore diag	ram of proportion of the reacher POZ C + 26	osed comp ed @ 14:1 % CaCl2 (	5 hrs 0 12.8
13. Describe proposed of of starting any proposed or recompletion.  Spud & Set Surface Csg - MI 07/10/06. Ran 8 jts 13-3/8" 4	RU Patterson 8# L/S ST&C C" + 2% CaC	#78. Spud well C csg. Cmt'd w/ 12 @ 14.8 ppg. F	For Multipl  @ 04:30 hrs 180 sks CI " Plug down @	e Completions:  s 07/09/06. Drld H" + add @ 14.6  2 21:00 hrs 07/10	Attach wellbore diag	ram of proportion of the reacher POZ C + 26	osed comp ed @ 14:1 % CaCl2 (	5 hrs 0 12.8
13. Describe proposed of of starting any proposed of of starting any proposed or recompletion.  Spud & Set Surface Csg – MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "6"	RU Patterson 8# L/S ST&C C" + 2% CaC	#78. Spud well C csg. Cmt'd w/ 12 @ 14.8 ppg. F	For Multipl  @ 04:30 hrs 180 sks CI " Plug down @	e Completions:  s 07/09/06. Drld H" + add @ 14.6  2 21:00 hrs 07/10	Attach wellbore diag	ram of proportion of the reacher POZ C + 26	osed comp ed @ 14:1 % CaCl2 (	5 hrs 0 12.8
13. Describe proposed of of starting any proposed of of starting any proposed or recompletion.  Spud & Set Surface Csg – MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "6"	RU Patterson 8# L/S ST&C C" + 2% CaC	#78. Spud well C csg. Cmt'd w/ 12 @ 14.8 ppg. F	For Multipl  @ 04:30 hrs 180 sks CI " Plug down @	e Completions:  s 07/09/06. Drld H" + add @ 14.6  2 21:00 hrs 07/10	Attach wellbore diag	ram of proportion of the reacher POZ C + 26	osed comp ed @ 14:1 % CaCl2 (	5 hrs 0 12.8
13. Describe proposed of of starting any proposed of of starting any proposed or recompletion.  Spud & Set Surface Csg – MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "6"	RU Patterson 8# L/S ST&C C" + 2% CaC	#78. Spud well C csg. Cmt'd w/ 12 @ 14.8 ppg. F	For Multipl  @ 04:30 hrs 180 sks CI " Plug down @	e Completions:  s 07/09/06. Drld H" + add @ 14.6  2 21:00 hrs 07/10	Attach wellbore diag	ram of proportion of the reacher POZ C + 26	osed comp ed @ 14:1 % CaCl2 (	5 hrs 0 12.8
13. Describe proposed of of starting any proposed of of starting any proposed or recompletion.  Spud & Set Surface Csg – MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "6"	RU Patterson 8# L/S ST&C C" + 2% CaC	#78. Spud well C csg. Cmt'd w/ 12 @ 14.8 ppg. F	For Multipl  @ 04:30 hrs 180 sks CI " Plug down @	e Completions:  s 07/09/06. Drld H" + add @ 14.6  2 21:00 hrs 07/10	Attach wellbore diag	ram of proportion of the reacher POZ C + 26	osed comp ed @ 14:1 % CaCl2 (	5 hrs 0 12.8
13. Describe proposed of of starting any proposed of of starting any proposed or recompletion.  Spud & Set Surface Csg – MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "6"	RU Patterson 8# L/S ST&C C" + 2% CaC	#78. Spud well C csg. Cmt'd w/ 12 @ 14.8 ppg. F	For Multipl  @ 04:30 hrs 180 sks CI " Plug down @	e Completions:  s 07/09/06. Drld H" + add @ 14.6  2 21:00 hrs 07/10	Attach wellbore diag	ram of proportion of the reacher POZ C + 26	osed comp ed @ 14:1 % CaCl2 (	5 hrs 0 12.8
13. Describe proposed of of starting any proposed of of starting any proposed or recompletion.  Spud & Set Surface Csg – MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "6"	RU Patterson 8# L/S ST&C C" + 2% CaC	#78. Spud well C csg. Cmt'd w/ 12 @ 14.8 ppg. F	For Multipl  @ 04:30 hrs 180 sks CI " Plug down @	e Completions:  s 07/09/06. Drld H" + add @ 14.6  2 21:00 hrs 07/10	Attach wellbore diag	ram of proportion of the reacher POZ C + 26	osed comp ed @ 14:1 % CaCl2 (	5 hrs 0 12.8
13. Describe proposed of of starting any proposed of of starting any proposed or recompletion.  Spud & Set Surface Csg – MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "6"	RU Patterson 8# L/S ST&C C" + 2% CaC	#78. Spud well C csg. Cmt'd w/ 12 @ 14.8 ppg. F	For Multipl  @ 04:30 hrs 180 sks CI " Plug down @	e Completions:  s 07/09/06. Drld H" + add @ 14.6  2 21:00 hrs 07/10	Attach wellbore diag	ram of proportion of the reacher POZ C + 26	osed comp ed @ 14:1 % CaCl2 (	5 hrs 0 12.8
13. Describe proposed of of starting any proposed of of starting any proposed or recompletion.  Spud & Set Surface Csg – MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "6"	RU Patterson 8# L/S ST&C C" + 2% CaC	#78. Spud well C csg. Cmt'd w/ 12 @ 14.8 ppg. F	For Multipl  @ 04:30 hrs 180 sks CI " Plug down @	e Completions:  s 07/09/06. Drld H" + add @ 14.6  2 21:00 hrs 07/10	Attach wellbore diag	ram of proportion of the reacher POZ C + 26	osed comp ed @ 14:1 % CaCl2 (	5 hrs 0 12.8
13. Describe proposed of of starting any proposed of starting any proposed or recompletion.  Spud & Set Surface Csg – MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "6 Make cut-off. Install WH. N	RU Patterson 8# L/S ST&C C" + 2% CaC U BOP's. Te	is true and complete	For Multipl  @ 04:30 hrs 180 sks Cl " Plug down @ g to 1000# fo	e Completions: 6 07/09/06. Drld H" + add @ 14.6 @ 21:00 hrs 07/10 pr 30 mins.	Attach wellbore diagonal Attach wellbore diagonal 17-1/2" hole to 315's ppg + 200 sks 35:65 h/06. Circ 115 sks to	TD reacher POZ C + 2° surface. We	ed @ 14:1 % CaCl2 o	5 hrs @ 12.8
13. Describe proposed of of starting any proposed of starting any proposed or recompletion.  Spud & Set Surface Csg – MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "6 Make cut-off. Install WH. N	RU Patterson 8# L/S ST&C C" + 2% CaC U BOP's. Te	is true and complete	For Multipl  @ 04:30 hrs 180 sks Cl " Plug down @ g to 1000# fo	e Completions: 6 07/09/06. Drld H" + add @ 14.6 @ 21:00 hrs 07/10 pr 30 mins.	Attach wellbore diagonal Attach wellbore diagonal 17-1/2" hole to 315's ppg + 200 sks 35:65 h/06. Circ 115 sks to	TD reacher POZ C + 2° surface. We	ed @ 14:1 % CaCl2 o	5 hrs @ 12.8
13. Describe proposed of of starting any proposed of starting any proposed or recompletion.  Spud & Set Surface Csg - MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "6 Make cut-off. Install WH. N	RU Patterson 8# L/S ST&C C" + 2% CaC U BOP's. Te	is true and complete	For Multipl  @ 04:30 hrs 180 sks Cl " Plug down @ g to 1000# for	e Completions:  3 07/09/06. Drld H" + add @ 14.6 2 21:00 hrs 07/10 or 30 mins.	Attach wellbore diagonal Attach wellbore diagonal 17-1/2" hole to 315 ppg + 200 sks 35:65 p/06. Circ 115 sks to	TD reacher POZ C + 26 surface. We her certify that native OCD-a	ed @ 14:1 % CaCl2 o	5 hrs @ 12.8
13. Describe proposed of of starting any proposed of starting any proposed or recompletion.  Spud & Set Surface Csg – MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "6 Make cut-off. Install WH. N	RU Patterson 8# L/S ST&C C" + 2% CaC U BOP's. Te	is true and complete	For Multipl  @ 04:30 hrs 180 sks Cl " Plug down @ g to 1000# for	e Completions: 6 07/09/06. Drld H" + add @ 14.6 @ 21:00 hrs 07/10 pr 30 mins.	Attach wellbore diagonal Attach wellbore diagonal 17-1/2" hole to 315 ppg + 200 sks 35:65 p/06. Circ 115 sks to	TD reacher POZ C + 2° surface. We	ed @ 14:1 % CaCl2 o	5 hrs @ 12.8
13. Describe proposed of of starting any proposed of starting any proposed or recompletion.  Spud & Set Surface Csg - MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "0 Make cut-off. Install WH. N	RU Patterson 8# L/S ST&C C" + 2% CaC U BOP's. To	is true and complactording to NMOC	@ 04:30 hrs 180 sks C1 " Plug down @ 3 to 1000# fo	est of my knowled a general permit	Attach wellbore diag  17-1/2" hole to 315" ppg + 200 sks 35:65  006. Circ 115 sks to	TD reacher POZ C + 20 surface. Wo	ed @ 14:1 % CaCl2 (OC 21 hrs	5 hrs @ 12.8
13. Describe proposed of of starting any proposed of starting any proposed or recompletion.  Spud & Set Surface Csg - MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "6 Make cut-off. Install WH. N	RU Patterson 8# L/S ST&C C" + 2% CaC U BOP's. To	is true and complactording to NMOC	@ 04:30 hrs 180 sks C1 " Plug down @ 3 to 1000# fo	est of my knowled a general permit	Attach wellbore diagonal Attach wellbore diagonal 17-1/2" hole to 315 ppg + 200 sks 35:65 p/06. Circ 115 sks to	TD reacher POZ C + 20 surface. Wo	ed @ 14:1 % CaCl2 (OC 21 hrs	5 hrs @ 12.8
13. Describe proposed of of starting any proposed of starting any proposed or recompletion.  Spud & Set Surface Csg – MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "6 Make cut-off. Install WH. N  I hereby certify that the information of the second of the	RU Patterson 8# L/S ST&C C" + 2% CaC U BOP's. Te	is true and complete to NMOC	@ 04:30 hrs 180 sks CI " Plug down @ 3 to 1000# fo D guidelines  TITLE S	est of my knowled a general permit	Attach wellbore diag  17-1/2" hole to 315" ppg + 200 sks 35:65  006. Circ 115 sks to	TD reacher POZ C + 26 surface. Wo	ed @ 14:1 % CaCl2 (OC 21 hrs	5 hrs @ 12.8
13. Describe proposed of of starting any proposed of starting any proposed or recompletion.  Spud & Set Surface Csg – MI 07/10/06. Ran 8 jts 13-3/8" 4 ppg followed by 200 sks Cl "6 Make cut-off. Install WH. N  I hereby certify that the information of the second of the	RU Patterson 8# L/S ST&CC" + 2% CaCU BOP's. To	is true and complactording to NMOC	@ 04:30 hrs 180 sks CI " Plug down @ 3 to 1000# fo D guidelines  TITLE S	est of my knowled a general permit	Attach wellbore diag  17-1/2" hole to 315" ppg + 200 sks 35:65  006. Circ 115 sks to	TD reacher POZ C + 20 surface. Wo	ed @ 14:1 % CaCl2 (OC 21 hrs	5 hrs @ 12.8