

3/19/2007

## Wellbore Diagram

r263

30-015-35391-00-00

EAST MILLMAN POOL UNIT No. 021

Company Name: STEPHENS &amp; JOHNSON OP CO

Location: Sec: 12 T: 19S R: 28E Spot:

## String Information

Lat: 32.6694696835953 Long: -104.123767905235

Property Name: EAST MILLMAN POOL UNIT

County Name: Eddy

## Cement Information

## Perforation Information

| Top<br>(ft sub) | Bottom<br>(ft sub) | Shts/Ft | No Shts | Dt Sqz |
|-----------------|--------------------|---------|---------|--------|
| 0               | 0                  |         |         |        |

## Formation Information

| St Code | Formation    | Depth |
|---------|--------------|-------|
| Psal    | Salado       | 370   |
| Pbslt   | Base of Salt | 600   |
| Pyts    | Yates        | 660   |
| Psr     | Seven Rivers | 874   |
| Psrbs   | Bowers Sand  | 1200  |
| Pqu     | Queen        | 1688  |
| Pgb     | Grayburg     | 2033  |
| Psa     | San Andres   | 2540  |

Hole: Unknown

TD:

TVD: 0

PBDT: