Oil Cons. N.M. DIV-Dist. 2 1301 W. Grand Avenue

Form 3160-5	ONITED STATE		T TTI GIQIQI	TO CITUCIORM APPROVED
(JUNE 1990)	DEPARTMENT OF TH	E INTERIOR A	rtesia, NIVI 8	821 (Judget Bureau No. 1004-0135
	BUREAU OF LAND M	ANAGEMENT		Expires: March 31, 1993
				5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.				NM70215
			6. If Indian, Allottee or Tribe Name	
Use	"APPLICATION FOR PERMIT	-" for such proposal	s 56780	N/A
	SUBMIT IN TRIPLICA	ITE /	V34567897077	7. If Unit of CA, Agreement Designation
1. Type of Well			A	<u>1</u>
Oil Gas		31,	Elm	SOUTH LONE WOLF
x Well Well Other			- CA 101 D 1 R	8Well Name and No.
2. Name of Operator	ELV OU COMPANY	293	RECENTESIA RECEARTESIA	SOCITIESTAL WOLL STATE
	ELK OIL COMPANY		Kr. VII.	API Well No.
3. Address and Telephone No.	P. O. Box 310	16	000	30-005-62896
	Roswell, New Mexico 882	02-0310	505-623-3190	10. Field and Pool, or Emploratory Area
4. Location of Well (Footage, Sec., T, R, M	L, or Survey Description)		\$\$55334 J	Southwest Lone Wolf Dev.
Section 29, Township 13 So	uth, Range 29 East			11. County or Pansh, State
2310' FNL & 1980' FWL				Chaves
12. CHECK APPROP	RIATE BOX(s) TO INDIC	ATE NATURE OF	NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSI	ON	T	YPE OF ACTION	
X Notice of Intent		X Abandonment		Change of Plans
		Recompletion		New Construction
Subsequent Report	ļ.	Plugging Back Casing Repair		Non-Routine Fracturing Water Shut-Off
Final Abandonment N	Votice	Altering Casing		Conversion to Injection
المستعدا		Other		Dispose Water
13. Describe Proposed or Completed Operations (Charles and all assistant details and aims			(Siste Report muits of maining completion on Well Completion or Recompletion Report and Log Form)
give subsurface locations and measured and tr	me vertical depths for all markers and zones perti		timeted Too)
Intend to plug and aband	ion well as follows:	1_3		12 = 6710
(1) Set cement plug at	9574'-9474'. 7750-7650'	:		
(2) Set cement plug at	[75 0]-7650'.	Fr	901	
(3) Set cement plug at	5695'-5595'- per + 8€	neeze @ 30	12	
(4) Cut and pull 2100 c	of 5 1/2" casing.			
(5) Set cement plug 50	in / 50 out casing stub and	8 5/8" shoe 2159'-	2050'.	•
(6) Set cement plug 35	2'-252' (13 3/8 shoe plug 5(3 in / 50 out.)		
(7) Set 10 sxs surface	plug.			
(8) Place mud between	all plugs.			
(9) Install dry hole mark				
(10) Clean up location.				
14. I hereby certify that the foregoing true	and correct			
Council Council trat the totagoing with	and cotteet	. President		Data 9/24/03

(This space for Federal or State office Approved by Conditions of approval, if any:

See Instruction on Reverse Side

F3160-5.wks