Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OII Cons. N.M. DIV-Dist. 2 OMB No. 1004-0135 Expires November 30, 2000 Actoric NIM 0004 Disease Serial No.

SUNDRY NOTICES AND REPORTS ON WELASTESIA, NM 8821	0
---------------------------------------------------	---

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. NM-662 6. If Indian, Allottee or Tribe Name

				N/A 7. If Unit or CA/Agreement, Name and/or No.		
SIII SIII	RMIT IN TRIPLICATE - O	ther Instructions on rever	se side			
. Type of Well			2456780	8. Well Name and No.		
Oil Well	X Gas Well	Other	Nikjection 707	FEDERAL FC #1		
2. Name of Operator		15	Do. # 20	9. API Well No.		
Yates Petroleum Co	rporation	30.37	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	00 010 2:000		
Ba Address 105 S. 4th Street - A	rtesia, NM 88210	3b. Phone No. (include a 505-748-147)	1.16	10. Field and Pool, or Exploratory Area		
Location of Well (Footage, Sec			14/20 B	DAGGER DRAW UPPER PENN S.		
660' FSL & 1980' FEL		0S-R25E	TICE REPORT OR OTHER	11. County or Parish, State EDDY COUNTY, NEW MEXICO		
12. CHECK APPR	OPRIATE BOX(ES) TO I	NDICATE NATURE OF NO	TYPE OF ACTION	DATA		
TYPE OF SUBMISSION			_			
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off		
Subsequent Report	Alter Casing	Fracture Treat	Reclamation	Well Integrity		
Final Abandonment Notice	Casing Repair	New Construction	Recomplete	Other		
	Change Plans	X Plug and Abandon	Temporarily Abandon			
·	Convert to Injection	Plug Back	Water Disposal			
NOTIFY NMOCD 24 HOURS NOTIFY BLM IN CARLSBAD 1. Rig up safety equipment; M 2. MIRU wireline & lubricator 3. TIH w/ tubing to set a 25 sk 4. RU wireline & perforate 6 s 5. RU wireline & perforate 6 s Squeeze w/ 40 sx Class C ce intermediate casing shoe. W 6. RU wireline & perf 6 squee 30 sx Class C cement & disp WOC 4 hrs & tag cement; res 7. RU wireline & perf 6 squee 85 sx Class C cement & disp I hereby certify that the foregoing Name (Printed/Typed) **Donna Clack** Signature	BEFORE STARTING PLUGG 24 HOURS BEFORE STAR fIRU WSU, ND wellhead & NI to run a gauge ring & set CIBI 3 plug from 5998'-6248' across queeze holes @ 4248'. TIH w queeze holes @ 3304'. TIH w ment & displace cement to 32 DC 4 hrs & tag cement; reset ize holes @ 2320'. TIH w/ tbg lace cement to 2120' or 100' a set plug if necessary. ize holes @ 300'. TIH w/ tbg, lace to 200' or 100' above the is true and correct	GING OPERATIONS. TING PLUGGING OPERATION U BOP. POH w/ tubing, packer @ 07024' & cap w/ 35' cement s Wolfcamp top. Pull tbg up ho v/ tbg, packer & tail pipe; load h v/ tbg, packer & tail pipe; load h v/ tbg, packer & tail pipe; load h 204', or above the top perforation plug if necessary. , pkr, & tail pipe; load w/ pluggi above the top perfs. This will lea pkr & tail pipe; load hole w/ plu top perf. This will leave a ceme	e & reverse circ clean. Load w/ pluce w/ plugging mud. Set a packer on. This will twave a 100' cement plug mud. Set a packer above performed ave a 100' cement plug across the gging mud; set a packer above perent plug across the surface casing title	ugging mud & POH. r above perforations. r above perfs. APPROVED rations. Squeeze w/ glorieta top. OCT - 9 2003 rfs. Squeeze w/ pshoe & circulate LES BABYAK PETRO(pontitiwiethor) inextenses		
_ Nonn	a Cass		10-02-03			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by	Not Lo		Title	Date		
Conditions of approval, if any, are the applicant noids legal or equite applicant to conduct operations to	e attached. Approval of this notice	e does not warrant or certify that ject lease which would entitle the	Office			
	Title 43 U.S.C. Section 1212, ma sentations as to any matter within	•••	gly and willfully to make to any departm	nent or agency of the United States any false, fictitious		

Form 3160-5 (August 1999)

FEDERAL FC # 1 Sec 19-20S-25E EDDY COUNTY, NM

cement to surface. WOC 4 hrs & tag cement, reset plug if necessary.

- 8. TIH w/ tbg to 150'; spot 15 sk plug to surface inside 5-1/2" casing. WOC 24 hrs & tag; reset if necessary.
- 9. Remove all surface equipment & weld dry hole marker per regulation.

Aona Clack



