Submit 3 Copies To Appropriate District	State of New I			Form C-10
Office District I	Energy, Minerals and Na	atural Resources		Revised March 25, 199
1625 N. French Dr., Hobbs, NM 87240			WELL API NO.	20702
District II 811 South First, Artesia, NM 87210	OIL CONSERVATION DIVISION 2040 South Pacheco		30-015-30702 5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE 5	
District IV	Danta 1 C, 1417	1 07303	6. State Oil & Gas	
2040 South Pacheco, Santa Fe, NM 87505			E-6353	3 20000 110.
(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)		N OR PLUG BACK TO A	7. Lease Name or Conoco 8 State	Unit Agreement Name:
1. Type of Well: Oil Well Gas Well	Other			
2. Name of Operator	No	OV - 7 2003	8. Well No.	
EOG Resources, Inc.	OCD-ARTESIA		1	
3. Address of Operator			9. Pool name or Wildcat	
P.O. Box 2267 Midland, TX 4. Well Location	79702		Undesignated; W	Olfcamp_
,	1650 feet from the	South line and		om the East line
Section 8	Township 17S 10. Elevation (Show whether	Range 29E	NMPM	County Eddy
	1	er DR, KKB, KI, GR, ei 8 611' G R	<i>C.)</i>	
11. Check A	ppropriate Box to Indica		Report or Other	r Data
NOTICE OF INTE		·	SEQUENT REI	
PERFORM REMEDIAL WORK		REMEDIAL WORK		ALTERING CASING
_				
TEMPORARILY ABANDON	CHANGE PLANS		ING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB		
OTHER:		OTHER:		
12. Describe Proposed or Complete of starting any proposed work). or recompilation. This sundry notice to P&A 1. Set CIBP @ 9525' in 3	SEE RULE 1103. For Multip Not A replaces the sundry not 3 1/2" tubing. Cap w/ 3	tice to recomplete t	wellbore diagram of the work dome diagram of t	of proposed completion 1 10/28/03.
2. Cut 3 1/2" tubing @ 9	105' and salvage.	100	'slug in Four	tof C59.
3. Set CIBP @ 9100' in 7	0105' and salvage. "" casing. Cap w/ 35' or Lvage. Spot 50 sx of cer	f cement on top	1070 10 7/1	70 -
4. Cut 7" casing and sal	vage. Spot 50 sx or der between 6100' and 9100';	ment, 50' in and 50'	out of 7" casin	ig stub. – /Ag
5. Spot 50 sx of cement	from 5500' to 5400'.	ir andacoprar, pde	10020)	_
6. Spot 45 sx of cement	from 2724'm to 2624'. Tag	rag.	al' poul s	y
7. Spot 35 sx of cement	from 490' to 390'. Tag	E100 plug f	79-894 7	ud consisting of 10#
♣ 8. Spot 20 sx of cement ♣ 9. Weld on P&A marker ar ■ 1. The state of the	from 40! to Surface. 60 ad clean and restore loca	5 - WOC 24 M/5 - 1	75 Salt gei int Rrine W/	25# of gel per bbl
	1 1 200	/	must be place	ced between each plug
flugs must be in ? Ou		Not fulled		
hereby certify that the information above	is true and complete to the best of	of my knowledge and belie	t.	
SIGNATURE The Wa	TI	TLE Regulatory Anal	yst j	DATE <u>11/04/03</u>
Type or print name Stan Wagner			Telepho	one No. 432 686 3689
(This space for State use)	100	1.01	les D	
APPROVED BY	TI	TLE	D	ATE
Conditions of approval, if any:			APPROVED)., NOV 1.3. 2003;