Form 3160-5 (August 2007)

## UNITED STATES OCD-ARTESIA DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No 1004-0137 Expires July 31, 2010

LC-069464-A

5 Lease Serial No

#### SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

6 If Indian, Allottee or Tribe Name

SUBMIT IN	TRIPLICATE - 0	ther instructions on p	page 2	7 If Unit or CA/Agreement, Name and/or No.
l Type of Well	)			<b>7</b> G
Oil Well Gas Well	Other	<b>*</b>	DECEIVED	8. Well Name and No
2. Name of Operator			HEULI	Federal 18 #004
Tom R Cone			APR 1 9 2010	9 AH Well No
3a Address		3b Phone No finclude area cos	(e) APR +	3001520226
1304 W Broadway Place Ho	obbs, NM 88240	575 390 9611	ARTES	3001520226  PArilld and Pool, or Exploratory Area  Benson; Yates, East
4 Location of Well (Footage, Sec., T., R	, M , or Survey Descript	ion)	NWOCD VIII	Benson; Yates, East
18-19S-31E				11 County or Parish, State
1980 FNL 1650 FEL	`			Eddy, NM
12. CHECK AP	PROPRIATE BOX	(ES) TO INDICATE NA	TURE OF NOTICE, REPO	ORT, OR OTHER DATA
TYPE OF SUBMISSION			TYPE OF ACTION	
	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
Notice of Intent	Alter Casing	Fracture Treat	Reclamantion	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon	
	Convert to Injection	n Plug Back	Water Disposal	
				proposed work and approximate duration thereof vertical depths of all pertinent markers and zones

Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamantion, have been completed, and the operator has

- 1. MIRU Plugging equipment
- 2. Spot 25 sx @ 2310 to 2210 WOC & Tag 41/2 shoe and OH
- 3. Circulate hole w 9.5# mud laiden fluid, 12.5# per bbl.
- 4. Perf 4 1/2 csg @ 1950, sqz 40 sx. WOC Tag @ 1850. BOS
- 5. Perf 4 1/2 csg @ 651, sqz 40 sx. WOC Tag @ 550. TOS, 7" shoe."
- 6. Perf 4 1/2 csg & 7 csg @ 60. Circ cmt inside and outside all csg.
- 7. Cut off well head. Install marker.

determined that the site is ready for final inspection.)

# SEE ATTACHED FOR CONDITIONS OF APPROVAL

## RECLAMATION PROCEDURE ATTACHED

14. I hereby certify that the foregoing is true and correct )							
Name (Printed Typed)							
Doug Ham Trile	Agent						
Signature Doug Hand	3/17/10	VCC	EPTEN	FOF	RECC	RD	
Signature House House THIS SPACE FOR FEDERAL OF	R STAT	E OF	FICE US	- 01	4 14 cm c		
Approved by	Title		. MAR	15	2010	<i>-</i> ,	
Conditions of approval, if any are attached Approval of this notice does not warrant or certify that	Office	1.	s/ Dus	tin V	Vinkle	,	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person know States any false, fictinous or fraudulent statements or representations as to any matter within its jurisc		ifully <b>a</b>	IREAU OF L CARLSBA	OTIEL	D OFFICE	the Uni	ed

(Instructions on page 2)

Ope/20/200

e	Well Fed 18 # 4 Unit 6 Section 18 Township 19 Range 3!
•	API# 30-0/5 20226 R-111-P AREA
	60° surface Plus
340' Toe 50%	·
7'601	525' 5A1-1 Plug
1481	To C @ SO%  1480-525-  1480-525-  1950-
4112	150 OH 150 JOH 150 JOH

Operator F.T. RO CORP

	•	TOPS	
Γ. Salt	575	_	
B. Salt	1900		
Yates	3065		
Glorieta		-,	
Delaware_			
Bone Sp			
Abo			
Wolfcamp			
Morrow_			
Devonian			
Fusselman			
Other			
<del></del>			

- Contact OCD 24 hrs. prior to any work done.
- Salt gel mud consisting of 10# brine with 25# of gel per barrel must be placed between each plug
- Install dry hole marker as per rule 202.B.2
- Plugs are to be set from point indicated up. Plugs must not be less than 100' or 25 Sacks of cement, whichever is greater, unless specifically indicated.
- Shoe and stub plugs will be 50' above and below shoe or stub and tagged.
- Surface plug will be from 0'- 60'
- Where plugs are required cement must be placed inside and outside of all casing string(s), in the correct footage or sacks required, if no cement exists.
- Plugs to be tagged will be indicated.

State of New Mexico formerly Tom R Cone NMLC-069464-A: Federal 18 #4 API: 30-015-20226 Eddy County, New Mexico

RE: Plugging and Abandonment Requirements, Conditions of Approval

SPECIAL NOTE—Mud Laden Fluid will consist of 9.5# brine with 12.5# Salt Gel per BBL (25 sacks of gel per 100 BBLS Brine). All cement plugs will be a minimum 25 sacks of cement or 100' + 10% per 1000' depth, whichever is greater. Unless otherwise specified in the approved procedure, cement plugs shall consist of class "C" for depths to 7500'. Class "H" will be used for plugs deeper than 7500'.

H2S monitoring equipment to be on location

- 1. OK
- 2. Plug to be a minimum of 120'. Tag at 2190' or shallower Otherwise OK (Open hole Casing shoe)
- 3. OK
- 4. Well is in the R-111-P Potash area A solid plug is required across the salt section. Perforate and squeeze cement from 1950'-525', WOC and tag at 525' or shallower. If injection rate cannot be established, spot 25sx 50' below perfs, WOC and tag, and perf 10' above tag and attempt again. If injection rate cannot be established, repeat steps above until there is a rate. (Salt Casing shoe)

  Optional: Free point the casing, cut and pull, and spot cement from 1950'-525', WOC and tag.
- 5. REMOVED Covered in step 4
- 6. OK
- 7. Verify cement to surface in all annuluses Otherwise OK.
- 8. Submit a subsequent report to the BLM.

See attached standard COAs.

DHW 041410

#### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

#### Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Any plug that requires a tag will have a minimum WOC time of 4 hours.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). **The BLM is to be notified when the wellhead is cut off to verify that cement is to surface in the casing and all annuluses.** The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.

DHW 112309



### **United States Department of the Interior**

#### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

#### **Reclamation Objectives and Procedures**

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
  Operations must include adequate measures for stabilization and reclamation of disturbed lands.
  Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
  process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

- equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Terry Gregston Environmental Protection Specialist 575-234-5958

Bobby Ballard Environmental Protection Specialist 575-234-2230

Randy Rust Environmental Protection Specialist 575-234-5943

Linda Denniston Environmental Protection Specialist 575-234-5974

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Justin Frye Environmental Protection Specialist 575-234-5922 Cody Layton Natural Resource Specialist 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Todd Suter Surface Protection Specialist 575-234-5987

Doug Hoag Civil Engineering Technician 575-234-5979